

# Addendum

HCSD Administration



VENDOR NO. :  
SOLICITATION : **000188**  
OPENING DATE : **07/06/2016**

BIDS WILL BE PUBLICLY OPENED:

**July 06, 2016      02:00 PM**

Return Sealed Bid to:  
Purchasing Department  
5429 Airline Hwy  
BATON ROUGE LA 70805

BUYER : Omorotionmwan, Peter  
BUYER PHONE : 225/354-3786  
DATE ISSUED : 05/31/2016  
REQ. NO :  
FISCAL YEAR : 0

DEMOLITION OF MOBILE KITCHEN

## Addendum 04

Your reference is directed to Solicitation Number 000188 for Mobile Kitchen in New Orleans, Louisiana, which is scheduled to open at 2:00 p.m. on July 6, 2016.

Questions for 000188 & 00186:

1. Are the pilings are to be completely extracted from the earth or cut below grade? If cut below grade, please clarify or provide depth to cut pilings. The intent of the project is to restore the site to pre-storm condition.

Pilings are to be cut a foot below the removed pile cap. All utilities as indicated in the construction documents provided, which indicate all the work that was performed to install the units shall be removed and properly capped to create a safe and secure condition that existed prior to the installation of the modular kitchen and dental clinic.

2. After any inspections for asbestos or lead material, Will a change order be provided for abatement and disposal? Or, Shall the contractor assume to add the abatement and disposal in original base bid?

LSU does not anticipate the presence of asbestos or lead materials at the site. Attached is a copy of the Asbestos Lead Based Paint and Universal Regulated Waste Survey Report, which was completed in 2015. There will be no change orders issued. Contractors should bid accordingly. Should asbestos or lead materials be found, the contractor must deal with these materials appropriately in accordance with regulations and provide certification of all findings and disposition.

3. What is the time frame to complete all projects and liquidated damages for each?

| VENDOR PHONE NUMBER:<br>FAX NUMBER:                | TITLE | DATE                                 |
|--|-------|--------------------------------------|
|  |       |                                      |
| SIGNATURE OF AUTHORIZED BIDDER<br>(MUST BE SIGNED) |       | NAME OF BIDDER<br>(TYPED OR PRINTED) |

# Addendum

|  |             |
|--|-------------|
| DEMOLITION OF MOBILE KITCHEN   | Page 2 of 2 |
| NUMBER : 000188<br>OPEN DATE : 07/06/2016      TIME: 02:00 PM  | BIDDER:     |
| The time frame for the completion of the entire project (dental clinic, mobile kitchen sidewalk & deck) is 90 days.  |             |
| Liquidates damages in the amount of \$250 per day will be assessed after the 90 day period.  |             |
| 4. What is the budget for the proposed projects?   |             |
| Estimated cost for Demolition of Mobile Kitchen and Site Restoration is \$242,283  |             |
| ACKNOWLEDGEMENT: If you have already submitted your bid and this Addendum does not cause you to revise your bid, you should acknowledge receipt of this Addendum by identifying your business name and by signing where indicated.   |             |
| REVISION: If you have already submitted your bid and this Addendum requires you to revise your bid, you must indicate any change(s) below, identify your business name and sign where shown. Revisions shall be delivered prior to bid opening by mail, by hand delivery or courier. |             |
| THIS ADDENDUM IS HEREBY OFFICIALLY MADE A PART OF THIS SOLICITATION.   |             |

# **Asbestos, Lead-Based Paint & Universal Regulated Waste Survey Report**

**LSU Health Sciences Center**

**Interim Louisiana Hospital Site**

**Dental Clinic and Pharmacy Buildings**


**2021 Perdido Street**

**New Orleans, Louisiana**

**December 18, 2015**

**Terracon Project No. EH137101**

**LSUHSC Task Order No. 00374423B / Task Order No. 2016-01**



**Prepared for:**

**LSU Health Sciences Center  
New Orleans, Louisiana 70112**

**Prepared by:**

**Terracon Consultants, Inc.  
Baton Rouge, Louisiana**

**terracon.com**

**Terracon**

**Environmental**

**Facilities**

**Geotechnical**

**Materials**



December 18, 2015

LSU Health Sciences Center (LSUHSC)  
450A South Claiborne Avenue  
Stanislaus Hall  
New Orleans, Louisiana 70112

Attn: Mr. Darren Burkett, CIH, MSPH  
Industrial Hygienist  
LSU HSC Environmental Health and Safety  
P: 504.402.9085  
E: [dburk2@lsuhsc.edu](mailto:dburk2@lsuhsc.edu)

Re: Asbestos, Lead-Based Paint & Universal Regulated Waste Survey  
Interim Louisiana Hospital Site – Dental Clinic and Pharmacy Buildings  
2021 Perdido Street  
New Orleans, Louisiana 70112  
Terracon Project No. EH137101  
LSUHSC PO No. 00374423B / Task Order No. 2016-01

Dear Mr. Burkett:

The purpose of this report is to present the results of an asbestos, lead-based paint and universal regulated waste survey performed between November 30 and December 3, 2015, at the above referenced site in New Orleans, Louisiana. This survey was conducted in general accordance with Terracon's Environmental Consulting Services Contract with LSUHSC, Task Order Number 2016-01 dated November 19, 2015. We understand that this survey was requested due to the planned demolition of the on-site structures.

Non-friable asbestos-containing materials and universal regulated waste were identified. Please refer to the attached report for details.

Terracon Consultants, Inc. appreciates the opportunity to provide this service to the LSU Health Sciences Center. If you have any questions regarding this report, please contact the undersigned at 225.344.6052.

Sincerely,  
**Terracon Consultants, Inc.**

Prepared By:

Phillip Bellan  
Senior Staff Industrial Hygienist

Reviewed By:

for  
Mitch Reiber, CIH  
National Director of Asbestos Services

Terracon Consultants, Inc. 2822-B O'Neal Lane Baton Rouge, LA  
P [225] 344-6052 F [225] 344-6346 [terracon.com](http://terracon.com)

## TABLE OF CONTENTS

|   | Page     |
|---|----------|
| <b>1.0 INTRODUCTION .....</b>                 | <b>1</b> |
| 1.1 Project Objective .....                   | 2        |
| <b>2.0 SITE DESCRIPTION .....</b>             | <b>2</b> |
| <b>3.0 FIELD ACTIVITIES .....</b>             | <b>2</b> |
| 3.1 Visual Assessment .....                   | 3        |
| 3.2 Physical Assessment.....                  | 3        |
| 3.3 Sample Collection.....                    | 3        |
| 3.4 Sample Analysis.....                      | 4        |
| <b>4.0 REGULATORY OVERVIEW .....</b>          | <b>4</b> |
| 4.1 Asbestos Regulations.....                 | 4        |
| 4.2 Lead Regulations.....                     | 6        |
| 4.3 Universal Waste Regulations .....         | 6        |
| <b>5.0 FINDINGS AND RECOMMENDATIONS .....</b> | <b>7</b> |
| 5.1 Asbestos Survey.....                      | 7        |
| 5.2 LBP Survey.....                           | 7        |
| 5.3 URW Survey.....                           | 7        |
| <b>6.0 GENERAL COMMENTS .....</b>             | <b>8</b> |

**APPENDIX A ASBESTOS SURVEY SAMPLE SUMMARY**

**APPENDIX B XRF INSTRUMENT DATA**

**APPENDIX C ASBESTOS ANALYTICAL LABORATORY DATA**

**APPENDIX D LICENSES AND CERTIFICATIONS**

**APPENDIX E PHOTOGRAPHIC DOCUMENTATION**

**APPENDIX F SAMPLE LOCATION DIAGRAMS**

# **ASBESTOS, LEAD-BASED PAINT & UNIVERSAL REGULATED WASTE SURVEY REPORT**

**LSU Health Sciences Center  
Interim Louisiana Hospital Site  
Dental Clinic and Pharmacy Buildings  
2021 Perdido Street  
New Orleans, Louisiana 70112**

**Terracon Project No. EH137101  
LSUHSC PO No. 00374423B / Task Order No. 2016-01  
December 18, 2015**

## **1.0 INTRODUCTION**

Terracon Consultants, Inc. (Terracon) conducted an asbestos, lead-based paint (LBP), and universal regulated waste (URW) survey of the Dental Clinic and Pharmacy buildings of the Interim Louisiana Hospital (ILH) site located at 2021 Perdido Street in New Orleans, Louisiana 70112. The survey was conducted between November 30 and December 3, 2015, by a State of Louisiana accredited asbestos inspector and lead inspector in general accordance general accordance with Terracon's Environmental Consulting Services Contract with LSUHSC, Task Order Number 2016-01 dated November 19, 2015.

Interior and exterior building components were surveyed and homogeneous areas (HA) of suspect asbestos-containing materials (ACM) were visually identified and documented. Although reasonable effort was made to survey accessible suspect materials, additional suspect but unsampled materials could be located in walls, in voids or in other concealed areas. Suspect ACM samples were collected in general accordance with the sampling protocols outlined in EPA regulation 40 CFR 763 (Asbestos Hazard Emergency Response Act, AHERA). Samples were delivered to an accredited laboratory for analysis by polarized light microscopy (PLM).

A Niton® XLp 300 X-ray fluorescence (XRF) instrument was used during the LBP survey to determine if painted or other coated building components contained lead and was conducted in accordance with the United States Department of Housing and Urban Development (HUD) and State of Louisiana guidelines.

Terracon conducted a URW survey of the interior and exterior areas of the on-site buildings. Universal waste such as mercury-containing light tubes, mercury-containing thermostats, polychlorinated biphenyl (PCB) containing light ballasts, oil, paints, solvents, etc. that cannot be disposed of as regular construction debris was quantified and findings documented in Section 5.3 of this report.

## 1.1 Project Objective

We understand this asbestos, LBP and URW survey was requested due to the planned demolition of the on-site structures. The United States Environmental Protection Agency (USEPA) regulation 40 CFR 61, Subpart M, National Emission Standards for Hazardous Air Pollutants (NESHAP), prohibits the release of asbestos fibers to the atmosphere during renovation or demolition activities. The asbestos NESHAP requires that potentially regulated ACM (RACM) be identified, classified and quantified prior to planned disturbances or demolition activities. The United States Occupational Safety and Health Administration (USOSHA) governs occupational exposure to lead occurring in the course of construction work, including maintenance activities, painting, alteration and repairs and is subject to the USOSHA Lead Exposure in Construction standard (29 CFR 1926.62).

## 2.0 SITE DESCRIPTION

The Louisiana Interim Hospital is a multi-story facility with supporting outlying buildings. The Dental Clinic and Pharmacy buildings are two such supporting buildings that are scheduled to be demolished. Each building underwent complete renovations post-Hurricane Katrina in 2005.

The Dental Clinic building is approximately 3,000 square feet with an elevated foundation. The building is finished with drop in ceiling tiles, drywall walls and floor tile. The roof is an epoxy material that has no flashing. The building caulk is all silicone material.

The Pharmacy Building is approximately 5,000 square feet with an elevated foundation. The building is finished with drop in ceiling tiles and drywall ceilings. The walls are finished drywall with a fiber reinforced plastic (FRP) wainscot. The floors are finished with floor tiles throughout most of the building. A rubberized floor with built in floor drains was observed in the IV laboratory. The kitchen addition to the Pharmacy Building is finished with drop in ceiling tiles, FRP panel walls, rubber flooring and floor tile.

## 3.0 FIELD ACTIVITIES

The survey was conducted by Mr. Phillip Bellan, a State of Louisiana accredited asbestos inspector and a State of Louisiana accredited lead inspector. A copy of Mr. Bellan's asbestos inspector license and lead inspector license is attached in Appendix D. The survey was conducted in general accordance with the sample collection protocols established in EPA regulation 40 CFR 763 (AHERA), HUD and State of Louisiana guidelines. A summary of survey activities is provided below. The downloaded XRF instrument data is presented in Appendix B of this report. Copies of the asbestos analytical laboratory reports are included in Appendix C.

### **3.1 Visual Assessment**

Our asbestos survey activities began with visual observation of the interior and exterior of the buildings to identify homogeneous areas of suspect ACM. A homogeneous area consists of building materials that appear similar throughout in terms of color and texture with consideration given to the date of application. Interior assessment was conducted throughout visually accessible areas of the buildings. The exterior survey included an assessment of the exterior walls and roof. Materials identified as concrete, glass, wood, masonry, metal or rubber were not considered suspect ACM.

The LBP survey began by visually surveying accessible interior and exterior painted and coated building components throughout the on-site structures and identifying homogeneous surfaces to be sampled. Homogeneous surfaces, with regards to a LBP survey, consist of a unique paint color and testing combination. A room equivalent is an identifiable part of a building, such as an office, hallway, stairway, exterior side, or other exterior area. Each room equivalent is constituted of components including walls, floors, ceiling, doors, windows, and other components. The substrate is the material beneath the painted surface of the component. Substrates typically found are drywall, brick, concrete, wood, plaster, and metal. A testing combination consists of a unique room equivalent, component, substrate, and visible paint color. Multiple random test locations are chosen for each testing combination for analysis with the XRF unit.

The URW survey activities began with visual observation of the interior and exterior of the buildings to identify mercury-containing light tubes, mercury-containing thermostats, PCB-containing light ballast, oil, paints, solvents, etc. Interior assessment was conducted throughout visually accessible areas of the buildings.

### **3.2 Physical Assessment**

A physical assessment of each homogeneous area of suspect ACM was conducted to assess the friability and condition of the materials. A friable material is defined by the EPA as a material, which can be crumbled, pulverized or reduced to powder by hand pressure when dry. Friability was assessed by physically touching suspect materials.

### **3.3 Sample Collection**

Based on results of the visual observation, bulk samples of suspect ACM were collected in general accordance with AHERA sampling protocols. Random samples of suspect materials were collected in each homogeneous area. Mr. Bellan collected bulk samples using wet methods as applicable to reduce the potential for fiber release. Samples were placed in sealable containers and labeled with unique sample numbers using an indelible marker.

**Asbestos, LBP & URW Survey Report**

ILH Dental Clinic and Pharmacy Building ■ New Orleans, Louisiana

December 18, 2015 ■ Terracon Project No. EH137101

LSUHSC PO No. 00374423B ■ Task Order No. 2016-01



One hundred and thirty-four (134) bulk samples were collected from forty-two (42) homogeneous areas of suspect ACM. A summary of suspect ACM samples collected during the survey is included in Appendix A.

According to the HUD guidelines and the EPA, a lead reading by XRF of 1.0 milligrams per square centimeter ( $\text{mg}/\text{cm}^2$ ) or above is considered positive for the presence of LBP. A total of three hundred and twenty-three (323) XRF readings, including calibration and component readings, were taken from testing combinations throughout the interior and exterior of the on-site structures during the LBP survey. The downloaded XRF instrument data is presented in Appendix B.

### 3.4 Sample Analysis

Bulk samples were submitted under chain of custody to EMSL Analytical, LLC, (EMSL) of Baton Rouge, Louisiana, for analysis by polarized light microscopy per EPA methodology EPA/600/R-93/116. The percentage of asbestos, where applicable, was determined by microscopic visual estimation or point counting. EMSL is accredited under the National Voluntary Laboratory Accreditation Program (NVLAP Accreditation No. 200375-0) and Louisiana Environmental Laboratory Accreditation Program (LELAP Accreditation No. 01950). Laboratory analytical reports are included in Appendix C.

Each XRF reading taken during the LBP survey was logged in the internal memory of the instrument and downloaded for reporting purposes at the conclusion of the survey. Terracon collected 323 readings, including calibration and component readings. Calibration checks were performed prior to and after sampling, using protocols provided by the instrument manufacturer. The Niton® XLp instrument provides a positive or negative result for lead at each testing location. According to the HUD guidelines and the USEPA regulations, a lead concentration equal to or above  $1.0 \text{ mg}/\text{cm}^2$  is considered positive for lead-based paint. Of the 323 XRF readings, zero (0) were positive for the presence of LBP. The downloaded XRF instrument data is presented in Appendix B of this report.

## 4.0 REGULATORY OVERVIEW

### 4.1 Asbestos Regulations

The asbestos NESHAP (40 CFR Part 61, Subpart M) regulates asbestos fiber emissions and asbestos waste disposal practices. It also requires the identification and classification of existing materials prior to demolition or renovation activity. Under NESHAP, ACM are classified as either friable, Category I non-friable or Category II non-friable ACM. Friable materials are those that, when dry, may be crumbled, pulverized or reduced to powder by hand pressure. Category I non-friable ACM includes packings, gaskets, resilient floor coverings and asphalt roofing products

**Asbestos, LBP & URW Survey Report**

ILH Dental Clinic and Pharmacy Building ■ New Orleans, Louisiana

December 18, 2015 ■ Terracon Project No. EH137101

LSUHSC PO No. 00374423B ■ Task Order No. 2016-01



containing more than 1% asbestos. Category II non-friable ACM are any materials other than Category I materials that contain more than 1% asbestos.

Friable ACM, along with Category I and Category II non-friable ACM which is in poor condition and has become friable or which will be subjected to drilling, sanding, grinding, cutting or abrading and which could be crushed or pulverized during anticipated renovation or demolition activities are considered RACM.

The State of Louisiana has established the LDEQ Asbestos Handbook, which requires any asbestos-related activity in a state building or school to be performed by an individual or company accredited or licensed by the State of Louisiana, through the LDEQ. An asbestos-related activity consists of the disturbance (whether intentional or unintentional) or abatement of ACM, the performance of asbestos surveys, the development of management plans and response actions, asbestos project design, the collection or analysis of asbestos samples, monitoring for airborne asbestos or any other activity required to be accredited or licensed under LDEQ Asbestos Handbook.

In non-state, non-school buildings, the following activities must be performed by accredited individuals or licensed companies: asbestos surveys, asbestos abatement, and monitoring for airborne asbestos. However, the EPA Model Accreditation Program (MAP) requires that a project design for the abatement of friable ACM (greater than a small-scale, short duration activity) be written by an EPA-accredited project designer.

Under Chapter 51, Section F, RACM must be removed prior to renovation or demolition activities that will disturb the materials. LDEQ requires a 10-working day notification (Form AAC-2) of any demolition activity, regardless of whether the building contains asbestos, and any renovation activity which disturbs RACM. In addition, LDEQ requires a 3-working day notification prior to the start of the removal of resilient floor covering by using dry ice, heat, wet methods, and chemicals where the tiles or sheeting are removed intact or asbestos-containing mastic removed by chemical or other means that results in the waste material being bound within a macro substrate and cannot reasonably become airborne. Any individual or company contracted to perform a demolition or renovation activity, which disturbs RACM, must be recognized by the Louisiana Licensing Board for Contractors to perform asbestos abatement.

The USOSHA asbestos standard for construction (29 CFR 1926.1101) regulates workplace exposure to asbestos. The USOSHA standard requires that employee exposure to airborne asbestos must not exceed 0.1 fibers per cubic centimeter of air (0.1 f/cc) as an eight hour time weighted average (TWA) and not exceed 1.0 fibers per cubic centimeter of air (1.0 f/cc) over a 30 minute time period known as an excursion limit (EL). The TWA and EL are known as USOSHA's asbestos permissible exposure limits (PELs). The USOSHA standard classifies construction and maintenance activities, which could disturb ACM, and specifies work practices and precautions, which employers must follow when engaging in each class of regulated work.

## **4.2 Lead Regulations**

Lead is regulated by the USEPA and USOSHA.

### **USEPA**

The Resource Conservation and Recovery Act (RCRA) gave the USEPA authority to regulate the waste status of demolition or renovation debris, including lead containing materials. Specific notification and testing requirements must be addressed prior to transporting, treating, storing, or disposing of hazardous wastes. Lead containing wastes are considered hazardous waste under RCRA if Toxicity Characteristic Leaching Procedure (TCLP) results exceed 5 milligrams per liter (mg/L). USEPA exempts from most RCRA requirements those generators whose combined hazardous waste generation is less than 100 kilograms (kg) per month. The USEPA also requires that personnel conducting lead-based paint removal activities be appropriately trained in accordance with 40 CFR 745.226. In accordance with EPA 40 CFR 745.225, contractors must notify the USEPA or governing state agency at least 5 business days prior to conducting lead-based paint abatement activities.

### **USOSHA**

All occupational exposure to lead occurring in the course of construction work, including maintenance activities, painting, alteration and repairs is subject to the USOSHA Lead Exposure in Construction standard (29 CFR 1926.62).

Construction work covered by 29 CFR 1926.62 includes any repair or renovation activities or other activities that disturb in-place lead-containing materials, but does not include routine cleaning and repainting where there is insignificant damage, wear, or corrosion of existing lead-containing coatings or substrates. Employers must assure that no employee will be exposed to lead at concentrations greater than 50 micrograms per cubic meter ( $\mu\text{g}/\text{m}^3$ ) averaged over an eight-hour period without adequate protection.

The above overview is not intended to be inclusive of all potentially pertinent regulatory information. The relevant USEPA and USOSHA standards should be consulted prior to undertaking activities involving the demolition, renovation, or maintenance of surfaces coated with lead-based paints.

## **4.3 Universal Waste Regulations**

Under the Louisiana Administrative Code (LAC) Title 33:V:38, the State of Louisiana has established requirements for managing batteries, pesticides, mercury-containing equipment, lamps, electronics, antifreeze, chlorofluorocarbons (CFC), and polychlorinated biphenyls (PCB) as universal waste. These specific materials and waste must be handled properly and disposed of accordingly in a facility that treats, disposes of, or recycles a particular category of universal

waste, except those management activities described in LAC 33:V.3821.A and C and 3843.A and C.

## **5.0 FINDINGS AND RECOMMENDATIONS**

### **5.1 Asbestos Survey**

Laboratory analysis confirmed the presence of asbestos in concentrations greater than 1% in the following materials:

- Black mirror mastic behind the restroom mirrors in the Pharmacy Building. Approximately 8 mirrors are affixed to the wall with black mastic.

Terracon recommends that the identified non-friable ACM, as outlined above, be removed and disposed of by a State of Louisiana licensed asbestos abatement contractor prior to renovation activities, in accordance with a project design prepared by a State of Louisiana accredited project designer. Licensed asbestos abatement contractors should be contacted to obtain competitive bids for removal of the identified ACM. Quantities are estimates only and must be verified by the abatement contractor.

It should be noted that suspect materials, other than those identified during this survey may exist within the buildings. Should suspect materials other than those which were identified during this survey be uncovered during the demolition process, those materials should be assumed asbestos-containing until sampling and analysis can confirm or deny their asbestos content.

A summary of the confirmed ACM is presented in Appendix A. Laboratory analytical reports are included in Appendix C. Photographs of each positive ACM identified during the survey are provided in a photographic log in Appendix E.

Terracon should be retained as the owner representative to develop an asbestos abatement specification for contractor bidding purposes and to conduct all abatement oversight and air monitoring.

### **5.2 LBP Survey**

Based on the XRF results of this survey, LBP was not identified in any painted surfaces tested in either the Dental Clinic or Pharmacy Building.

### **5.3 URW Survey**

Based on the visual assessment of the URW survey, the following waste materials that were identified are listed in Table 1 below:

**Asbestos, LBP & URW Survey Report**

ILH Dental Clinic and Pharmacy Building ■ New Orleans, Louisiana

December 18, 2015 ■ Terracon Project No. EH137101

LSUHSC PO No. 00374423B ■ Task Order No. 2016-01

**Table 1: Summary of URW Visual Assessment**

| Location                               | Material Description                | Quantity               |
|--|-------------------------------------|------------------------|
| Dental Clinic Building                 | Mercury-containing light tube       | 212                    |
|  | PCB-containing light ballast        | 76                     |
|  | Mercury-containing can lights       | 4                      |
|  | Dental surgery light                | 2                      |
|  | R-410 HVAC refrigerant              | 4 HVAC units           |
|  | Sharps containers                   | 15 boxes               |
|  | Biohazard trash receptacles         | 3 empty receptacles    |
| Pharmacy Building                      | Mercury-containing light tube       | 175                    |
|  | PCB-containing light ballast        | 65                     |
|  | Sharps containers                   | 5 full boxes           |
|  | Biohazard trash receptacles         | 6 full / 6 empty boxes |
|  | Misc. medical trash                 | 1 box                  |
|  | Standing freezer refrigerant        | 5 sample freezers      |
|  | Backup generator with diesel fuel   | Amount of fuel unknown |
| Kitchen Extension of Pharmacy Building | Mercury-containing light tube       | 50                     |
|  | Mercury-containing screw light bulb | 13                     |
|  | PCB-containing light ballast        | 25                     |
|  | Ecolab cleaning chemicals           | 3 gallons              |
|  | Walk-in freezer refrigerant         | 2 freezers             |
|  | Hydrologic equipment lift           | 1 unit                 |
|  | Used cooking oil                    | 100 gallons            |

Terracon recommends the materials identified in Table 1 above be handled properly and disposed of accordingly in a facility that treats, disposes of or recycles universal waste.

## 6.0 GENERAL COMMENTS

This asbestos, LBP, URW survey was conducted in a manner consistent with the level of care and skill ordinarily exercised by members of the profession currently practicing under similar conditions in the same locale. The results, findings, conclusions and recommendations expressed in this report are based on conditions observed during our survey of the buildings. The information contained in this report is relevant to the date(s) on which this survey was performed, and should not be relied upon to represent conditions at a later date. This report has been

**Asbestos, LBP & URW Survey Report**

ILH Dental Clinic and Pharmacy Building ■ New Orleans, Louisiana

December 18, 2015 ■ Terracon Project No. EH137101

LSUHSC PO No. 00374423B ■ Task Order No. 2016-01



prepared on behalf of and exclusively for use by the LSUHSC for specific application to their project as discussed. This report is not a bidding document. Contractors or consultants reviewing this report must draw their own conclusions regarding further investigation or remediation deemed necessary. Terracon does not warrant the work of regulatory agencies, laboratories or other third parties supplying information, which may have been used in the preparation of this report. No warranty, express or implied is made.

**APPENDIX A**  
**ASBESTOS SURVEY SAMPLE LOCATION SUMMARY**

| HA No. | Material Description                          | Sample Number | Material Location | Lab Results                          | Estimated Quantity |
|--------|---|---------------|-------------------|--------------------------------------|--------------------|
| 01     | 2' X 2' Ceiling Tile                          | 01-CT3-01     | Dental Clinic     | None Detected - 2'x2'<br>worm/pin CT | 3,000 Sq.<br>Ft.   |
| 01     | 2' X 2' Ceiling Tile                          | 01-CT3-02     | Dental Clinic     | None Detected - 2'x2'<br>worm/pin CT | 3,000 Sq.<br>Ft.   |
| 01     | 2' X 2' Ceiling Tile                          | 01-CT3-03     | Dental Clinic     | None Detected - 2'x2'<br>worm/pin CT | 3,000 Sq.<br>Ft.   |
| 02     | Gypsum Wallboard with Joint Compound and Tape | 02-WB1-04     | Dental Clinic     | None Detected - Texture              | 20,000 Sq.<br>Ft.  |
| 02     | Gypsum Wallboard with Joint Compound and Tape | 02-WB1-04     | Dental Clinic     | None Detected - Joint<br>Compound    | 20,000 Sq.<br>Ft.  |
| 02     | Gypsum Wallboard with Joint Compound and Tape | 02-WB1-04     | Dental Clinic     | None Detected -<br>Sheetrock         | 20,000 Sq.<br>Ft.  |
| 02     | Gypsum Wallboard with Joint Compound and Tape | 02-WB1-05     | Dental Clinic     | None Detected - Texture              | 20,000 Sq.<br>Ft.  |
| 02     | Gypsum Wallboard with Joint Compound and Tape | 02-WB1-05     | Dental Clinic     | None Detected - Joint<br>Compound    | 20,000 Sq.<br>Ft.  |
| 02     | Gypsum Wallboard with Joint Compound and Tape | 02-WB1-05     | Dental Clinic     | None Detected -<br>Sheetrock         | 20,000 Sq.<br>Ft.  |
| 02     | Gypsum Wallboard with Joint Compound and Tape | 02-WB1-06     | Dental Clinic     | None Detected - Texture              | 20,000 Sq.<br>Ft.  |
| 02     | Gypsum Wallboard with Joint Compound and Tape | 02-WB1-06     | Dental Clinic     | None Detected - Joint<br>Compound    | 20,000 Sq.<br>Ft.  |
| 02     | Gypsum Wallboard with Joint Compound and Tape | 02-WB1-06     | Dental Clinic     | None Detected -<br>Sheetrock         | 20,000 Sq.<br>Ft.  |
| 02     | Gypsum Wallboard with Joint Compound and Tape | 02-WB1-07     | Dental Clinic     | None Detected -<br>Sheetrock         | 20,000 Sq.<br>Ft.  |
| 02     | Gypsum Wallboard with Joint Compound and Tape | 02-WB1-08     | Dental Clinic     | None Detected - Texture              | 20,000 Sq.<br>Ft.  |
| 02     | Gypsum Wallboard with Joint Compound and Tape | 02-WB1-08     | Dental Clinic     | None Detected - Joint<br>Compound    | 20,000 Sq.<br>Ft.  |
| 02     | Gypsum Wallboard with Joint Compound and Tape | 02-WB1-08     | Dental Clinic     | None Detected -<br>Sheetrock         | 20,000 Sq.<br>Ft.  |
| 02     | Gypsum Wallboard with Joint Compound and Tape | 02-WB1-09     | Dental Clinic     | None Detected - Texture              | 20,000 Sq.<br>Ft.  |

| <b>HA No.</b> | <b>Material Description</b>                   | <b>Sample Number</b> | <b>Material Location</b> | <b>Lab Results</b>                 | <b>Estimated Quantity</b> |
|---------------|---|----------------------|--------------------------|------------------------------------|---------------------------|
| 02            | Gypsum Wallboard with Joint Compound and Tape | 02-WB1-09            | Dental Clinic            | None Detected - Sheetrock          | 20,000 Sq. Ft.            |
| 02            | Gypsum Wallboard with Joint Compound and Tape | 02-WB1-10            | Dental Clinic            | None Detected - Texture            | 20,000 Sq. Ft.            |
| 02            | Gypsum Wallboard with Joint Compound and Tape | 02-WB1-10            | Dental Clinic            | None Detected - Joint Compound     | 20,000 Sq. Ft.            |
| 02            | Gypsum Wallboard with Joint Compound and Tape | 02-WB1-10            | Dental Clinic            | None Detected - Sheetrock          | 20,000 Sq. Ft.            |
| 03            | Mastic Behind Cove Base                       | 03-MG3-11            | Dental Clinic            | None Detected - Cove base adhesive | 5,000 Sq. Ft.             |
| 03            | Mastic Behind Cove Base                       | 03-MG3-12            | Dental Clinic            | None Detected - Cove base adhesive | 5,000 Sq. Ft.             |
| 03            | Mastic Behind Cove Base                       | 03-MG3-13            | Dental Clinic            | None Detected - Cove base adhesive | 5,000 Sq. Ft.             |
| 04            | 12"x12" Tan Floor Tile with Yellow Glue       | 04-FT5-14            | Dental Clinic            | None Detected - Floor Tile         | 3,000 Sq. Ft.             |
| 04            | 12"x12" Tan Floor Tile with Yellow Glue       | 04-FT5-14            | Dental Clinic            | None Detected - Mastic             | 3,000 Sq. Ft.             |
| 04            | 12"x12" Tan Floor Tile with Yellow Glue       | 04-FT5-14            | Dental Clinic            | None Detected - Leveler            | 3,000 Sq. Ft.             |
| 04            | 12"x12" Tan Floor Tile with Yellow Glue       | 04-FT5-15            | Dental Clinic            | None Detected - Floor Tile         | 3,000 Sq. Ft.             |
| 04            | 12"x12" Tan Floor Tile with Yellow Glue       | 04-FT5-15            | Dental Clinic            | None Detected - Mastic             | 3,000 Sq. Ft.             |
| 04            | 12"x12" Tan Floor Tile with Yellow Glue       | 04-FT5-15            | Dental Clinic            | None Detected - Leveler            | 3,000 Sq. Ft.             |
| 04            | 12"x12" Tan Floor Tile with Yellow Glue       | 04-FT5-16            | Dental Clinic            | None Detected - Floor Tile         | 3,000 Sq. Ft.             |
| 04            | 12"x12" Tan Floor Tile with Yellow Glue       | 04-FT5-16            | Dental Clinic            | None Detected - Mastic/Leveler     | 3,000 Sq. Ft.             |
| 05            | 12"x12" Blue Floor Tile with Yellow Glue      | 05-FT5-17            | Dental Clinic            | None Detected - Floor Tile         | 1,000 Sq. Ft.             |
| 05            | 12"x12" Blue Floor Tile with Yellow Glue      | 05-FT5-17            | Dental Clinic            | None Detected - Leveler            | 1,000 Sq. Ft.             |
| 05            | 12"x12" Blue Floor Tile with Yellow Glue      | 05-FT5-18            | Dental Clinic            | None Detected - Floor Tile         | 1,000 Sq. Ft.             |
| 05            | 12"x12" Blue Floor Tile with Yellow Glue      | 05-FT5-18            | Dental Clinic            | None Detected - Mastic             | 1,000 Sq. Ft.             |

| HA No. | Material Description                      | Sample Number | Material Location | Lab Results                        | Estimated Quantity |
|--------|---|---------------|-------------------|------------------------------------|--------------------|
| 05     | 12"x12" Blue Floor Tile with Yellow Glue  | 05-FT5-18     | Dental Clinic     | None Detected - Leveler            | 1,000 Sq. Ft.      |
| 05     | 12"x12" Blue Floor Tile with Yellow Glue  | 05-FT5-19     | Dental Clinic     | None Detected - Floor Tile         | 1,000 Sq. Ft.      |
| 05     | 12"x12" Blue Floor Tile with Yellow Glue  | 05-FT5-19     | Dental Clinic     | None Detected - Mastic             | 1,000 Sq. Ft.      |
| 05     | 12"x12" Blue Floor Tile with Yellow Glue  | 05-FT5-19     | Dental Clinic     | None Detected - Leveler            | 1,000 Sq. Ft.      |
| 06     | 12"x12" Brown Floor Tile with Yellow Glue | 06-FT5-20     | Dental Clinic     | None Detected - Floor Tile         | 500 Sq. Ft.        |
| 06     | 12"x12" Brown Floor Tile with Yellow Glue | 06-FT5-20     | Dental Clinic     | None Detected - Mastic             | 500 Sq. Ft.        |
| 06     | 12"x12" Brown Floor Tile with Yellow Glue | 06-FT5-20     | Dental Clinic     | None Detected - Leveler            | 500 Sq. Ft.        |
| 06     | 12"x12" Brown Floor Tile with Yellow Glue | 06-FT5-21     | Dental Clinic     | None Detected - Floor Tile         | 500 Sq. Ft.        |
| 06     | 12"x12" Brown Floor Tile with Yellow Glue | 06-FT5-21     | Dental Clinic     | None Detected - Mastic             | 500 Sq. Ft.        |
| 06     | 12"x12" Brown Floor Tile with Yellow Glue | 06-FT5-21     | Dental Clinic     | None Detected - Leveler            | 500 Sq. Ft.        |
| 06     | 12"x12" Brown Floor Tile with Yellow Glue | 06-FT5-22     | Dental Clinic     | None Detected - Floor Tile         | 500 Sq. Ft.        |
| 06     | 12"x12" Brown Floor Tile with Yellow Glue | 06-FT5-22     | Dental Clinic     | None Detected - Mastic/Leveler     | 500 Sq. Ft.        |
| 07     | Carpet Glue                               | 07-MG7-23     | Dental Clinic     | None Detected - Yellow carpet glue | 185 Sq. Ft.        |
| 07     | Carpet Glue                               | 07-MG7-24     | Dental Clinic     | None Detected - Yellow carpet glue | 185 Sq. Ft.        |
| 07     | Carpet Glue                               | 07-MG7-25     | Dental Clinic     | None Detected - Yellow carpet glue | 185 Sq. Ft.        |
| 08     | Sheet Vinyl//Paper Backing                | 08-SG1-26     | Dental Clinic     | None Detected - Flooring           | 120 Sq. Ft.        |
| 08     | Sheet Vinyl//Paper Backing                | 08-SG1-26     | Dental Clinic     | None Detected - Glue               | 120 Sq. Ft.        |
| 08     | Sheet Vinyl//Paper Backing                | 08-SG1-26     | Dental Clinic     | None Detected - Leveler            | 120 Sq. Ft.        |
| 08     | Sheet Vinyl//Paper Backing                | 08-SG1-27     | Dental Clinic     | None Detected - Flooring           | 120 Sq. Ft.        |
| 08     | Sheet Vinyl//Paper Backing                | 08-SG1-27     | Dental Clinic     | None Detected - Glue               | 120 Sq. Ft.        |
| 08     | Sheet Vinyl//Paper Backing                | 08-SG1-27     | Dental Clinic     | None Detected - Leveler            | 120 Sq. Ft.        |
| 08     | Sheet Vinyl//Paper Backing                | 08-SG1-28     | Dental Clinic     | None Detected - Flooring           | 120 Sq. Ft.        |
| 08     | Sheet Vinyl//Paper Backing                | 08-SG1-28     | Dental Clinic     | None Detected - Glue               | 120 Sq. Ft.        |
| 08     | Sheet Vinyl//Paper Backing                | 08-SG1-28     | Dental Clinic     | None Detected - Leveler            | 120 Sq. Ft.        |
| 09     | Duct Insulation                           | 09-MI4-29     | Dental Clinic     | None Detected - Wrap               | 700 Sq. Ft.        |
| 09     | Duct Insulation                           | 09-MI4-29     | Dental Clinic     | Insulation                         | 700 Sq. Ft.        |
| 09     | Duct Insulation                           | 09-MI4-30     | Dental Clinic     | None Detected - Wrap               | 700 Sq. Ft.        |

| HA No. | Material Description            | Sample Number | Material Location | Lab Results                                       | Estimated Quantity |
|--------|---------------------------------|---------------|-------------------|---|--------------------|
| 09     | Duct Insulation                 | 09-MI4-30     | Dental Clinic     | None Detected - Insulation                        | 700 Sq. Ft.        |
| 09     | Duct Insulation                 | 09-MI4-31     | Dental Clinic     | None Detected - Wrap                              | 700 Sq. Ft.        |
| 09     | Duct Insulation                 | 09-MI4-31     | Dental Clinic     | None Detected - Insulation                        | 700 Sq. Ft.        |
| 10     | Sink Undercoating               | 10-SC6-32     | Dental Clinic     | None Detected - Sink under coating                | 2 Sq. Ft.          |
| 10     | Sink Undercoating               | 10-SC6-33     | Dental Clinic     | None Detected - Sink under coating                | 2 Sq. Ft.          |
| 10     | Sink Undercoating               | 10-SC6-34     | Dental Clinic     | None Detected - Sink under coating                | 2 Sq. Ft.          |
| 11     | Laminate Counter Tops with Glue | 11-MG5-35     | Dental Clinic     | None Detected - Laminate countertop under coating | 300 Sq. Ft.        |
| 11     | Laminate Counter Tops with Glue | 11-MG5-36     | Dental Clinic     | None Detected - Laminate countertop               | 300 Sq. Ft.        |
| 11     | Laminate Counter Tops with Glue | 11-MG5-37     | Dental Clinic     | None Detected - Laminate countertop               | 300 Sq. Ft.        |
| 12     | Black Insulation of Water Pipes | 12-PI5-38     | Dental Clinic     | None Detected - Tape                              | 500 Linear Ft.     |
| 12     | Black Insulation of Water Pipes | 12-PI5-38     | Dental Clinic     | None Detected - Insulation                        | 500 Linear Ft.     |
| 12     | Black Insulation of Water Pipes | 12-PI5-39     | Dental Clinic     | None Detected - Tape                              | 500 Linear Ft.     |
| 12     | Black Insulation of Water Pipes | 12-PI5-39     | Dental Clinic     | None Detected - Insulation                        | 500 Linear Ft.     |
| 12     | Black Insulation of Water Pipes | 12-PI5-40     | Dental Clinic     | None Detected - Tape                              | 500 Linear Ft.     |
| 12     | Black Insulation of Water Pipes | 12-PI5-40     | Dental Clinic     | None Detected - Insulation                        | 500 Linear Ft.     |
| 13     | Fire Stop Caulk                 | 13-CA7-41     | Dental Clinic     | None Detected - Fire stop caulk                   | 100 Linear Ft.     |
| 13     | Fire Stop Caulk                 | 13-CA7-42     | Dental Clinic     | None Detected - Fire stop caulk                   | 100 Linear Ft.     |
| 13     | Fire Stop Caulk                 | 13-CA7-43     | Dental Clinic     | None Detected - Fire stop caulk                   | 100 Linear Ft.     |
| 14     | 2' X 2' Ceiling Tile            | 14-CT3-44     | Pharmacy (Lab)    | None Detected - 2'x2' texture CT                  | 700 Sq. Ft.        |
| 14     | 2' X 2' Ceiling Tile            | 14-CT3-45     | Pharmacy (Lab)    | None Detected - 2'x2' texture CT                  | 700 Sq. Ft.        |

| HA No. | Material Description                             | Sample Number | Material Location      | Lab Results                          | Estimated Quantity |
|--------|--|---------------|------------------------|--------------------------------------|--------------------|
| 14     | 2' X 2' Ceiling Tile                             | 14-CT13-46    | Pharmacy (Lab)         | None Detected - 2'x2'<br>texture CT  | 700 Sq. Ft.        |
| 15     | 2' X 2' Ceiling Tile                             | 15-CT13-47    | Pharmacy               | None Detected - 2'x2'<br>worm/pin CT | 3,500 Sq.<br>Ft.   |
| 15     | 2' X 2' Ceiling Tile                             | 15-CT13-48    | Pharmacy (Hall)        | None Detected - 2'x2'<br>worm/pin CT | 3,500 Sq.<br>Ft.   |
| 15     | 2' X 2' Ceiling Tile                             | 15-CT13-49    | Pharmacy (Rm<br>P0100) | None Detected - 2'x2'<br>worm/pin CT | 3,500 Sq.<br>Ft.   |
| 16     | Gypsum Wallboard with Joint Compound and<br>Tape | 16-WB1-50     | Pharmacy<br>(P0100)    | None Detected - Texture<br>Ft.       | 10,000 Sq.<br>Ft.  |
| 16     | Gypsum Wallboard with Joint Compound and<br>Tape | 16-WB1-50     | Pharmacy<br>(P0100)    | None Detected - Joint<br>Compound    | 10,000 Sq.<br>Ft.  |
| 16     | Gypsum Wallboard with Joint Compound and<br>Tape | 16-WB1-50     | Pharmacy<br>(P0100)    | None Detected -<br>Sheetrock         | 10,000 Sq.<br>Ft.  |
| 16     | Gypsum Wallboard with Joint Compound and<br>Tape | 16-WB1-51     | Pharmacy (Hall)        | None Detected - Texture<br>Compound  | 10,000 Sq.<br>Ft.  |
| 16     | Gypsum Wallboard with Joint Compound and<br>Tape | 16-WB1-51     | Pharmacy (Hall)        | None Detected - Joint<br>Compound    | 10,000 Sq.<br>Ft.  |
| 16     | Gypsum Wallboard with Joint Compound and<br>Tape | 16-WB1-51     | Pharmacy (Hall)        | None Detected -<br>Sheetrock         | 10,000 Sq.<br>Ft.  |
| 16     | Gypsum Wallboard with Joint Compound and<br>Tape | 16-WB1-52     | Pharmacy               | None Detected - Texture<br>Ft.       | 10,000 Sq.<br>Ft.  |
| 16     | Gypsum Wallboard with Joint Compound and<br>Tape | 16-WB1-52     | Pharmacy               | None Detected -<br>Sheetrock         | 10,000 Sq.<br>Ft.  |
| 16     | Gypsum Wallboard with Joint Compound and<br>Tape | 16-WB1-53     | Pharmacy               | None Detected - Texture<br>Ft.       | 10,000 Sq.<br>Ft.  |
| 16     | Gypsum Wallboard with Joint Compound and<br>Tape | 16-WB1-53     | Pharmacy               | None Detected - Joint<br>Compound    | 10,000 Sq.<br>Ft.  |
| 16     | Gypsum Wallboard with Joint Compound and<br>Tape | 16-WB1-53     | Pharmacy               | None Detected -<br>Sheetrock         | 10,000 Sq.<br>Ft.  |
| 16     | Gypsum Wallboard with Joint Compound and<br>Tape | 16-WB1-54     | Pharmacy               | None Detected - Texture<br>Compound  | 10,000 Sq.<br>Ft.  |
| 16     | Gypsum Wallboard with Joint Compound and<br>Tape | 16-WB1-54     | Pharmacy               | None Detected -<br>Sheetrock         | 10,000 Sq.<br>Ft.  |
| 16     | Gypsum Wallboard with Joint Compound and<br>Tape | 16-WB1-55     | Pharmacy               | None Detected - Texture<br>Compound  | 10,000 Sq.<br>Ft.  |
| 16     | Gypsum Wallboard with Joint Compound and<br>Tape | 16-WB1-55     | Pharmacy               | None Detected - Joint<br>Compound    | 10,000 Sq.<br>Ft.  |

| <b>HA No.</b> | <b>Material Description</b>                       | <b>Sample Number</b> | <b>Material Location</b> | <b>Lab Results</b>             | <b>Estimated Quantity</b> |
|---------------|---|----------------------|--------------------------|--------------------------------|---------------------------|
| 16            | Gypsum Wallboard with Joint Compound and Tape     | 16-WB1-55            | Pharmacy                 | None Detected - Sheetrock      | 10,000 Sq. Ft.            |
| 16            | Gypsum Wallboard with Joint Compound and Tape     | 16-WB1-56            | Pharmacy (Lab)           | None Detected - Texture        | 10,000 Sq. Ft.            |
| 16            | Gypsum Wallboard with Joint Compound and Tape     | 16-WB1-56            | Pharmacy (Lab)           | None Detected - Joint Compound | 10,000 Sq. Ft.            |
| 16            | Gypsum Wallboard with Joint Compound and Tape     | 16-WB1-56            | Pharmacy (Lab)           | None Detected - Sheetrock      | 10,000 Sq. Ft.            |
| 17            | Clear Mastic on Fiber Reinforced Plastic Wainscot | 17-MG5-57            | Pharmacy (Hall)          | None Detected - Mastic         | 800 Sq. Ft.               |
| 17            | Clear Mastic on Fiber Reinforced Plastic Wainscot | 17-MG5-58            | Pharmacy (Hall)          | None Detected - Mastic         | 800 Sq. Ft.               |
| 17            | Clear Mastic on Fiber Reinforced Plastic Wainscot | 17-MG5-59            | Pharmacy (Hall)          | None Detected - Mastic         | 800 Sq. Ft.               |
| 18            | Mastic Behind Cove Base                           | 18-MG3-60            | Pharmacy                 | None Detected - Adhesive       | 2,000 Sq. Ft.             |
| 18            | Mastic Behind Cove Base                           | 18-MG3-61            | Pharmacy                 | None Detected - Adhesive       | 2,000 Sq. Ft.             |
| 18            | Mastic Behind Cove Base                           | 18-MG3-62            | Pharmacy                 | None Detected - Adhesive       | 2,000 Sq. Ft.             |
| 19            | 12"x12" Tan Floor Tile with Yellow Glue           | 19-FT15-63           | Pharmacy                 | None Detected - Floor Tile     | 2,500 Sq. Ft.             |
| 19            | 12"x12" Tan Floor Tile with Yellow Glue           | 19-FT15-63           | Pharmacy                 | None Detected - Mastic         | 2,500 Sq. Ft.             |
| 19            | 12"x12" Tan Floor Tile with Yellow Glue           | 19-FT15-64           | Pharmacy                 | None Detected - Floor Tile     | 2,500 Sq. Ft.             |
| 19            | 12"x12" Tan Floor Tile with Yellow Glue           | 19-FT15-64           | Pharmacy                 | None Detected - Mastic         | 2,500 Sq. Ft.             |
| 19            | 12"x12" Tan Floor Tile with Yellow Glue           | 19-FT15-65           | Pharmacy                 | None Detected - Floor Tile     | 2,500 Sq. Ft.             |
| 19            | 12"x12" Tan Floor Tile with Yellow Glue           | 19-FT15-65           | Pharmacy                 | None Detected - Mastic         | 2,500 Sq. Ft.             |
| 20            | 12"x12" Off-White Floor Tile with Yellow Glue     | 20-FT5-66            | Pharmacy                 | None Detected - Floor Tile     | 3,000 Sq. Ft.             |
| 20            | 12"x12" Off-White Floor Tile with Yellow Glue     | 20-FT5-66            | Pharmacy                 | None Detected - Mastic         | 3,000 Sq. Ft.             |
| 20            | 12"x12" Off-White Floor Tile with Yellow Glue     | 20-FT5-67            | Pharmacy                 | None Detected - Floor Tile     | 3,000 Sq. Ft.             |

| HA No. | Material Description                             | Sample Number | Material Location | Lab Results                | Estimated Quantity |
|--------|--|---------------|-------------------|----------------------------|--------------------|
| 20     | 12"x12" Off-White Floor Tile with Yellow Glue    | 20-FT5-67     | Pharmacy          | None Detected - Mastic     | 3,000 Sq. Ft.      |
| 20     | 12"x12" Off-White Floor Tile with Yellow Glue    | 20-FT5-68     | Pharmacy          | None Detected - Floor Tile | 3,000 Sq. Ft.      |
| 20     | 12"x12" Off-White Floor Tile with Yellow Glue    | 20-FT5-68     | Pharmacy          | None Detected - Mastic     | 3,000 Sq. Ft.      |
| 21     | 12"x12" Blue Floor Tile with Yellow Glue         | 21-FT5-69     | Pharmacy          | None Detected - Floor Tile | 100 Sq. Ft.        |
| 21     | 12"x12" Blue Floor Tile with Yellow Glue         | 21-FT5-69     | Pharmacy          | None Detected - Mastic     | 100 Sq. Ft.        |
| 21     | 12"x12" Blue Floor Tile with Yellow Glue         | 21-FT5-70     | Pharmacy          | None Detected - Floor Tile | 100 Sq. Ft.        |
| 21     | 12"x12" Blue Floor Tile with Yellow Glue         | 21-FT5-70     | Pharmacy          | None Detected - Mastic     | 100 Sq. Ft.        |
| 21     | 12"x12" Blue Floor Tile with Yellow Glue         | 21-FT5-71     | Pharmacy          | None Detected - Floor Tile | 100 Sq. Ft.        |
| 21     | 12"x12" Blue Floor Tile with Yellow Glue         | 21-FT5-71     | Pharmacy          | None Detected - Mastic     | 100 Sq. Ft.        |
| 21     | 12"x12" Light Brown Floor Tile with Yellow Glue  | 22-FT5-72     | Pharmacy          | None Detected - Floor Tile | 80 Sq. Ft.         |
| 22     | 12"x12" Light Brown Floor Tile with Yellow Glue  | 22-FT5-72     | Pharmacy          | None Detected - Mastic     | 100 Sq. Ft.        |
| 22     | 12"x12" Light Brown Floor Tile with Yellow Glue  | 22-FT5-73     | Pharmacy          | None Detected - Floor Tile | 80 Sq. Ft.         |
| 22     | 12"x12" Light Brown Floor Tile with Yellow Glue  | 22-FT5-74     | Pharmacy          | None Detected - Mastic     | 80 Sq. Ft.         |
| 22     | 12"x12" Light Brown Floor Tile with Yellow Glue  | 22-FT5-74     | Pharmacy          | None Detected - Floor Tile | 80 Sq. Ft.         |
| 22     | 12"x12" Light Brown Floor Tile with Yellow Glue  | 22-FT5-74     | Pharmacy          | None Detected - Mastic     | 80 Sq. Ft.         |
| 23     | 12"x12" Dark Brown Floor Tile with Yellow Glue   | 23-FT5-75     | Pharmacy          | None Detected - Floor Tile | 80 Sq. Ft.         |
| 23     | 12"x12" Dark Brown Floor Tile with Yellow Glue   | 23-FT5-76     | Pharmacy          | None Detected - Floor Tile | 80 Sq. Ft.         |
| 23     | 12"x12" Dark Brown Floor Tile with Yellow Glue   | 23-FT5-77     | Pharmacy          | None Detected - Floor Tile | 80 Sq. Ft.         |
| 23     | 12"x12" Dark Brown Floor Tile with Yellow Glue   | 23-FT5-77     | Pharmacy          | None Detected - Mastic     | 80 Sq. Ft.         |
| 24     | 12"x12" White Streak Floor Tile with Yellow Glue | 24-FT5-78     | Pharmacy          | None Detected - Floor Tile | 300 Sq. Ft.        |
| 24     | 12"x12" White Streak Floor Tile with Yellow Glue | 24-FT5-78     | Pharmacy          | None Detected - Mastic     | 300 Sq. Ft.        |
| 24     | 12"x12" White Streak Floor Tile with Yellow Glue | 24-FT5-79     | Pharmacy          | None Detected - Floor Tile | 300 Sq. Ft.        |

| HA No. | Material Description                             | Sample Number | Material Location | Lab Results                          | Estimated Quantity |
|--------|--|---------------|-------------------|--------------------------------------|--------------------|
| 24     | 12"x12" White Streak Floor Tile with Yellow Glue | 24-FT5-80     | Pharmacy          | None Detected - Floor Tile           | 300 Sq. Ft.        |
| 25     | Carpet Glue                                      | 25-MG7-81     | Pharmacy          | None Detected - Yellow carpet glue   | 2,000 Sq. Ft.      |
| 25     | Carpet Glue                                      | 25-MG7-82     | Pharmacy          | None Detected - Yellow carpet glue   | 2,000 Sq. Ft.      |
| 25     | Carpet Glue                                      | 25-MG7-83     | Pharmacy          | None Detected - Yellow carpet glue   | 2,000 Sq. Ft.      |
| 26     | Sheet Vinyl Flooring/Paper Backing               | 26-FC1-84     | Pharmacy          | None Detected - Floor Tile           | 600 Sq. Ft.        |
| 26     | Sheet Vinyl Flooring/Paper Backing               | 26-FC1-84     | Pharmacy          | None Detected - Mastic               | 600 Sq. Ft.        |
| 26     | Sheet Vinyl Flooring/Paper Backing               | 26-FC1-85     | Pharmacy          | None Detected - Floor Tile           | 600 Sq. Ft.        |
| 26     | Sheet Vinyl Flooring/Paper Backing               | 26-FC1-85     | Pharmacy          | None Detected - Mastic               | 600 Sq. Ft.        |
| 26     | Sheet Vinyl Flooring/Paper Backing               | 26-FC1-86     | Pharmacy          | None Detected - Floor Tile           | 600 Sq. Ft.        |
| 27     | Sheet Vinyl Flooring/Paper Backing               | 27-FC1-86     | Pharmacy          | None Detected - Mastic               | 400 Sq. Ft.        |
| 27     | Sheet Vinyl Flooring/Paper Backing               | 27-FC1-87     | Pharmacy          | None Detected - Flooring             | 400 Sq. Ft.        |
| 27     | Sheet Vinyl Flooring/Paper Backing               | 27-FC1-87     | Pharmacy          | None Detected - Mastic               | 400 Sq. Ft.        |
| 27     | Sheet Vinyl Flooring/Paper Backing               | 27-FC1-88     | Pharmacy          | None Detected - Flooring             | 400 Sq. Ft.        |
| 27     | Sheet Vinyl Flooring/Paper Backing               | 27-FC1-88     | Pharmacy          | None Detected - Mastic               | 400 Sq. Ft.        |
| 27     | Sheet Vinyl Flooring/Paper Backing               | 27-FC1-89     | Pharmacy          | None Detected - Flooring             | 400 Sq. Ft.        |
| 27     | Sheet Vinyl Flooring/Paper Backing               | 27-FC1-89     | Pharmacy          | None Detected - Mastic               | 400 Sq. Ft.        |
| 28     | Sheet Vinyl/Paper Backing                        | 28-SG1-90     | Pharmacy          | None Detected - Formica              | 200 Sq. Ft.        |
| 28     | Sheet Vinyl/Paper Backing                        | 28-SG1-90     | Pharmacy          | None Detected - Adhesive             | 200 Sq. Ft.        |
| 28     | Sheet Vinyl/Paper Backing                        | 28-SG1-91     | Pharmacy          | None Detected - Formica              | 200 Sq. Ft.        |
| 28     | Sheet Vinyl/Paper Backing                        | 28-SG1-91     | Pharmacy          | None Detected - Adhesive             | 200 Sq. Ft.        |
| 28     | Sheet Vinyl/Paper Backing                        | 28-SG1-92     | Pharmacy          | None Detected - Formica              | 200 Sq. Ft.        |
| 28     | Sheet Vinyl/Paper Backing                        | 28-SG1-92     | Pharmacy          | None Detected - Adhesive             | 200 Sq. Ft.        |
| 29     | Black Mirror Mastic Dots                         | 29-MG5-93     | Pharmacy          | 10% Chrysotile - Black Mirror Mastic | 8 Mirrors          |
| 29     | Black Mirror Mastic Dots                         | 29-MG5-94     | Pharmacy          | 15.4% - Point Count                  | 8 Mirrors          |
| 29     | Black Mirror Mastic Dots                         | 29-MG5-95     | Pharmacy          | 10% Chrysotile - Black Mirror Mastic | 8 Mirrors          |
|        |  |               |                   | 10% Chrysotile - Black Mirror Mastic | 8 Mirrors          |

| <b>HA No.</b> | <b>Material Description</b>                   | <b>Sample Number</b> | <b>Material Location</b> | <b>Lab Results</b>                   | <b>Estimated Quantity</b> |
|---------------|---|----------------------|--------------------------|--------------------------------------|---------------------------|
| 30            | Duct Insulation                               | 30-MI4-96            | Pharmacy                 | None Detected - Wrap                 | 600 Sq. Ft.               |
| 30            | Duct Insulation                               | 30-MI4-96            | Pharmacy                 | None Detected - Insulation           | 600 Sq. Ft.               |
| 30            | Duct Insulation                               | 30-MI4-97            | Pharmacy                 | None Detected - Wrap                 | 600 Sq. Ft.               |
| 30            | Duct Insulation                               | 30-MI4-97            | Pharmacy                 | None Detected - Insulation           | 600 Sq. Ft.               |
| 30            | Duct Insulation                               | 30-MI4-98            | Pharmacy                 | None Detected - Wrap                 | 600 Sq. Ft.               |
| 30            | Duct Insulation                               | 30-MI4-98            | Pharmacy                 | None Detected - Insulation           | 600 Sq. Ft.               |
| 31            | Fire Stop Caulk                               | 31-CA7-99            | Pharmacy                 | None Detected - Fire stop caulk      | 50 Linear Ft.             |
| 31            | Fire Stop Caulk                               | 31-CA7-100           | Pharmacy                 | None Detected - Fire stop caulk      | 50 Linear Ft.             |
| 31            | Fire Stop Caulk                               | 31-CA7-101           | Pharmacy                 | None Detected - Fire stop caulk      | 50 Linear Ft.             |
| 32            | Fiberglass Pipe Insulation                    | 32-PI4-102           | Pharmacy                 | None Detected - Pipe insulation wrap | 1,000 Linear Ft.          |
| 32            | Fiberglass Pipe Insulation                    | 32-PI4-103           | Pharmacy                 | None Detected - Pipe insulation wrap | 1,000 Linear Ft.          |
| 32            | Fiberglass Pipe Insulation                    | 32-PI4-104           | Pharmacy                 | None Detected - Pipe insulation wrap | 1,000 Linear Ft.          |
| 33            | Gypsum Wallboard with Joint Compound and Tape | 33-WB1-105           | Pharmacy                 | None Detected - Texture              | 700 Sq. Ft.               |
| 33            | Gypsum Wallboard with Joint Compound and Tape | 33-WB1-105           | Pharmacy                 | None Detected - Joint Compound       | 700 Sq. Ft.               |
| 33            | Gypsum Wallboard with Joint Compound and Tape | 33-WB1-105           | Pharmacy                 | None Detected - Sheetrock            | 700 Sq. Ft.               |
| 33            | Gypsum Wallboard with Joint Compound and Tape | 33-WB1-106           | Pharmacy                 | None Detected - Texture              | 700 Sq. Ft.               |
| 33            | Gypsum Wallboard with Joint Compound and Tape | 33-WB1-106           | Pharmacy                 | None Detected - Joint Compound       | 700 Sq. Ft.               |
| 33            | Gypsum Wallboard with Joint Compound and Tape | 33-WB1-106           | Pharmacy                 | None Detected - Sheetrock            | 700 Sq. Ft.               |
| 33            | Gypsum Wallboard with Joint Compound and Tape | 33-WB1-107           | Pharmacy                 | None Detected - Texture              | 700 Sq. Ft.               |
| 33            | Gypsum Wallboard with Joint Compound and Tape | 33-WB1-107           | Pharmacy                 | None Detected - Joint Compound       | 700 Sq. Ft.               |
| 33            | Gypsum Wallboard with Joint Compound and Tape | 33-WB1-107           | Pharmacy                 | None Detected - Sheetrock            | 700 Sq. Ft.               |

| <b>HA No.</b> | <b>Material Description</b>              | <b>Sample Number</b> | <b>Material Location</b> | <b>Lab Results</b>                               | <b>Estimated Quantity</b> |
|---------------|--|----------------------|--------------------------|--|---------------------------|
| 34            | Exterior HVAC Pipe Insulation            | 34-PI5-108           | Pharmacy                 | None Detected - Exterior pipe insulation on HVAC | 200 Linear Ft.            |
| 34            | Exterior HVAC Pipe Insulation            | 34-PI5-109           | Pharmacy                 | None Detected - Exterior pipe insulation on HVAC | 200 Linear Ft.            |
| 34            | Exterior HVAC Pipe Insulation            | 34-PI5-110           | Pharmacy                 | None Detected - Exterior pipe insulation on HVAC | 200 Linear Ft.            |
| 35            | Roofing Flashing/Penetration Tar         | 35-RF4-111           | Pharmacy                 | None Detected - Vent flashing on roof            | 50 Sq. Ft.                |
| 35            | Roofing Flashing/Penetration Tar         | 35-RF4-112           | Pharmacy                 | None Detected - Vent flashing on roof            | 50 Sq. Ft.                |
| 35            | Roofing Flashing/Penetration Tar         | 35-RF4-113           | Pharmacy                 | None Detected - Vent flashing on roof            | 50 Sq. Ft.                |
| 36            | Built-Up Roofing                         | 36-RF8-114           | Pharmacy                 | None Detected - Pitch tar walkway roof           | 400 Sq. Ft.               |
| 36            | Built-Up Roofing                         | 36-RF8-115           | Pharmacy                 | None Detected - Pitch tar walkway roof           | 400 Sq. Ft.               |
| 36            | Built-Up Roofing                         | 36-RF8-116           | Pharmacy                 | None Detected - Pitch tar walkway roof           | 400 Sq. Ft.               |
| 01            | Rubber Floor Mastic                      | 01-MG5-01            | Kitchen                  | None Detected - Mastic                           | 1000 Sq. Ft.              |
| 01            | Rubber Floor Mastic                      | 01-MG5-02            | Kitchen                  | None Detected - Mastic                           | 1000 Sq. Ft.              |
| 01            | Rubber Floor Mastic                      | 01-MG5-03            | Kitchen                  | None Detected - Mastic                           | 1000 Sq. Ft.              |
| 02            | FRP Paneling                             | 02-MG5-04            | Kitchen                  | None Detected - Paneling                         | 5000 Sq. Ft.              |
| 02            | FRP Paneling                             | 02-MG5-04            | Kitchen                  | None Detected - Mastic                           | 5000 Sq. Ft.              |
| 02            | FRP Paneling                             | 02-MG5-05            | Kitchen                  | None Detected - Paneling                         | 5000 Sq. Ft.              |
| 02            | FRP Paneling                             | 02-MG5-05            | Kitchen                  | None Detected - Mastic                           | 5000 Sq. Ft.              |
| 02            | FRP Paneling                             | 02-MG5-06            | Kitchen                  | None Detected - Paneling                         | 5000 Sq. Ft.              |
| 02            | FRP Paneling                             | 02-MG5-06            | Kitchen                  | None Detected - Mastic                           | 5000 Sq. Ft.              |
| 03            | 2'x4' Worm/Pinhole Ceiling Tile          | 03-CT4-07            | Kitchen                  | None Detected - 2'x4' Ceiling Tile               | 1000 Sq. Ft.              |
| 03            | 2'x4' Worm/Pinhole Ceiling Tile          | 03-CT4-08            | Kitchen                  | None Detected - 2'x4' Ceiling Tile               | 1000 Sq. Ft.              |
| 03            | 2'x4' Worm/Pinhole Ceiling Tile          | 03-CT4-09            | Kitchen                  | None Detected - 2'x4' Ceiling Tile               | 1000 Sq. Ft.              |
| 04            | Sink Undercoating                        | 04-SC6-10            | Kitchen                  | None Detected - Sink                             | 1 unit                    |
| 04            | Sink Undercoating                        | 04-SC6-11            | Kitchen                  | None Detected - Sink                             | 1 unit                    |
| 04            | Sink Undercoating                        | 04-SC6-12            | Kitchen                  | None Detected - Sink                             | 1 unit                    |
| 05            | 12"x12" Grey Floor Tile with Yellow Glue | 05-FT5-13            | Kitchen                  | None Detected - Floor Tile                       | 200 Sq. Ft.               |

| <b>HA No.</b> | <b>Material Description</b>              | <b>Sample Number</b> | <b>Material Location</b> | <b>Lab Results</b>             | <b>Estimated Quantity</b> |
|---------------|--|----------------------|--------------------------|--------------------------------|---------------------------|
| 05            | 12"x12" Grey Floor Tile with Yellow Glue | 05-FT15-14           | Kitchen                  | None Detected – Floor<br>Tile  | 200 Sq. Ft.               |
| 05            | 12"x12" Grey Floor Tile with Yellow Glue | 05-FT15-14           | Kitchen                  | None Detected – Mastic         | 200 Sq. Ft.               |
| 05            | 12"x12" Grey Floor Tile with Yellow Glue | 05-FT15-15           | Kitchen                  | None Detected – Floor<br>Tile  | 200 Sq. Ft.               |
| 05            | 12"x12" Grey Floor Tile with Yellow Glue | 05-FT15-15           | Kitchen                  | None Detected – Mastic         | 200 Sq. Ft.               |
| 06            | Laminate Countertops with Glue           | 06-SG1-16            | Kitchen                  | None Detected –<br>Countertops | 10 Sq. Ft.                |
| 06            | Laminate Countertops with Glue           | 06-SG1-17            | Kitchen                  | None Detected –<br>Countertops | 10 Sq. Ft.                |
| 06            | Laminate Countertops with Glue           | 06-SCG1-18           | Kitchen                  | None Detected –<br>Countertops | 10 Sq. Ft.                |

**APPENDIX B**

**XRF INSTRUMENT DATA**

| Reading | Time             | Type        | Duration | Units      | Sequence | Component            | Substrate | Side | Condition | Color | Room                | Results  | Depth Index | Action Level | PbC   |
|---------|------------------|-------------|----------|------------|----------|----------------------|-----------|------|-----------|-------|---------------------|----------|-------------|--------------|-------|
| 1       | 11/30/2015 14:42 | SHUTTER_CAL | 425.04   | cps        | Final    | Detector Calibration |           |      |           |       |                     | Positive | 1.07        | 1            | 1.1   |
| 2       | 11/30/2015 14:43 | PAINT       | 7.47     | mg / cm ^2 | Final    | Calibration          |           |      |           |       |                     | Positive | 1.14        | 1            | 1.1   |
| 3       | 11/30/2015 14:45 | PAINT       | 8.34     | mg / cm ^2 | Final    | Calibration          |           |      |           |       |                     | Positive | 1.14        | 1            | 1.2   |
| 4       | 11/30/2015 14:45 | PAINT       | 3.36     | mg / cm ^2 | Final    | Calibration          |           |      |           |       |                     | Positive | 1.21        | 1            | 1.2   |
| 5       | 11/30/2015 14:46 | PAINT       | 3.14     | mg / cm ^2 | Final    | Calibration          |           |      |           |       |                     | Positive | 1.16        | 1            | 1.2   |
| 6       | 11/30/2015 14:47 | PAINT       | 5.13     | mg / cm ^2 | Final    | Calibration          |           |      |           |       |                     | Positive | 1.15        | 1            | 1.2   |
| 7       | 11/30/2015 14:48 | PAINT       | 3.42     | mg / cm ^2 | Final    | Calibration          |           |      |           |       |                     | Positive | 1.09        | 1            | 1.1   |
| 8       | 11/30/2015 14:49 | PAINT       | 7.9      | mg / cm ^2 | Final    | Calibration          |           |      |           |       |                     | Negative | 1           | 1            | < LOD |
| 9       | 11/30/2015 14:54 | PAINT       | 1.14     | mg / cm ^2 | Final    | Calibration          |           |      |           |       |                     | Negative | 1           | 1            | < LOD |
| 10      | 11/30/2015 14:54 | PAINT       | 1.43     | mg / cm ^2 | Final    | Calibration          |           |      |           |       |                     | Negative | 1           | 1            | < LOD |
| 11      | 11/30/2015 14:55 | PAINT       | 1.15     | mg / cm ^2 | Final    | Calibration          |           |      |           |       |                     | Negative | 1           | 1            | < LOD |
| 12      | 11/30/2015 14:56 | PAINT       | 1.57     | mg / cm ^2 | Final    | Calibration          |           |      |           |       |                     | Null     | 5.63        | 1            | < LOD |
| 13      | 11/30/2015 14:56 | PAINT       | 1.29     | mg / cm ^2 | Final    | Door Frame           | Wall      | A    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 14      | 11/30/2015 14:56 | PAINT       | 1        | mg / cm ^2 | Final    | Door Frame           | Wall      | B    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 15      | 11/30/2015 14:57 | PAINT       | 1.43     | mg / cm ^2 | Final    | Door Frame           | Door      | C    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 16      | 11/30/2015 14:57 | PAINT       | 1.21     | mg / cm ^2 | Final    | Door Frame           | Door      | D    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 17      | 11/30/2015 14:58 | PAINT       | 1.07     | mg / cm ^2 | Final    | Door Frame           | Door      | E    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 18      | 11/30/2015 14:58 | PAINT       | 1        | mg / cm ^2 | Final    | Door Frame           | Door      | F    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 19      | 11/30/2015 14:58 | PAINT       | 1.07     | mg / cm ^2 | Final    | Door Frame           | Door      | G    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 20      | 11/30/2015 14:59 | PAINT       | 1.5      | mg / cm ^2 | Final    | Door Frame           | Door      | H    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 21      | 11/30/2015 15:00 | PAINT       | 2.22     | mg / cm ^2 | Final    | Door Frame           | Door      | I    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 22      | 11/30/2015 15:00 | PAINT       | 1.28     | mg / cm ^2 | Final    | Door Frame           | Door      | J    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 23      | 11/30/2015 15:00 | PAINT       | 1.65     | mg / cm ^2 | Final    | Door Frame           | Door      | K    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 24      | 11/30/2015 15:01 | PAINT       | 1        | mg / cm ^2 | Final    | Door Frame           | Door      | L    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 25      | 11/30/2015 15:03 | PAINT       | 2.22     | mg / cm ^2 | Final    | Door Frame           | Door      | M    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 26      | 11/30/2015 15:03 | PAINT       | 1.07     | mg / cm ^2 | Final    | Door Frame           | Door      | N    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 27      | 11/30/2015 15:04 | PAINT       | 1.79     | mg / cm ^2 | Final    | Door Frame           | Door      | O    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 28      | 11/30/2015 15:04 | PAINT       | 1.37     | mg / cm ^2 | Final    | Door Frame           | Door      | P    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 29      | 11/30/2015 15:05 | PAINT       | 1        | mg / cm ^2 | Final    | Door Frame           | Door      | Q    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 30      | 11/30/2015 15:05 | PAINT       | 2.3      | mg / cm ^2 | Final    | Door Frame           | Door      | R    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 31      | 11/30/2015 15:06 | PAINT       | 1.15     | mg / cm ^2 | Final    | Door Frame           | Door      | S    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 32      | 11/30/2015 15:06 | PAINT       | 1.72     | mg / cm ^2 | Final    | Door Frame           | Door      | T    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 33      | 11/30/2015 15:07 | PAINT       | 1.15     | mg / cm ^2 | Final    | Door Frame           | Door      | U    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 34      | 11/30/2015 15:07 | PAINT       | 1        | mg / cm ^2 | Final    | Door Frame           | Door      | V    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 35      | 11/30/2015 15:07 | PAINT       | 0.22     | mg / cm ^2 | Final    | Door Frame           | Door      | W    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 36      | 11/30/2015 15:09 | PAINT       | 0.5      | mg / cm ^2 | Final    | Door Frame           | Door      | X    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 37      | 11/30/2015 15:09 | PAINT       | 0.21     | mg / cm ^2 | Final    | Door Frame           | Door      | Y    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 38      | 11/30/2015 15:09 | PAINT       | 1        | mg / cm ^2 | Final    | Door Frame           | Door      | Z    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 39      | 11/30/2015 15:10 | PAINT       | 2.44     | mg / cm ^2 | Final    | Door Frame           | Door      | A    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 40      | 11/30/2015 15:10 | PAINT       | 1.22     | mg / cm ^2 | Final    | Door Frame           | Door      | B    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 41      | 11/30/2015 15:11 | PAINT       | 1.36     | mg / cm ^2 | Final    | Door Frame           | Door      | C    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 42      | 11/30/2015 15:11 | PAINT       | 1.72     | mg / cm ^2 | Final    | Door Frame           | Door      | D    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 43      | 11/30/2015 15:11 | PAINT       | 1        | mg / cm ^2 | Final    | Door Frame           | Door      | E    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 44      | 11/30/2015 15:12 | PAINT       | 0.86     | mg / cm ^2 | Final    | Door Frame           | Door      | F    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 45      | 11/30/2015 15:12 | PAINT       | 2.44     | mg / cm ^2 | Final    | Door Frame           | Door      | G    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 46      | 11/30/2015 15:13 | PAINT       | 1.15     | mg / cm ^2 | Final    | Door Frame           | Door      | H    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 47      | 11/30/2015 15:13 | PAINT       | 2.01     | mg / cm ^2 | Final    | Door Frame           | Door      | I    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 48      | 11/30/2015 15:14 | PAINT       | 1.08     | mg / cm ^2 | Final    | Door Frame           | Door      | J    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |
| 49      | 11/30/2015 15:14 | PAINT       | 0.43     | mg / cm ^2 | Final    | Door Frame           | Door      | K    | Good      | Cream | West Corner Hallway | Negative | 1           | 1            | < LOD |

| Reading | Time             | Type  | Duration | Units      | Sequence | Component  | Substrate | Side | Condition | Color | Room                     | Results  | Depth Index | Action | PbC   |
|---------|------------------|-------|----------|------------|----------|------------|-----------|------|-----------|-------|--------------------------|----------|-------------|--------|-------|
| 50      | 11/30/2015 15:14 | PAINT | 1.44     | mg / cm ^2 | Final    | Door Frame | Steel     | C    | Good      | Cream | Room 1010 Entrance       | Negative | 1           | 1      | < LOD |
| 51      | 11/30/2015 15:15 | PAINT | 1        | mg / cm ^2 | Final    | Wall       | Gypsum    | A    | Good      | Cream | Room 1033                | Negative | 1           | 1      | < LOD |
| 52      | 11/30/2015 15:16 | PAINT | 2.66     | mg / cm ^2 | Final    | Wall       | Gypsum    | B    | Good      | Cream | Room 1033                | Negative | 1           | 1      | < LOD |
| 53      | 11/30/2015 15:16 | PAINT | 1.87     | mg / cm ^2 | Final    | Wall       | Gypsum    | C    | Good      | Cream | Room 1033                | Negative | 1           | 1      | < LOD |
| 54      | 11/30/2015 15:17 | PAINT | 1.58     | mg / cm ^2 | Final    | Wall       | Gypsum    | D    | Good      | Cream | Room 1033                | Negative | 1           | 1      | < LOD |
| 55      | 11/30/2015 15:17 | PAINT | 1.07     | mg / cm ^2 | Final    | Wall       | Gypsum    | A    | Good      | Green | Room 1011                | Negative | 1           | 1      | < LOD |
| 56      | 11/30/2015 15:18 | PAINT | 1.07     | mg / cm ^2 | Final    | Wall       | Gypsum    | B    | Good      | Cream | Room 1011                | Negative | 1           | 1      | < LOD |
| 57      | 11/30/2015 15:18 | PAINT | 1.79     | mg / cm ^2 | Final    | Wall       | Gypsum    | D    | Good      | Cream | Room 1011                | Negative | 1           | 1      | < LOD |
| 58      | 11/30/2015 15:19 | PAINT | 2.01     | mg / cm ^2 | Final    | Door Frame | Steel     | B    | Good      | Cream | Room 1011 Entrance       | Negative | 1           | 1      | < LOD |
| 59      | 11/30/2015 15:20 | PAINT | 1.01     | mg / cm ^2 | Final    | Wall       | Gypsum    | A    | Good      | Cream | Room 1034                | Negative | 1           | 1      | < LOD |
| 60      | 11/30/2015 15:20 | PAINT | 2        | mg / cm ^2 | Final    | Wall       | Gypsum    | B    | Good      | Cream | Room 1034                | Negative | 1           | 1      | < LOD |
| 61      | 11/30/2015 15:21 | PAINT | 1.57     | mg / cm ^2 | Final    | Wall       | Gypsum    | C    | Good      | Cream | Room 1034                | Negative | 1           | 1      | < LOD |
| 62      | 11/30/2015 15:21 | PAINT | 3.94     | mg / cm ^2 | Final    | Wall       | Gypsum    | D    | Good      | Cream | Room 1034                | Negative | 1           | 1      | < LOD |
| 63      | 11/30/2015 15:22 | PAINT | 1.22     | mg / cm ^2 | Final    | Wall       | Gypsum    | N/A  | Good      | Cream | Room 1034 Ceiling Header | Negative | 1           | 1      | < LOD |
| 64      | 11/30/2015 15:23 | PAINT | 3.07     | mg / cm ^2 | Final    | Wall       | Gypsum    | A    | Good      | Cream | Room 1034                | Negative | 2.92        | 1      | < LOD |
| 65      | 11/30/2015 15:24 | PAINT | 1.36     | mg / cm ^2 | Final    | Wall       | Gypsum    | B    | Good      | Cream | Room 1034                | Negative | 1.03        | 1      | < LOD |
| 66      | 11/30/2015 15:24 | PAINT | 1.44     | mg / cm ^2 | Final    | Wall       | Gypsum    | A    | Good      | Cream | Room 1012                | Negative | 1           | 1      | < LOD |
| 67      | 11/30/2015 15:25 | PAINT | 1.79     | mg / cm ^2 | Final    | Wall       | Gypsum    | B    | Good      | Cream | Room 1012                | Negative | 1           | 1      | < LOD |
| 68      | 11/30/2015 15:25 | PAINT | 1.08     | mg / cm ^2 | Final    | Wall       | Gypsum    | C    | Good      | Cream | Room 1012                | Negative | 1           | 1      | < LOD |
| 69      | 11/30/2015 15:26 | PAINT | 1.07     | mg / cm ^2 | Final    | Wall       | Gypsum    | D    | Good      | Cream | Room 1012                | Negative | 1           | 1      | < LOD |
| 70      | 11/30/2015 15:26 | PAINT | 1        | mg / cm ^2 | Final    | Door Frame | Steel     | A    | Good      | Cream | Room 1012 Entrance       | Negative | 1           | 1      | < LOD |
| 71      | 11/30/2015 15:27 | PAINT | 1.15     | mg / cm ^2 | Final    | Door Frame | Steel     | A    | Good      | Cream | Room 1014 Entrance       | Negative | 1           | 1      | < LOD |
| 72      | 11/30/2015 15:27 | PAINT | 1.36     | mg / cm ^2 | Final    | Wall       | Gypsum    | A    | Good      | Cream | Room 1014                | Negative | 1           | 1      | < LOD |
| 73      | 11/30/2015 15:27 | PAINT | 2.08     | mg / cm ^2 | Final    | Wall       | Gypsum    | B    | Good      | Cream | Room 1014                | Negative | 4.57        | 1      | < LOD |
| 74      | 11/30/2015 15:28 | PAINT | 1.72     | mg / cm ^2 | Final    | Wall       | Gypsum    | C    | Good      | Cream | Room 1014                | Negative | 1           | 1      | < LOD |
| 75      | 11/30/2015 15:28 | PAINT | 1.36     | mg / cm ^2 | Final    | Wall       | Gypsum    | D    | Good      | Brown | Room 1014                | Null     | 1           | 1      | < LOD |
| 76      | 11/30/2015 15:28 | PAINT | 1.08     | mg / cm ^2 | Final    | Wall       | Gypsum    | D    | Good      | Brown | Room 1014                | Negative | 1           | 1      | < LOD |
| 77      | 11/30/2015 15:29 | PAINT | 1.07     | mg / cm ^2 | Final    | Wall       | Gypsum    | A    | Good      | Cream | Room 1015                | Null     | 1           | 1      | < LOD |
| 78      | 11/30/2015 15:29 | PAINT | 2.08     | mg / cm ^2 | Final    | Wall       | Gypsum    | B    | Good      | Cream | Room 1015                | Null     | 10          | 1      | < LOD |
| 79      | 11/30/2015 15:30 | PAINT | 1.22     | mg / cm ^2 | Final    | Wall       | Gypsum    | C    | Good      | Cream | Room 1015                | Null     | 1           | 1      | < LOD |
| 80      | 11/30/2015 15:30 | PAINT | 1        | mg / cm ^2 | Final    | Wall       | Gypsum    | D    | Good      | Blue  | North Hallway            | Null     | 1           | 1      | < LOD |
| 81      | 11/30/2015 15:31 | PAINT | 2.87     | mg / cm ^2 | Final    | Wall       | Gypsum    | C    | Good      | Blue  | North Hallway            | Null     | 1           | 1      | < LOD |
| 82      | 11/30/2015 15:32 | PAINT | 0.57     | mg / cm ^2 | Final    | Wall       | Gypsum    | D    | Good      | Blue  | North Hallway            | Null     | 1           | 1      | < LOD |
| 83      | 11/30/2015 15:32 | PAINT | 0.64     | mg / cm ^2 | Final    | Wall       | Gypsum    | D    | Good      | Blue  | North Hallway            | Negative | 1           | 1      | < LOD |
| 84      | 11/30/2015 15:32 | PAINT | 0.43     | mg / cm ^2 | Final    | Wall       | Gypsum    | B    | Good      | Blue  | North Hallway            | Negative | 3.57        | 1      | < LOD |
| 85      | 11/30/2015 15:33 | PAINT | 0.65     | mg / cm ^2 | Final    | Wall       | Gypsum    | B    | Good      | Blue  | North Hallway            | Negative | 1           | 1      | < LOD |
| 86      | 11/30/2015 15:33 | PAINT | 1.44     | mg / cm ^2 | Final    | Wall       | Gypsum    | B    | Good      | Blue  | North Hallway            | Negative | 4.21        | 1      | < LOD |
| 87      | 11/30/2015 15:34 | PAINT | 2.51     | mg / cm ^2 | Final    | Wall       | Gypsum    | B    | Good      | Blue  | North Hallway            | Null     | 1           | 1      | < LOD |
| 88      | 11/30/2015 15:34 | PAINT | 1.22     | mg / cm ^2 | Final    | Wall       | Gypsum    | C    | Good      | Blue  | North Hallway            | Negative | 1           | 1      | < LOD |
| 89      | 11/30/2015 15:34 | PAINT | 1.14     | mg / cm ^2 | Final    | Wall       | Gypsum    | D    | Good      | Blue  | North Hallway            | Negative | 1           | 1      | < LOD |
| 90      | 11/30/2015 15:35 | PAINT | 2.44     | mg / cm ^2 | Final    | Wall       | Gypsum    | A    | Good      | Cream | Room 1020                | Negative | 1           | 1      | < LOD |
| 91      | 11/30/2015 15:36 | PAINT | 1.57     | mg / cm ^2 | Final    | Wall       | Gypsum    | B    | Good      | Brown | Room 1020                | Null     | 1           | 1      | < LOD |
| 92      | 11/30/2015 15:37 | PAINT | 1.43     | mg / cm ^2 | Final    | Wall       | Gypsum    | B    | Good      | Brown | Room 1020                | Negative | 1           | 1      | < LOD |
| 93      | 11/30/2015 15:38 | PAINT | 1.15     | mg / cm ^2 | Final    | Wall       | Gypsum    | C    | Good      | Cream | Room 1020                | Negative | 1           | 1      | < LOD |
| 94      | 11/30/2015 15:38 | PAINT | 1.49     | mg / cm ^2 | Final    | Wall       | Gypsum    | D    | Good      | Cream | Room 1020                | Negative | 1           | 1      | < LOD |
| 95      | 11/30/2015 15:39 | PAINT | 1.07     | mg / cm ^2 | Final    | Wall       | Gypsum    | A    | Good      | Cream | Room 1038                | Negative | 2.02        | 1      | < LOD |
| 96      | 11/30/2015 15:39 | PAINT | 2.29     | mg / cm ^2 | Final    | Wall       | Gypsum    | B    | Good      | Cream | Room 1038                | Negative | 1           | 1      | < LOD |
| 97      | 11/30/2015 15:40 | PAINT | 1.22     | mg / cm ^2 | Final    | Wall       | Gypsum    | C    | Good      | Cream | Room 1038                | Negative | 1           | 1      | < LOD |
| 98      | 11/30/2015 15:40 | PAINT | 1.29     | mg / cm ^2 | Final    | Wall       | Gypsum    | D    | Good      | Brown | Room 1038                | Negative | 1           | 1      | < LOD |

| Reading | Time             | Type        | Duration | Units      | Sequence | Component            | Substrate | Side | Condition | Color | Room                            | Results  | Depth Index | Action Level | PC       |
|---------|------------------|-------------|----------|------------|----------|----------------------|-----------|------|-----------|-------|---------------------------------|----------|-------------|--------------|----------|
| 99      | 11/30/2015 15:41 | PAINT       | 1.15     | mg / cm ^2 | Final    | Wall                 | Gypsum    | A    | Good      | Cream | Dirty Instruments Room          | Negative | 1           | 1            | < LOD    |
| 100     | 11/30/2015 15:41 | PAINT       | 1.28     | mg / cm ^2 | Final    | Wall                 | Gypsum    | B    | Good      | Cream | Dirty Instruments Room          | Negative | 2.8         | 1            | < LOD    |
| 101     | 11/30/2015 15:41 | PAINT       | 1.29     | mg / cm ^2 | Final    | Wall                 | Gypsum    | C    | Good      | Cream | Dirty Instruments Room          | Negative | 1           | 1            | < LOD    |
| 102     | 11/30/2015 15:42 | PAINT       | 0.93     | mg / cm ^2 | Final    | Wall                 | Gypsum    | D    | Good      | Cream | Dirty Instruments Room          | Null     | 1           | 1            | < LOD    |
| 103     | 11/30/2015 15:42 | PAINT       | 1.57     | mg / cm ^2 | Final    | Wall                 | Gypsum    | D    | Good      | Cream | Dirty Instruments Room          | Negative | 1           | 1            | < LOD    |
| 104     | 11/30/2015 15:43 | PAINT       | 1.29     | mg / cm ^2 | Final    | Door Frame           | Steel     | D    | Good      | Cream | Dirty Instruments Room Entrance | Negative | 1           | 1            | < LOD    |
| 105     | 11/30/2015 15:43 | PAINT       | 1.22     | mg / cm ^2 | Final    | Wall                 | Gypsum    | A    | Good      | Cream | Room 1022                       | Negative | 1           | 1            | < LOD    |
| 106     | 11/30/2015 15:44 | PAINT       | 1.15     | mg / cm ^2 | Final    | Wall                 | Gypsum    | B    | Good      | Cream | Room 1022                       | Negative | 1           | 1            | < LOD    |
| 107     | 11/30/2015 15:44 | PAINT       | 1.29     | mg / cm ^2 | Final    | Wall                 | Gypsum    | C    | Good      | Cream | Room 1022                       | Negative | 1           | 1            | < LOD    |
| 108     | 11/30/2015 15:44 | PAINT       | 1.14     | mg / cm ^2 | Final    | Wall                 | Gypsum    | D    | Good      | Cream | Room 1022                       | Negative | 1           | 1            | < LOD    |
| 109     | 11/30/2015 15:45 | PAINT       | 1.36     | mg / cm ^2 | Final    | Wall                 | Gypsum    | A    | Good      | Cream | Room 1024                       | Negative | 1           | 1            | < LOD    |
| 110     | 11/30/2015 15:46 | PAINT       | 1.86     | mg / cm ^2 | Final    | Wall                 | Gypsum    | B    | Good      | Brown | Room 1024                       | Negative | 1           | 1            | < LOD    |
| 111     | 11/30/2015 15:46 | PAINT       | 1.79     | mg / cm ^2 | Final    | Wall                 | Gypsum    | C    | Good      | Cream | Room 1024                       | Negative | 1           | 1            | < LOD    |
| 112     | 11/30/2015 15:47 | PAINT       | 1.29     | mg / cm ^2 | Final    | Wall                 | Gypsum    | D    | Good      | Cream | Room 1024                       | Negative | 1           | 1            | < LOD    |
| 113     | 11/30/2015 15:47 | PAINT       | 1.14     | mg / cm ^2 | Final    | Wall                 | Gypsum    | A    | Good      | Brown | East Hallway                    | Negative | 1           | 1            | < LOD    |
| 114     | 11/30/2015 15:48 | PAINT       | 0.36     | mg / cm ^2 | Final    | Wall                 | Gypsum    | C    | Good      | Blue  | Room 1024                       | Negative | 1.8         | 1            | < LOD    |
| 115     | 11/30/2015 15:49 | PAINT       | 1.51     | mg / cm ^2 | Final    | Wall                 | Gypsum    | C    | Good      | Blue  | East Hallway                    | Negative | 1           | 1            | < LOD    |
| 116     | 11/30/2015 15:49 | PAINT       | 1.29     | mg / cm ^2 | Final    | Wall                 | Gypsum    | D    | Good      | Cream | East Hallway                    | Negative | 1           | 1            | < LOD    |
| 117     | 11/30/2015 15:50 | PAINT       | 1.07     | mg / cm ^2 | Final    | Door Frame           | Steel     | D    | Good      | Cream | East Hallway Entrance           | Negative | 1           | 1            | < LOD    |
| 118     | 11/30/2015 15:50 | PAINT       | 1.44     | mg / cm ^2 | Final    | Wall                 | Gypsum    | A    | Good      | Brown | Room 1040                       | Negative | 1           | 1            | < LOD    |
| 119     | 11/30/2015 15:51 | PAINT       | 1.42     | mg / cm ^2 | Final    | Wall                 | Gypsum    | B    | Good      | Brown | Room 1040                       | Negative | 1.27        | 1            | < LOD    |
| 120     | 11/30/2015 15:51 | PAINT       | 1.36     | mg / cm ^2 | Final    | Wall                 | Gypsum    | C    | Good      | Brown | Room 1040                       | Negative | 1           | 1            | < LOD    |
| 121     | 11/30/2015 15:52 | PAINT       | 0.72     | mg / cm ^2 | Final    | Wall                 | Gypsum    | D    | Good      | Brown | Room 1040                       | Negative | 1           | 1            | < LOD    |
| 122     | 11/30/2015 15:52 | PAINT       | 0.5      | mg / cm ^2 | Final    | Wall                 | Gypsum    | D    | Good      | Brown | Room 1040                       | Negative | 1           | 1            | < LOD    |
| 123     | 11/30/2015 15:52 | PAINT       | 1.36     | mg / cm ^2 | Final    | Wall                 | Gypsum    | D    | Good      | Brown | Room 1040                       | Negative | 1           | 1            | < LOD    |
| 124     | 11/30/2015 15:53 | PAINT       | 1.57     | mg / cm ^2 | Final    | Wall                 | Gypsum    | D    | Good      | Brown | Room 1040                       | Negative | 1.84        | 1            | < LOD    |
| 125     | 11/30/2015 15:53 | PAINT       | 1.44     | mg / cm ^2 | Final    | Wall                 | Gypsum    | A    | Good      | Cream | Room 1032                       | Negative | 1           | 1            | < LOD    |
| 126     | 11/30/2015 15:54 | PAINT       | 1.43     | mg / cm ^2 | Final    | Wall                 | Gypsum    | B    | Good      | Cream | Room 1032                       | Negative | 1           | 1            | < LOD    |
| 127     | 11/30/2015 15:54 | PAINT       | 1.08     | mg / cm ^2 | Final    | Wall                 | Gypsum    | C    | Good      | Brown | Room 1032                       | Negative | 1           | 1            | < LOD    |
| 128     | 11/30/2015 15:54 | PAINT       | 1.08     | mg / cm ^2 | Final    | Wall                 | Gypsum    | D    | Good      | Cream | Room 1032                       | Negative | 1           | 1            | < LOD    |
| 129     | 11/30/2015 15:56 | PAINT       | 7.82     | mg / cm ^2 | Final    | Calibration          |           |      |           |       | Positive                        | 1.08     | 1           | 1.1          | Positive |
| 130     | 11/30/2015 15:57 | PAINT       | 3.13     | mg / cm ^2 | Final    | Calibration          |           |      |           |       | Positive                        | 1.16     | 1           | 1.2          | Positive |
| 131     | 11/30/2015 15:58 | PAINT       | 7.75     | mg / cm ^2 | Final    | Calibration          |           |      |           |       | Null                            | 1.12     | 1           | 1.1          | Null     |
| 132     | 11/30/2015 15:59 | PAINT       | 0.21     | mg / cm ^2 | Final    | Calibration          |           |      |           |       | Null                            | 1.16     | 1           | 1.2          | < LOD    |
| 133     | 11/30/2015 15:59 | PAINT       | 3.2      | mg / cm ^2 | Final    | Calibration          |           |      |           |       | Positive                        | 1.14     | 1           | 1.2          | Positive |
| 134     | 11/30/2015 16:01 | PAINT       | 8.47     | mg / cm ^2 | Final    | Calibration          |           |      |           |       | Positive                        | 1.17     | 1           | 1.1          | Positive |
| 135     | 11/30/2015 16:02 | PAINT       | 6.12     | mg / cm ^2 | Final    | Calibration          |           |      |           |       | Negative                        | 1.06     | 1           | 0.9          | Negative |
| 136     | 12/2/2015 9:57   | SHUTTER_CAL | 417.26   | cps        | Final    | Detector Calibration |           |      |           |       | Positive                        | 1.08     | 1           | 1.1          | Positive |
| 137     | 12/2/2015 10:01  | PAINT       | 7.24     | mg / cm ^2 | Final    | Calibration          |           |      |           |       | Negative                        | 1.14     | 1           | 0.7          | Negative |
| 138     | 12/2/2015 10:01  | PAINT       | 1.64     | mg / cm ^2 | Final    | Calibration          |           |      |           |       | Positive                        | 1.08     | 1           | 1.1          | Positive |
| 139     | 12/2/2015 10:03  | PAINT       | 10.99    | mg / cm ^2 | Final    | Calibration          |           |      |           |       | Positive                        | 1.17     | 1           | 1.2          | Positive |
| 140     | 12/2/2015 10:04  | PAINT       | 3.13     | mg / cm ^2 | Final    | Calibration          |           |      |           |       | Positive                        | 1.18     | 1           | 1.2          | Positive |
| 141     | 12/2/2015 10:05  | PAINT       | 3.13     | mg / cm ^2 | Final    | Calibration          |           |      |           |       | Positive                        | 1.12     | 1           | 1.1          | Positive |
| 142     | 12/2/2015 10:06  | PAINT       | 7.66     | mg / cm ^2 | Final    | Calibration          |           |      |           |       | Positive                        | 1.08     | 1           | 1.1          | Positive |
| 143     | 12/2/2015 10:20  | SHUTTER_CAL | 416.97   | cps        | Final    | Calibration          |           |      |           |       | Negative                        | 1.14     | 1           | 0.7          | Negative |
| 144     | 12/2/2015 10:20  | PAINT       | 1.79     | mg / cm ^2 | Final    | Wall                 | Gypsum    | A    | Good      | Cream | South Hallway                   | Negative | 1           | 1            | < LOD    |
| 145     | 12/2/2015 10:21  | PAINT       | 2.36     | mg / cm ^2 | Final    | Wall                 | Gypsum    | B    | Good      | Cream | South Hallway                   | Negative | 1           | 1            | < LOD    |
| 146     | 12/2/2015 10:21  | PAINT       | 1.64     | mg / cm ^2 | Final    | Wall                 | Gypsum    | D    | Good      | Cream | South Hallway                   | Negative | 1           | 1            | < LOD    |
| 147     | 12/2/2015 10:22  | PAINT       | 1.29     | mg / cm ^2 | Final    | Wall                 | Gypsum    | A    | Good      | Green | Room 1003                       | Negative | 1           | 1            | < LOD    |

| Reading | Time            | Type        | Duration | Units      | Sequence | Component            | Substrate            | Side                 | Condition            | Color                | Room                               | Results  | Depth Index | Action Level | PbC   |
|---------|-----------------|-------------|----------|------------|----------|----------------------|----------------------|----------------------|----------------------|----------------------|------------------------------------|----------|-------------|--------------|-------|
| 148     | 12/2/2015 10:22 | PAINT       | 1.21     | mg / cm ^2 | Final    | Wall                 | Gypsum               | B                    | Good                 | Cream                | Room 1003                          | Negative | 1           | 1            | < LOD |
| 149     | 12/2/2015 10:23 | PAINT       | 1.35     | mg / cm ^2 | Final    | Wall                 | Gypsum               | C                    | Good                 | Cream                | Room 1003                          | Negative | 1           | 1            | < LOD |
| 150     | 12/2/2015 10:23 | PAINT       | 1.78     | mg / cm ^2 | Final    | Wall                 | Gypsum               | D                    | Good                 | Cream                | Room 1003                          | Negative | 1           | 1            | < LOD |
| 151     | 12/2/2015 10:24 | PAINT       | 1        | mg / cm ^2 | Final    | Door Frame           | Steel                | B                    | Good                 | Cream                | Room 1003 Entrance                 | Negative | 1           | 1            | < LOD |
| 152     | 12/2/2015 10:24 | PAINT       | 2.07     | mg / cm ^2 | Final    | Wall                 | Gypsum               | A                    | Good                 | Cream                | Waiting Room                       | Negative | 1           | 1            | < LOD |
| 153     | 12/2/2015 10:25 | PAINT       | 2.5      | mg / cm ^2 | Final    | Wall                 | Gypsum               | B                    | Good                 | Cream                | Waiting Room                       | Negative | 1           | 1            | < LOD |
| 154     | 12/2/2015 10:25 | PAINT       | 1.22     | mg / cm ^2 | Final    | Wall                 | Gypsum               | C                    | Good                 | Green                | Waiting Room                       | Negative | 1           | 1            | < LOD |
| 155     | 12/2/2015 10:26 | PAINT       | 1.78     | mg / cm ^2 | Final    | Wall                 | Gypsum               | D                    | Good                 | Cream                | Waiting Room                       | Null     | 1           | 1            | < LOD |
| 156     | 12/2/2015 10:26 | PAINT       | 1.57     | mg / cm ^2 | Final    | Wall                 | Gypsum               | D                    | Good                 | Cream                | Waiting Room                       | Negative | 1           | 1            | < LOD |
| 157     | 12/2/2015 10:27 | PAINT       | 1.15     | mg / cm ^2 | Final    | Wall                 | Gypsum               | A                    | Good                 | Cream                | Ladies' Restroom                   | Negative | 1           | 1            | < LOD |
| 158     | 12/2/2015 10:27 | PAINT       | 1.28     | mg / cm ^2 | Final    | Wall                 | Gypsum               | B                    | Good                 | Cream                | Ladies' Restroom                   | Negative | 1           | 1            | < LOD |
| 159     | 12/2/2015 10:27 | PAINT       | 1.29     | mg / cm ^2 | Final    | Wall                 | Gypsum               | C                    | Good                 | Cream                | Ladies' Restroom                   | Negative | 1           | 1            | < LOD |
| 160     | 12/2/2015 10:28 | PAINT       | 1.43     | mg / cm ^2 | Final    | Wall                 | Gypsum               | D                    | Good                 | Cream                | Ladies' Restroom                   | Negative | 1           | 1            | < LOD |
| 161     | 12/2/2015 10:28 | PAINT       | 1.07     | mg / cm ^2 | Final    | Door Frame           | Steel                | B                    | Good                 | Cream                | Ladies' Restroom Entrance          | Negative | 1           | 1            | < LOD |
| 162     | 12/2/2015 10:28 | PAINT       | 1        | mg / cm ^2 | Final    | Door Frame           | Steel                | B                    | Good                 | Cream                | Men's Restroom Entrance            | Null     | 1           | 1            | < LOD |
| 163     | 12/2/2015 10:29 | PAINT       | 1        | mg / cm ^2 | Final    | Door Frame           | Steel                | B                    | Good                 | Cream                | Men's Restroom Entrance            | Negative | 1           | 1            | < LOD |
| 164     | 12/2/2015 10:29 | PAINT       | 1.65     | mg / cm ^2 | Final    | Wall                 | Gypsum               | A                    | Good                 | Cream                | Men's Restroom                     | Negative | 1           | 1            | < LOD |
| 165     | 12/2/2015 10:29 | PAINT       | 1.07     | mg / cm ^2 | Final    | Wall                 | Gypsum               | B                    | Good                 | Cream                | Men's Restroom                     | Negative | 1           | 1            | < LOD |
| 166     | 12/2/2015 10:30 | PAINT       | 1.71     | mg / cm ^2 | Final    | Wall                 | Gypsum               | C                    | Good                 | Cream                | Men's Restroom                     | Negative | 1           | 1            | < LOD |
| 167     | 12/2/2015 10:30 | PAINT       | 1.07     | mg / cm ^2 | Final    | Wall                 | Gypsum               | D                    | Good                 | Cream                | Men's Restroom                     | Negative | 1           | 1            | < LOD |
| 168     | 12/2/2015 10:31 | PAINT       | 1        | mg / cm ^2 | Final    | Walk-Way             | Steel                | A                    | Good                 | Black                | Exterior Walk-Way to Dental Clinic | Negative | 1           | 1            | < LOD |
| 169     | 12/2/2015 10:31 | PAINT       | 0.14     | mg / cm ^2 | Final    | Walk-Way             | Steel                | A                    | Good                 | Black                | Exterior Walk-Way to Dental Clinic | Null     | 10          | 1            | < LOD |
| 170     | 12/2/2015 10:32 | PAINT       | 1.07     | mg / cm ^2 | Final    | Walk-Way             | Steel                | A                    | Good                 | Black                | Exterior Walk-Way to Dental Clinic | Negative | 1           | 1            | < LOD |
| 171     | 12/2/2015 10:32 | PAINT       | 1.07     | mg / cm ^2 | Final    | Walk-Way             | Steel                | B                    | Good                 | Black                | Exterior Walk-Way to Dental Clinic | Negative | 1           | 1            | < LOD |
| 172     | 12/2/2015 10:33 | PAINT       | 1.07     | mg / cm ^2 | Final    | Walk-Way             | Steel                | B                    | Good                 | Black                | Exterior Walk-Way to Dental Clinic | Negative | 1           | 1            | < LOD |
| 173     | 12/2/2015 10:33 | PAINT       | 1.06     | mg / cm ^2 | Final    | Walk-Way             | Steel                | C                    | Good                 | Black                | Exterior Walk-Way to Dental Clinic | Negative | 1           | 1            | < LOD |
| 174     | 12/2/2015 10:33 | PAINT       | 1.07     | mg / cm ^2 | Final    | Walk-Way             | Steel                | C                    | Good                 | Black                | Exterior Walk-Way to Dental Clinic | Negative | 1           | 1            | < LOD |
| 175     | 12/2/2015 10:34 | PAINT       | 1.06     | mg / cm ^2 | Final    | Walk-Way             | Steel                | D                    | Good                 | Black                | Exterior Walk-Way to Dental Clinic | Negative | 1           | 1            | < LOD |
| 176     | 12/2/2015 10:34 | PAINT       | 1.07     | mg / cm ^2 | Final    | Walk-Way             | Steel                | D                    | Good                 | Black                | Exterior Walk-Way to Dental Clinic | Negative | 1           | 1            | < LOD |
| 177     | 12/2/2015 10:35 | PAINT       | 1.07     | mg / cm ^2 | Final    | Stairs               | Steel                | D                    | Good                 | Black                | Exterior Stairs to Dental Clinic   | Negative | 1           | 1            | < LOD |
| 178     | 12/2/2015 10:37 | PAINT       | 1.07     | mg / cm ^2 | Final    | Walk-Way             | Steel                | C                    | Good                 | Black                | Exterior Walk-Way to Dental Clinic | Negative | 1           | 1            | < LOD |
| 179     | 12/2/2015 10:37 | PAINT       | 1.07     | mg / cm ^2 | Final    | Walk-Way             | Steel                | A                    | Good                 | Black                | Exterior Walk-Way to Dental Clinic | Negative | 1           | 1            | < LOD |
| 180     | 12/2/2015 10:38 | PAINT       | 1.07     | mg / cm ^2 | Final    | Walk-Way             | Steel                | A                    | Good                 | Black                | Exterior Walk-Way to Dental Clinic | Negative | 1           | 1            | < LOD |
| 181     | 12/2/2015 10:41 | PAINT       | 4.05     | mg / cm ^2 | Final    | Stairs               | Steel                | A                    | Good                 | Black                | Exterior Stairs to Dental Clinic   | Negative | 1           | 1            | < LOD |
| 182     | 12/2/2015 10:43 | PAINT       | 7.95     | mg / cm ^2 | Final    | I Beam               | Steel                | C                    | Good                 | Black                | Exterior Walk-Way to Dental Clinic | Positive | 1.16        | 1            | 1.2   |
| 183     | 12/2/2015 10:46 | PAINT       | 8.17     | mg / cm ^2 | Final    | Calibration          | Calibration          | Calibration          | Calibration          | Calibration          | Calibration                        | Positive | 1.12        | 1            | 1.1   |
| 184     | 12/2/2015 10:46 | PAINT       | 5.88     | mg / cm ^2 | Final    | Calibration          | Calibration          | Calibration          | Calibration          | Calibration          | Calibration                        | Positive | 1.09        | 1            | 1     |
| 185     | 12/2/2015 10:50 | PAINT       | 3.26     | mg / cm ^2 | Final    | Calibration          | Calibration          | Calibration          | Calibration          | Calibration          | Calibration                        | Positive | 1.32        | 1            | 1.4   |
| 186     | 12/3/2015 9:01  | SHUTTER_CAL | 405.06   | cps        | Final    | Detector Calibration               | Positive | 1.08        | 1            | 1.2   |
| 187     | 12/3/2015 9:49  | PAINT       | 19.8     | mg / cm ^2 | Final    | Calibration          | Calibration          | Calibration          | Calibration          | Calibration          | Calibration                        | Positive | 0.96        | 0.96         | 0.96  |
| 188     | 12/3/2015 9:51  | PAINT       | 1.77     | mg / cm ^2 | Final    | Calibration          | Calibration          | Calibration          | Calibration          | Calibration          | Calibration                        | Null     | 1.09        | 1            | < LOD |
| 189     | 12/3/2015 9:52  | PAINT       | 19.86    | mg / cm ^2 | Final    | Calibration          | Calibration          | Calibration          | Calibration          | Calibration          | Calibration                        | Negative | 1.02        | 1            | 0.9   |
| 190     | 12/3/2015 9:55  | PAINT       | 5.61     | mg / cm ^2 | Final    | Calibration          | Calibration          | Calibration          | Calibration          | Calibration          | Calibration                        | Positive | 1.13        | 1            | 1     |
| 191     | 12/3/2015 9:56  | PAINT       | 0.57     | mg / cm ^2 | Final    | Calibration          | Calibration          | Calibration          | Calibration          | Calibration          | Calibration                        | Null     | 1.09        | 1            | < LOD |
| 192     | 12/3/2015 9:56  | PAINT       | 2.56     | mg / cm ^2 | Final    | Calibration          | Calibration          | Calibration          | Calibration          | Calibration          | Calibration                        | Null     | 1.25        | 1            | 1.3   |
| 193     | 12/3/2015 9:57  | PAINT       | 19.85    | mg / cm ^2 | Final    | Calibration          | Calibration          | Calibration          | Calibration          | Calibration          | Calibration                        | Positive | 1.22        | 1            | 1     |
| 194     | 12/3/2015 10:00 | PAINT       | 3.07     | mg / cm ^2 | Final    | Calibration          | Calibration          | Calibration          | Calibration          | Calibration          | Calibration                        | Positive | 1.1         | 1            | < LOD |
| 195     | 12/3/2015 10:03 | PAINT       | 1.92     | mg / cm ^2 | Final    | Calibration          | Calibration          | Calibration          | Calibration          | Calibration          | Calibration                        | Negative | 1.5         | 1            | < LOD |
| 196     | 12/3/2015 10:04 | PAINT       |          |            |          | Pharmacy             | Pharmacy             | Pharmacy             | Pharmacy             | Pharmacy             | Pharmacy                           | Positive |             |              |       |

| Reading | Time            | Type  | Duration | Units      | Sequence | Component     | Substrate | Side | Condition | Color  | Room                           | Results  | Depth Index | Action Level | PbC   |
|---------|-----------------|-------|----------|------------|----------|---------------|-----------|------|-----------|--------|--------------------------------|----------|-------------|--------------|-------|
| 197     | 12/3/2015 10:05 | PAINT | 3.06     | mg / cm ^2 | Final    | Wall          | Gypsum    | C    | Good      | Cream  | Walkway Corridor to Pharmacy   | Negative | 1           | 1            | < LOD |
| 198     | 12/3/2015 10:06 | PAINT | 3.49     | mg / cm ^2 | Final    | Wall          | Gypsum    | D    | Good      | Cream  | Walkway Corridor to Pharmacy   | Negative | 1.4         | 1            | < LOD |
| 199     | 12/3/2015 10:07 | PAINT | 1.07     | mg / cm ^2 | Final    | Security Post | Steel     | N/A  | Good      | Yellow | Walkway Corridor to Pharmacy   | Negative | 1           | 1            | < LOD |
| 200     | 12/3/2015 10:07 | PAINT | 1.07     | mg / cm ^2 | Final    | Security Post | Steel     | N/A  | Good      | Yellow | Walkway Corridor to Pharmacy   | Negative | 1           | 1            | < LOD |
| 201     | 12/3/2015 10:08 | PAINT | 1.06     | mg / cm ^2 | Final    | Door Frame    | Steel     | B    | Good      | Cream  | Walkway Corridor to Pharmacy   | Negative | 1           | 1            | < LOD |
| 202     | 12/3/2015 10:09 | PAINT | 1.07     | mg / cm ^2 | Final    | Door          | Steel     | B    | Good      | Cream  | Walkway Corridor to Pharmacy   | Negative | 1           | 1            | < LOD |
| 203     | 12/3/2015 10:10 | PAINT | 1.07     | mg / cm ^2 | Final    | Wall          | Gypsum    | A    | Good      | Cream  | Entrance Hallway to Pharmacy   | Negative | 1           | 1            | < LOD |
| 204     | 12/3/2015 10:11 | PAINT | 1.28     | mg / cm ^2 | Final    | Wall          | Gypsum    | D    | Good      | Cream  | Entrance Hallway to Pharmacy   | Negative | 1.73        | 1            | < LOD |
| 205     | 12/3/2015 10:12 | PAINT | 2.86     | mg / cm ^2 | Final    | Wall          | Gypsum    | A    | Good      | Cream  | Room P025                      | Null     | 1           | 1            | < LOD |
| 206     | 12/3/2015 10:13 | PAINT | 1.71     | mg / cm ^2 | Final    | Wall          | Gypsum    | A    | Good      | Cream  | Room P025                      | Negative | 1.28        | 1            | < LOD |
| 207     | 12/3/2015 10:13 | PAINT | 1.79     | mg / cm ^2 | Final    | Wall          | Gypsum    | B    | Good      | Cream  | Room P025                      | Negative | 1           | 1            | < LOD |
| 208     | 12/3/2015 10:15 | PAINT | 2.43     | mg / cm ^2 | Final    | Wall          | Gypsum    | C    | Good      | Cream  | Room P025                      | Negative | 1           | 1            | < LOD |
| 209     | 12/3/2015 10:15 | PAINT | 1.64     | mg / cm ^2 | Final    | Wall          | Gypsum    | D    | Good      | Cream  | Room P025                      | Negative | 1           | 1            | < LOD |
| 210     | 12/3/2015 10:16 | PAINT | 1        | mg / cm ^2 | Final    | Door Frame    | Steel     | B    | Good      | Cream  | Room P025 Entrance             | Negative | 1           | 1            | < LOD |
| 211     | 12/3/2015 10:18 | PAINT | 1.57     | mg / cm ^2 | Final    | Wall          | Gypsum    | A    | Good      | Cream  | North Hallway                  | Negative | 1           | 1            | < LOD |
| 212     | 12/3/2015 10:19 | PAINT | 1.36     | mg / cm ^2 | Final    | Door Frame    | Steel     | B    | Good      | Cream  | North Hallway                  | Negative | 1           | 1            | < LOD |
| 213     | 12/3/2015 10:20 | PAINT | 2.64     | mg / cm ^2 | Final    | Wall          | Gypsum    | C    | Good      | Cream  | North Hallway                  | Negative | 1           | 1            | < LOD |
| 214     | 12/3/2015 10:20 | PAINT | 2.29     | mg / cm ^2 | Final    | Wall          | Gypsum    | D    | Good      | Cream  | Emergency Exit Door North Hall | Negative | 1           | 1            | < LOD |
| 215     | 12/3/2015 10:21 | PAINT | 1.06     | mg / cm ^2 | Final    | Door          | Steel     | C    | Good      | Cream  | Emergency Exit Door North Hall | Negative | 1           | 1            | < LOD |
| 216     | 12/3/2015 10:21 | PAINT | 1        | mg / cm ^2 | Final    | Door Frame    | Steel     | C    | Good      | Cream  | Emergency Exit Door North Hall | Negative | 1           | 1            | < LOD |
| 217     | 12/3/2015 10:36 | PAINT | 1.06     | mg / cm ^2 | Final    | Door Frame    | Steel     | A    | Good      | Cream  | Pharmacy Door Frame            | Negative | 1           | 1            | < LOD |
| 218     | 12/3/2015 10:37 | PAINT | 1.57     | mg / cm ^2 | Final    | Wall          | Gypsum    | A    | Good      | Cream  | East-West Hallway              | Negative | 4.84        | 1            | < LOD |
| 219     | 12/3/2015 10:37 | PAINT | 1.43     | mg / cm ^2 | Final    | Wall          | Gypsum    | D    | Good      | Cream  | East-West Hallway              | Negative | 1           | 1            | < LOD |
| 220     | 12/3/2015 10:39 | PAINT | 2.64     | mg / cm ^2 | Final    | Door          | Steel     | C    | Good      | Cream  | South Hallway                  | Negative | 5.44        | 1            | < LOD |
| 221     | 12/3/2015 10:39 | PAINT | 1        | mg / cm ^2 | Final    | Door Frame    | Steel     | A    | Good      | Cream  | South Hallway                  | Null     | 1           | 1            | < LOD |
| 222     | 12/3/2015 10:40 | PAINT | 3.06     | mg / cm ^2 | Final    | Door Frame    | Steel     | C    | Good      | Cream  | South Hallway                  | Negative | 2.64        | 1            | < LOD |
| 223     | 12/3/2015 10:41 | PAINT | 2.57     | mg / cm ^2 | Final    | Wall          | Gypsum    | C    | Good      | Cream  | South Hallway                  | Negative | 1           | 1            | < LOD |
| 224     | 12/3/2015 10:42 | PAINT | 2.21     | mg / cm ^2 | Final    | Wall          | Gypsum    | D    | Good      | Cream  | South Hallway                  | Negative | 1           | 1            | < LOD |
| 225     | 12/3/2015 10:43 | PAINT | 1.06     | mg / cm ^2 | Final    | Door Frame    | Steel     | A    | Good      | Cream  | South Hallway                  | Negative | 1           | 1            | < LOD |
| 226     | 12/3/2015 10:44 | PAINT | 0.71     | mg / cm ^2 | Final    | Door Frame    | Steel     | C    | Good      | Cream  | South Hallway                  | Null     | 1           | 1            | < LOD |
| 227     | 12/3/2015 10:44 | PAINT | 1.07     | mg / cm ^2 | Final    | Door Frame    | Steel     | C    | Good      | Cream  | South Hallway                  | Negative | 1           | 1            | < LOD |
| 228     | 12/3/2015 10:53 | PAINT | 1.07     | mg / cm ^2 | Final    | Wall          | Gypsum    | A    | Good      | Cream  | Drug Storage                   | Negative | 1           | 1            | < LOD |
| 229     | 12/3/2015 10:54 | PAINT | 3.07     | mg / cm ^2 | Final    | Wall          | Gypsum    | B    | Good      | Cream  | Drug Storage                   | Negative | 1           | 1            | < LOD |
| 230     | 12/3/2015 10:54 | PAINT | 1.07     | mg / cm ^2 | Final    | Door Frame    | Steel     | C    | Good      | Cream  | Drug Storage                   | Negative | 1           | 1            | < LOD |
| 231     | 12/3/2015 10:55 | PAINT | 3.14     | mg / cm ^2 | Final    | Door Frame    | Steel     | D    | Good      | Cream  | Drug Storage                   | Negative | 1           | 1            | < LOD |
| 232     | 12/3/2015 10:56 | PAINT | 1        | mg / cm ^2 | Final    | Door Frame    | Steel     | D    | Good      | Cream  | Picking Room                   | Negative | 1           | 1            | < LOD |
| 233     | 12/3/2015 10:56 | PAINT | 1.07     | mg / cm ^2 | Final    | Wall          | Gypsum    | A    | Good      | Cream  | Picking Room                   | Negative | 1           | 1            | < LOD |
| 234     | 12/3/2015 10:57 | PAINT | 1.5      | mg / cm ^2 | Final    | Wall          | Gypsum    | B    | Good      | Cream  | Picking Room                   | Negative | 1.45        | 1            | < LOD |
| 235     | 12/3/2015 10:58 | PAINT | 1.79     | mg / cm ^2 | Final    | Wall          | Gypsum    | C    | Good      | Cream  | Picking Room                   | Negative | 1           | 1            | < LOD |
| 236     | 12/3/2015 10:58 | PAINT | 1.93     | mg / cm ^2 | Final    | Wall          | Gypsum    | D    | Good      | Cream  | Controlled Substances Room     | Negative | 1           | 1            | < LOD |
| 237     | 12/3/2015 10:59 | PAINT | 1.43     | mg / cm ^2 | Final    | Wall          | Gypsum    | A    | Good      | Cream  | Controlled Substances Room     | Negative | 1           | 1            | < LOD |
| 238     | 12/3/2015 11:00 | PAINT | 1.07     | mg / cm ^2 | Final    | Wall          | Gypsum    | B    | Good      | Cream  | Controlled Substances Room     | Null     | 1           | 1            | < LOD |
| 239     | 12/3/2015 11:00 | PAINT | 1.85     | mg / cm ^2 | Final    | Wall          | Gypsum    | C    | Good      | Cream  | Controlled Substances Room     | Negative | 2.32        | 1            | < LOD |
| 240     | 12/3/2015 11:01 | PAINT | 1.07     | mg / cm ^2 | Final    | Wall          | Gypsum    | D    | Good      | Cream  | Controlled Substances Room     | Negative | 1.12        | 1            | < LOD |
| 241     | 12/3/2015 11:01 | PAINT | 1.07     | mg / cm ^2 | Final    | IV Room       | Steel     | C    | Good      | Cream  | Controlled Substances Room     | Negative | 1           | 1            | < LOD |
| 242     | 12/3/2015 11:03 | PAINT | 2        | mg / cm ^2 | Final    | IV Room       | Gypsum    | A    | Good      | Cream  | Controlled Substances Room     | Negative | 1           | 1            | < LOD |
| 243     | 12/3/2015 11:03 | PAINT | 0.29     | mg / cm ^2 | Final    | IV Room       | Gypsum    | B    | Good      | Cream  | Controlled Substances Room     | Null     | 1           | 1            | < LOD |
| 244     | 12/3/2015 11:03 | PAINT | 1.21     | mg / cm ^2 | Final    | IV Room       | Gypsum    | B    | Good      | Cream  | Controlled Substances Room     | Negative | 1.12        | 1            | < LOD |
| 245     | 12/3/2015 11:04 | PAINT | 1.99     | mg / cm ^2 | Final    | IV Room       | Gypsum    | C    | Good      | Cream  | Controlled Substances Room     | Negative | 1           | 1            | < LOD |

| Reading | Time            | Type  | Duration | Units      | Sequence | Component  | Substrate | Side | Condition | Color | Room                               | Results  | Depth Index | Action Level | PbC   |
|---------|-----------------|-------|----------|------------|----------|------------|-----------|------|-----------|-------|------------------------------------|----------|-------------|--------------|-------|
| 246     | 12/3/2015 11:04 | PAINT | 1.14     | mg / cm ^2 | Final    | Wall       | Gypsum    | D    | Good      | Cream | IV Room                            | Null     | 1           | 1            | < LOD |
| 247     | 12/3/2015 11:05 | PAINT | 1.07     | mg / cm ^2 | Final    | Door Frame | Steel     | C    | Good      | Cream | IV Room                            | Negative | 1           | 1            | < LOD |
| 248     | 12/3/2015 11:05 | PAINT | 1.06     | mg / cm ^2 | Final    | Door       | Steel     | C    | Good      | Cream | IV Room                            | Negative | 1           | 1            | < LOD |
| 249     | 12/3/2015 11:06 | PAINT | 1.07     | mg / cm ^2 | Final    | Door       | Steel     | A    | Good      | Grey  | :emergency Exit Door South Hallway | Negative | 1           | 1            | < LOD |
| 250     | 12/3/2015 11:06 | PAINT | 1.07     | mg / cm ^2 | Final    | Door       | Steel     | A    | Good      | Grey  | :emergency Exit Door South Hallway | Negative | 1           | 1            | < LOD |
| 251     | 12/3/2015 11:07 | PAINT | 2.13     | mg / cm ^2 | Final    | Wall       | Gypsum    | A    | Good      | Cream | Break Room                         | Negative | 1           | 1            | < LOD |
| 252     | 12/3/2015 11:08 | PAINT | 1.64     | mg / cm ^2 | Final    | Wall       | Gypsum    | B    | Good      | Cream | Break Room                         | Negative | 1           | 1            | < LOD |
| 253     | 12/3/2015 11:09 | PAINT | 1.93     | mg / cm ^2 | Final    | Wall       | Gypsum    | C    | Good      | Cream | Break Room                         | Negative | 1           | 1            | < LOD |
| 254     | 12/3/2015 11:10 | PAINT | 1.56     | mg / cm ^2 | Final    | Wall       | Gypsum    | D    | Good      | Cream | Break Room                         | Negative | 1           | 1            | < LOD |
| 255     | 12/3/2015 11:10 | PAINT | 1.07     | mg / cm ^2 | Final    | Door Frame | Steel     | D    | Good      | Cream | Break Room                         | Negative | 1           | 1            | < LOD |
| 256     | 12/3/2015 11:10 | PAINT | 1        | mg / cm ^2 | Final    | Door Frame | Steel     | D    | Good      | Cream | Women's Restroom                   | Negative | 1.71        | 1            | < LOD |
| 257     | 12/3/2015 11:11 | PAINT | 1.07     | mg / cm ^2 | Final    | Wall       | Gypsum    | A    | Good      | Cream | Women's Restroom                   | Negative | 1.39        | 1            | < LOD |
| 258     | 12/3/2015 11:11 | PAINT | 1.78     | mg / cm ^2 | Final    | Wall       | Gypsum    | B    | Good      | Cream | Women's Restroom                   | Negative | 1           | 1            | < LOD |
| 259     | 12/3/2015 11:12 | PAINT | 2.22     | mg / cm ^2 | Final    | Wall       | Gypsum    | C    | Good      | Cream | Women's Restroom                   | Negative | 1           | 1            | < LOD |
| 260     | 12/3/2015 11:12 | PAINT | 0.28     | mg / cm ^2 | Final    | Wall       | Gypsum    | D    | Good      | Cream | Women's Restroom                   | Negative | 2.36        | 1            | < LOD |
| 261     | 12/3/2015 11:12 | PAINT | 2.22     | mg / cm ^2 | Final    | Wall       | Gypsum    | D    | Good      | Cream | Women's Restroom                   | Null     | 1           | 1            | < LOD |
| 262     | 12/3/2015 11:13 | PAINT | 2.5      | mg / cm ^2 | Final    | Wall       | Gypsum    | A    | Good      | Cream | Men's Restroom                     | Negative | 1           | 1            | < LOD |
| 263     | 12/3/2015 11:13 | PAINT | 2.36     | mg / cm ^2 | Final    | Wall       | Gypsum    | B    | Good      | Cream | Men's Restroom                     | Negative | 1           | 1            | < LOD |
| 264     | 12/3/2015 11:14 | PAINT | 1.28     | mg / cm ^2 | Final    | Wall       | Gypsum    | C    | Good      | Cream | Men's Restroom                     | Negative | 1.22        | 1            | < LOD |
| 265     | 12/3/2015 11:14 | PAINT | 2.36     | mg / cm ^2 | Final    | Wall       | Gypsum    | C    | Good      | Cream | Men's Restroom                     | Negative | 1           | 1            | < LOD |
| 266     | 12/3/2015 11:15 | PAINT | 3.07     | mg / cm ^2 | Final    | Wall       | Gypsum    | D    | Good      | Cream | Men's Restroom                     | Negative | 1.22        | 1            | < LOD |
| 267     | 12/3/2015 11:16 | PAINT | 1.07     | mg / cm ^2 | Final    | Door Frame | Steel     | D    | Good      | Cream | Men's Restroom                     | Negative | 1           | 1            | < LOD |
| 268     | 12/3/2015 11:16 | PAINT | 1.07     | mg / cm ^2 | Final    | Wall       | Gypsum    | A    | Good      | White | Electrical Closet South Hallway    | Negative | 1           | 1            | < LOD |
| 269     | 12/3/2015 11:16 | PAINT | 1.07     | mg / cm ^2 | Final    | Wall       | Gypsum    | A    | Good      | White | Electrical Closet South Hallway    | Negative | 1           | 1            | < LOD |
| 270     | 12/3/2015 11:17 | PAINT | 2.36     | mg / cm ^2 | Final    | Wall       | Gypsum    | B    | Good      | White | Electrical Closet South Hallway    | Negative | 1           | 1            | < LOD |
| 271     | 12/3/2015 11:18 | PAINT | 1.14     | mg / cm ^2 | Final    | Wall       | Gypsum    | D    | Good      | White | Electrical Closet South Hallway    | Negative | 1           | 1            | < LOD |
| 272     | 12/3/2015 11:18 | PAINT | 1.06     | mg / cm ^2 | Final    | Door Frame | Steel     | D    | Good      | White | Electrical Closet South Hallway    | Negative | 1           | 1            | < LOD |
| 273     | 12/3/2015 11:19 | PAINT | 0.57     | mg / cm ^2 | Final    | Wall       | Gypsum    | A    | Good      | White | South Hallway - Shower Room        | Null     | 1           | 1            | < LOD |
| 274     | 12/3/2015 11:20 | PAINT | 1.71     | mg / cm ^2 | Final    | Wall       | Gypsum    | A    | Good      | White | South Hallway - Shower Room        | Negative | 1           | 1            | < LOD |
| 277     | 12/3/2015 11:22 | PAINT | 2        | mg / cm ^2 | Final    | Door Frame | Steel     | D    | Good      | White | South Hallway - Shower Room        | Negative | 1           | 1            | < LOD |
| 278     | 12/3/2015 11:22 | PAINT | 1.7      | mg / cm ^2 | Final    | Wall       | Gypsum    | C    | Good      | White | South Hallway - Shower Room        | Negative | 1           | 1            | < LOD |
| 279     | 12/3/2015 11:23 | PAINT | 3.13     | mg / cm ^2 | Final    | Door Frame | Steel     | D    | Good      | White | South Hallway - Shower Room        | Negative | 1.79        | 1            | < LOD |
| 280     | 12/3/2015 11:23 | PAINT | 1.07     | mg / cm ^2 | Final    | Wall       | Gypsum    | A    | Good      | White | South Hallway - Shower Room        | Negative | 1           | 1            | < LOD |
| 281     | 12/3/2015 11:24 | PAINT | 1.28     | mg / cm ^2 | Final    | Door Frame | Steel     | D    | Good      | White | South Hallway - Shower Room        | Negative | 1           | 1            | < LOD |
| 282     | 12/3/2015 11:25 | PAINT | 2.21     | mg / cm ^2 | Final    | Wall       | Gypsum    | B    | Good      | White | Room P038                          | Negative | 1           | 1            | < LOD |
| 283     | 12/3/2015 11:25 | PAINT | 2.21     | mg / cm ^2 | Final    | Wall       | Gypsum    | C    | Good      | White | Room P038                          | Negative | 1           | 1            | < LOD |
| 284     | 12/3/2015 11:26 | PAINT | 2        | mg / cm ^2 | Final    | Door Frame | Steel     | A    | Good      | White | Room P038                          | Negative | 1           | 1            | < LOD |
| 285     | 12/3/2015 11:26 | PAINT | 0.5      | mg / cm ^2 | Final    | Door Frame | Steel     | A    | Good      | White | Room P038                          | Negative | 1           | 1            | < LOD |
| 286     | 12/3/2015 11:26 | PAINT | 1        | mg / cm ^2 | Final    | Wall       | Gypsum    | D    | Good      | White | Room P038                          | Negative | 1           | 1            | < LOD |
| 287     | 12/3/2015 11:27 | PAINT | 2.43     | mg / cm ^2 | Final    | Wall       | Gypsum    | A    | Good      | White | North Hallway - Shower Room        | Negative | 2.54        | 1            | < LOD |
| 288     | 12/3/2015 11:28 | PAINT | 1.85     | mg / cm ^2 | Final    | Wall       | Gypsum    | B    | Good      | White | North Hallway - Shower Room        | Negative | 1           | 1            | < LOD |
| 289     | 12/3/2015 11:28 | PAINT | 2.7      | mg / cm ^2 | Final    | Wall       | Gypsum    | C    | Good      | White | North Hallway - Shower Room        | Negative | 2.35        | 1            | < LOD |
| 290     | 12/3/2015 11:29 | PAINT | 1        | mg / cm ^2 | Final    | Wall       | Gypsum    | D    | Good      | White | North Hallway - Shower Room        | Null     | 1           | 1            | < LOD |
| 291     | 12/3/2015 11:29 | PAINT | 2.5      | mg / cm ^2 | Final    | Wall       | Gypsum    | D    | Good      | White | North Hallway - Shower Room        | Negative | 1           | 1            | < LOD |
| 292     | 12/3/2015 11:30 | PAINT | 1.07     | mg / cm ^2 | Final    | Door Frame | Steel     | B    | Good      | White | North Hallway - Shower Room        | Negative | 1           | 1            | < LOD |
| 293     | 12/3/2015 11:31 | PAINT | 2.21     | mg / cm ^2 | Final    | Wall       | Gypsum    | A    | Good      | White | Room P010                          | Negative | 1.39        | 1            | < LOD |
| 294     | 12/3/2015 11:31 | PAINT | 1.28     | mg / cm ^2 | Final    | Wall       | Gypsum    | B    | Good      | White | Room P010                          | Negative | 1           | 1            | < LOD |
| 295     | 12/3/2015 11:32 | PAINT | 1.36     | mg / cm ^2 | Final    | Wall       | Gypsum    | C    | Good      | White | Room P010                          | Negative | 1           | 1            | < LOD |
| 296     | 12/3/2015 11:32 | PAINT | 1.07     | mg / cm ^2 | Final    | Wall       | Gypsum    | D    | Good      | White | Room P010                          | Negative | 1           | 1            | < LOD |

| Reading | Time            | Type  | Duration | Units      | Sequence | Component   | Substrate | Side | Condition | Color | Room                                    | Results  | Depth Index | Action Level | PoC |
|---------|-----------------|-------|----------|------------|----------|-------------|-----------|------|-----------|-------|---|----------|-------------|--------------|-----|
| 297     | 12/3/2015 11:33 | PAINT | 1.06     | mg / cm ^2 | Final    | Door Frame  | Steel     | D    | Good      | Cream | Room P010                               | Negative | 1           | < LOD        |     |
| 298     | 12/3/2015 11:33 | PAINT | 1.85     | mg / cm ^2 | Final    | Wall        | Gypsum    | A    | Good      | Cream | Room P009                               | Negative | 1           | < LOD        |     |
| 299     | 12/3/2015 11:33 | PAINT | 1.07     | mg / cm ^2 | Final    | Wall        | Gypsum    | B    | Good      | Cream | Room P009                               | Negative | 1           | < LOD        |     |
| 300     | 12/3/2015 11:34 | PAINT | 1.14     | mg / cm ^2 | Final    | Wall        | Gypsum    | C    | Good      | Cream | Room P009                               | Negative | 1           | < LOD        |     |
| 301     | 12/3/2015 11:34 | PAINT | 1.28     | mg / cm ^2 | Final    | Wall        | Gypsum    | D    | Good      | Cream | Room P009                               | Negative | 1           | < LOD        |     |
| 302     | 12/3/2015 11:34 | PAINT | 1.06     | mg / cm ^2 | Final    | Door Frame  | Steel     | D    | Good      | Grey  | Kitchen Addition to Pharmacy            | Negative | 1           | < LOD        |     |
| 303     | 12/3/2015 12:32 | PAINT | 1.07     | mg / cm ^2 | Final    | Stairs      | Steel     | D    | Good      | White | Kitchen Addition to Pharmacy            | Negative | 1           | < LOD        |     |
| 304     | 12/3/2015 12:33 | PAINT | 1.07     | mg / cm ^2 | Final    | Door Frame  | Steel     | A    | Good      | White | Kitchen Addition to Pharmacy            | Negative | 1           | < LOD        |     |
| 305     | 12/3/2015 12:34 | PAINT | 1.06     | mg / cm ^2 | Final    | Door        | Wood      | A    | Good      | White | Kitchen Addition to Pharmacy            | Negative | 1           | < LOD        |     |
| 306     | 12/3/2015 12:34 | PAINT | 1.07     | mg / cm ^2 | Final    | Door Frame  | Door      | A    | Good      | White | Kitchen Addition to Pharmacy            | Negative | 1           | < LOD        |     |
| 307     | 12/3/2015 12:35 | PAINT | 1.57     | mg / cm ^2 | Final    | Door        | Steel     | D    | Good      | White | Kitchen Addition to Pharmacy            | Negative | 1           | < LOD        |     |
| 308     | 12/3/2015 12:35 | PAINT | 1.07     | mg / cm ^2 | Final    | Door Frame  | Steel     | D    | Good      | White | Kitchen Addition to Pharmacy            | Negative | 1.97        | < LOD        |     |
| 309     | 12/3/2015 12:36 | PAINT | 1.07     | mg / cm ^2 | Final    | Corner Post | Wood      | D    | Good      | White | Kitchen Addition to Pharmacy            | Negative | 1.11        | < LOD        |     |
| 310     | 12/3/2015 12:37 | PAINT | 0.78     | mg / cm ^2 | Final    | I-Beam      | Steel     | D    | Good      | Black | Walkway to Kitchen Addition to Pharmacy | Null     | 1           | < LOD        |     |
| 311     | 12/3/2015 12:37 | PAINT | 1.07     | mg / cm ^2 | Final    | I-Beam      | Steel     | D    | Good      | Black | Walkway to Kitchen Addition to Pharmacy | Negative | 1           | < LOD        |     |
| 312     | 12/3/2015 12:38 | PAINT | 1.07     | mg / cm ^2 | Final    | I-Beam      | Steel     | B    | Good      | Black | Walkway to Kitchen Addition to Pharmacy | Negative | 1           | < LOD        |     |
| 313     | 12/3/2015 12:38 | PAINT | 1.06     | mg / cm ^2 | Final    | I-Beam      | Steel     | A    | Good      | Black | Walkway to Kitchen Addition to Pharmacy | Negative | 1           | < LOD        |     |
| 314     | 12/3/2015 12:39 | PAINT | 1.06     | mg / cm ^2 | Final    | Door Frame  | Wood      | D    | Good      | Black | Walkway to Kitchen Addition to Pharmacy | Negative | 1           | < LOD        |     |
| 315     | 12/3/2015 12:40 | PAINT | 1.06     | mg / cm ^2 | Final    | Door        | Steel     | D    | Good      | Black | Walkway to Kitchen Addition to Pharmacy | Negative | 2.71        | < LOD        |     |
| 316     | 12/3/2015 12:41 | PAINT | 1.06     | mg / cm ^2 | Final    | Door Frame  | Steel     | A    | Good      | Black | Women's Restroom in Kitchen Addition    | Negative | 1           | < LOD        |     |
| 317     | 12/3/2015 12:42 | PAINT | 1.07     | mg / cm ^2 | Final    | Door Frame  | Steel     | D    | Good      | Black | Storage Room in Kitchen Addition        | Negative | 1           | < LOD        |     |
| 318     | 12/3/2015 12:42 | PAINT | 1.07     | mg / cm ^2 | Final    | Door Frame  | Steel     | C    | Good      | Black | Men's Restroom in Kitchen Addition      | Negative | 1           | < LOD        |     |
| 319     | 12/3/2015 12:45 | PAINT | 1.07     | mg / cm ^2 | Final    | Door Way    | Wood      | C    | Good      | Black | Kitchen Addition to Pharmacy door way   | Negative | 6.22        | < LOD        |     |
| 320     | 12/3/2015 12:45 | PAINT | 1.57     | mg / cm ^2 | Final    | Wall        | FRP       | C    | Good      | White | Kitchen Addition to Pharmacy            | Negative | 1           | < LOD        |     |
| 321     | 12/3/2015 13:05 | PAINT | 7.88     | mg / cm ^2 | Final    | Calibration |           |      |           |       | Positive                                | 1.09     | 1           | 1.1          |     |
| 322     | 12/3/2015 13:06 | PAINT | 7.66     | mg / cm ^2 | Final    | Calibration |           |      |           |       | Positive                                | 1.12     | 1           | 1.1          |     |
| 323     | 12/3/2015 13:09 | PAINT | 19.86    | mg / cm ^2 | Final    | Calibration |           |      |           |       | Positive                                | 1.11     | 1           | 1            |     |

**APPENDIX C**

**ASBESTOS LABORATORY ANALYTICAL REPORTS**



# EMSL Analytical, Inc.

11931 Industriplex, Suite 100 Baton Rouge, LA 70809  
 Tel/Fax: (225) 755-1920 / (225) 755-1989  
<http://www.EMSL.com> / batonrougelab@emsl.com

**EMSL Order:** 251508142

**Customer ID:** AQTE62

**Customer PO:**

**Project ID:**

**Attention:** Phillip Bellan  
 Terracon Consultants, Inc.  
 2822-B O'Neal Lane  
 Baton Rouge, LA 70816

**Phone:** (225) 442-7019

**Fax:** (225) 344-6346

**Received Date:** 12/3/2015 8:00 AM

**Analysis Date:** 12/4/2015

**Collected Date:** 11/30/2015

**Project:** EH137101-2016-01

## **Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

| Sample                                      | Description                        | Appearance                    | Non-Asbestos               |   | % Type        |
|---|------------------------------------|-------------------------------|----------------------------|---|---------------|
|   |                                    |                               | % Fibrous                  | % Non-Fibrous                               |               |
| 01-CT3-01<br>251508142-0001                 | Dental Clinic - 2'x2' worm/pin CT  | Tan/White Fibrous Homogeneous | 40% Cellulose<br>15% Glass | 45% Non-fibrous (Other)                     | None Detected |
| 01-CT3-02<br>251508142-0002                 | Dental Clinic - 2'x2' worm/pin CT  | Tan/White Fibrous Homogeneous | 40% Cellulose<br>15% Glass | 45% Non-fibrous (Other)                     | None Detected |
| 01-CT3-03<br>251508142-0003                 | Dental Clinic - 2'x2' worm/pin CT  | Tan/White Fibrous Homogeneous | 40% Cellulose<br>15% Glass | 45% Non-fibrous (Other)                     | None Detected |
| 02-WBt-04-Texture<br>251508142-0004         | Dental Clinic - Drywall walls w/JC | White Non-Fibrous Homogeneous |                            | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected |
| 02-WBt-04-Joint Compound<br>251508142-0004A | Dental Clinic - Drywall walls w/JC | White Non-Fibrous Homogeneous |                            | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected |
| 02-WBt-04-Sheetrock<br>251508142-0004B      | Dental Clinic - Drywall walls w/JC | White Non-Fibrous Homogeneous |                            | 100% Non-fibrous (Other)                    | None Detected |
| 02-WBt-05-Texture<br>251508142-0005         | Dental Clinic - Drywall walls w/JC | White Non-Fibrous Homogeneous |                            | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected |
| 02-WBt-05-Joint Compound<br>251508142-0005A | Dental Clinic - Drywall walls w/JC | White Non-Fibrous Homogeneous |                            | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected |
| 02-WBt-05-Sheetrock<br>251508142-0005B      | Dental Clinic - Drywall walls w/JC | White Non-Fibrous Homogeneous |                            | 100% Non-fibrous (Other)                    | None Detected |
| 02-WB1-06-Texture<br>251508142-0006         | Dental Clinic - Drywall walls w/JC | White Non-Fibrous Homogeneous |                            | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected |
| 02-WB1-06-Joint Compound<br>251508142-0006A | Dental Clinic - Drywall walls w/JC | White Non-Fibrous Homogeneous |                            | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected |
| 02-WB1-06-Sheetrock<br>251508142-0006B      | Dental Clinic - Drywall walls w/JC | White Non-Fibrous Homogeneous |                            | 100% Non-fibrous (Other)                    | None Detected |
| 02-WB1-07<br>251508142-0007                 | Dental Clinic - Drywall walls w/JC | White Non-Fibrous Homogeneous |                            | 100% Non-fibrous (Other)                    | None Detected |
| 02-WB1-08-Texture<br>251508142-0008         | Dental Clinic - Drywall walls w/JC | White Non-Fibrous Homogeneous |                            | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected |
| 02-WB1-08-Joint Compound<br>251508142-0008A | Dental Clinic - Drywall walls w/JC | White Non-Fibrous Homogeneous |                            | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected |

Initial Report From: 12/08/2015 13:16:24

PLM - 1.65 Printed: 12/8/2015 12:16 PM

Page 1 of 12



# EMSL Analytical, Inc.

11931 Industriplex, Suite 100 Baton Rouge, LA 70809  
 Tel/Fax: (225) 755-1920 / (225) 755-1989  
<http://www.EMSL.com> / batonrougelab@emsl.com

EMSL Order: 251508142

Customer ID: AQTE62

Customer PO:

Project ID:

## Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample                                       | Description                                   | Appearance                                  | Non-Asbestos  |   | Asbestos % Type |
|--|---|---|---------------|---|-----------------|
|  |   |   | % Fibrous     | % Non-Fibrous                               |                 |
| 02-WB1-08-Sheetrock<br>251508142-0008B       | Dental Clinic - Drywall walls w/JC            | White<br>Non-Fibrous<br>Homogeneous         |               | 100% Non-fibrous (Other)                    | None Detected   |
| 02-WB1-09-Texture<br>251508142-0009          | Dental Clinic - Drywall walls w/JC            | White<br>Non-Fibrous<br>Homogeneous         |               | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected   |
| 02-WB1-09-Sheetrock<br>251508142-0009A       | Dental Clinic - Drywall walls w/JC            | White<br>Non-Fibrous<br>Homogeneous         |               | 100% Non-fibrous (Other)                    | None Detected   |
| 02-WB1-10-Texture<br>251508142-0010          | Dental Clinic - Drywall walls w/JC            | White<br>Non-Fibrous<br>Homogeneous         |               | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected   |
| 02-WB1-10-Joint Compound<br>251508142-0010A  | Dental Clinic - Drywall walls w/JC            | White<br>Non-Fibrous<br>Homogeneous         |               | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected   |
| 02-WB1-10-Sheetrock<br>251508142-0010B       | Dental Clinic - Drywall walls w/JC            | White<br>Non-Fibrous<br>Homogeneous         |               | 100% Non-fibrous (Other)                    | None Detected   |
| 03-MG3-11<br>251508142-0011                  | Dental Clinic - Cove base adhesive            | Yellow<br>Non-Fibrous<br>Homogeneous        |               | 100% Non-fibrous (Other)                    | None Detected   |
| 03-MG3-12<br>251508142-0012                  | Dental Clinic - Cove base adhesive            | Yellow<br>Non-Fibrous<br>Homogeneous        |               | 100% Non-fibrous (Other)                    | None Detected   |
| 03-MG3-13<br>251508142-0013                  | Dental Clinic - Cove base adhesive            | Yellow<br>Non-Fibrous<br>Homogeneous        |               | 100% Non-fibrous (Other)                    | None Detected   |
| 05-FT5-14-Floor Tile<br>251508142-0014       | Dental Clinic - 12"x12" tan FT w/yellow glue  | Tan<br>Non-Fibrous<br>Homogeneous           |               | 100% Non-fibrous (Other)                    | None Detected   |
| 05-FT5-14-Mastic<br>251508142-0014A          | Dental Clinic - 12"x12" tan FT w/yellow glue  | Yellow<br>Non-Fibrous<br>Homogeneous        |               | 100% Non-fibrous (Other)                    | None Detected   |
| 05-FT5-14-Leveler<br>251508142-0014B         | Dental Clinic - 12"x12" tan FT w/yellow glue  | Gray/Tan<br>Fibrous<br>Homogeneous          | 10% Cellulose | 90% Non-fibrous (Other)                     | None Detected   |
| 05-FT5-15-Floor Tile<br>251508142-0015       | Dental Clinic - 12"x12" tan FT w/yellow glue  | Tan<br>Non-Fibrous<br>Homogeneous           |               | 100% Non-fibrous (Other)                    | None Detected   |
| 05-FT5-15-Mastic<br>251508142-0015A          | Dental Clinic - 12"x12" tan FT w/yellow glue  | Yellow<br>Non-Fibrous<br>Homogeneous        |               | 100% Non-fibrous (Other)                    | None Detected   |
| 05-FT5-15-Leveler<br>251508142-0015B         | Dental Clinic - 12"x12" tan FT w/yellow glue  | Gray/Tan<br>Fibrous<br>Homogeneous          | 10% Cellulose | 90% Non-fibrous (Other)                     | None Detected   |
| 05-FT5-16-Floor Tile<br>251508142-0016       | Dental Clinic - 12"x12" tan FT w/yellow glue  | Tan<br>Non-Fibrous<br>Homogeneous           |               | 100% Non-fibrous (Other)                    | None Detected   |
| 05-FT5-16-Mastic/Level er<br>251508142-0016A | Dental Clinic - 12"x12" tan FT w/yellow glue  | Gray/Tan/Yellow<br>Fibrous<br>Heterogeneous | 10% Cellulose | 90% Non-fibrous (Other)                     | None Detected   |
| 05-FT5-17-Floor Tile<br>251508142-0017       | Dental Clinic - 12"x12" blue FT w/yellow glue | Gray<br>Non-Fibrous<br>Homogeneous          |               | 100% Non-fibrous (Other)                    | None Detected   |
| 05-FT5-17-Mastic<br>251508142-0017A          | Dental Clinic - 12"x12" blue FT w/yellow glue | Yellow<br>Non-Fibrous<br>Homogeneous        |               | 100% Non-fibrous (Other)                    | None Detected   |

Initial Report From: 12/08/2015 13:16:24

PLM - 1.65 Printed: 12/8/2015 12:16 PM

Page 2 of 12



# EMSL Analytical, Inc.

11931 Industriplex, Suite 100 Baton Rouge, LA 70809

Tel/Fax: (225) 755-1920 / (225) 755-1989

<http://www.EMSL.com> / batonrougelab@emsl.com

EMSL Order: 251508142

Customer ID: AQTE62

Customer PO:

Project ID:

## Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample                                      | Description  | Appearance                                  | Non-Asbestos  |                          | Asbestos<br>% Type |
|---|--|---|---------------|--------------------------|--------------------|
|   |  |   | % Fibrous     | % Non-Fibrous            |                    |
| 05-FT5-17-Leveler<br>251508142-0017B        | Dental Clinic -<br>12"x12" blue FT<br>w/yellow glue  | Gray/Tan<br>Fibrous<br>Homogeneous          | 10% Cellulose | 90% Non-fibrous (Other)  | None Detected      |
| 05-FT5-18-Floor Tile<br>251508142-0018      | Dental Clinic -<br>12"x12" blue FT<br>w/yellow glue  | Blue<br>Non-Fibrous<br>Homogeneous          |               | 100% Non-fibrous (Other) | None Detected      |
| 05-FT5-18-Mastic<br>251508142-0018A         | Dental Clinic -<br>12"x12" blue FT<br>w/yellow glue  | Yellow<br>Non-Fibrous<br>Homogeneous        |               | 100% Non-fibrous (Other) | None Detected      |
| 05-FT5-18-Leveler<br>251508142-0018B        | Dental Clinic -<br>12"x12" blue FT<br>w/yellow glue  | Gray/Tan<br>Fibrous<br>Homogeneous          | 10% Cellulose | 90% Non-fibrous (Other)  | None Detected      |
| 05-FT5-19-Floor Tile<br>251508142-0019      | Dental Clinic -<br>12"x12" blue FT<br>w/yellow glue  | Blue<br>Non-Fibrous<br>Homogeneous          |               | 100% Non-fibrous (Other) | None Detected      |
| 05-FT5-19-Mastic<br>251508142-0019A         | Dental Clinic -<br>12"x12" blue FT<br>w/yellow glue  | Yellow<br>Non-Fibrous<br>Homogeneous        |               | 100% Non-fibrous (Other) | None Detected      |
| 05-FT5-19-Leveler<br>251508142-0019B        | Dental Clinic -<br>12"x12" blue FT<br>w/yellow glue  | Gray/Tan<br>Fibrous<br>Homogeneous          | 10% Cellulose | 90% Non-fibrous (Other)  | None Detected      |
| 05-FT5-20-Floor Tile<br>251508142-0020      | Dental Clinic -<br>12"x12" brown FT<br>w/yellow glue | Brown<br>Non-Fibrous<br>Homogeneous         |               | 100% Non-fibrous (Other) | None Detected      |
| 05-FT5-20-Mastic<br>251508142-0020A         | Dental Clinic -<br>12"x12" brown FT<br>w/yellow glue | Yellow<br>Non-Fibrous<br>Homogeneous        |               | 100% Non-fibrous (Other) | None Detected      |
| 05-FT5-20-Leveler<br>251508142-0020B        | Dental Clinic -<br>12"x12" brown FT<br>w/yellow glue | Gray/Tan<br>Fibrous<br>Homogeneous          | 10% Cellulose | 90% Non-fibrous (Other)  | None Detected      |
| 05-FT5-21-Floor Tile<br>251508142-0021      | Dental Clinic -<br>12"x12" brown FT<br>w/yellow glue | Brown<br>Non-Fibrous<br>Homogeneous         |               | 100% Non-fibrous (Other) | None Detected      |
| 05-FT5-21-Mastic<br>251508142-0021A         | Dental Clinic -<br>12"x12" brown FT<br>w/yellow glue | Yellow<br>Non-Fibrous<br>Homogeneous        |               | 100% Non-fibrous (Other) | None Detected      |
| 05-FT5-21-Leveler<br>251508142-0021B        | Dental Clinic -<br>12"x12" brown FT<br>w/yellow glue | Gray/Tan<br>Fibrous<br>Homogeneous          | 10% Cellulose | 90% Non-fibrous (Other)  | None Detected      |
| 05-FT5-22-Floor Tile<br>251508142-0022      | Dental Clinic -<br>12"x12" brown FT<br>w/yellow glue | Brown<br>Non-Fibrous<br>Homogeneous         |               | 100% Non-fibrous (Other) | None Detected      |
| 05-FT5-22-Mastic/Leveler<br>251508142-0022A | Dental Clinic -<br>12"x12" brown FT<br>w/yellow glue | Gray/Tan/Yellow<br>Fibrous<br>Heterogeneous | 10% Cellulose | 90% Non-fibrous (Other)  | None Detected      |
| 07-MG7-23<br>251508142-0023                 | Dental Clinic - Yellow<br>carpet glue                | Yellow<br>Non-Fibrous<br>Homogeneous        |               | 100% Non-fibrous (Other) | None Detected      |
| 07-MG7-24<br>251508142-0024                 | Dental Clinic - Yellow<br>carpet glue                | Yellow<br>Non-Fibrous<br>Homogeneous        |               | 100% Non-fibrous (Other) | None Detected      |
| 07-MG7-25<br>251508142-0025                 | Dental Clinic - Yellow<br>carpet glue                | Yellow<br>Non-Fibrous<br>Homogeneous        |               | 100% Non-fibrous (Other) | None Detected      |
| 08-SG1-26-Flooring<br>251508142-0026        | Dental Clinic -<br>Laminate flooring<br>(RRs)        | Gray/White<br>Fibrous<br>Homogeneous        | 20% Synthetic | 80% Non-fibrous (Other)  | None Detected      |

Initial Report From: 12/08/2015 13:16:24

PLM - 1.65 Printed: 12/8/2015 12:16 PM

Page 3 of 12



# EMSL Analytical, Inc.

11931 Industriplex, Suite 100 Baton Rouge, LA 70809  
 Tel/Fax: (225) 755-1920 / (225) 755-1989  
<http://www.EMSL.com> / batonrougelab@emsl.com

**EMSL Order:** 251508142

**Customer ID:** AQTE62

**Customer PO:**

**Project ID:**

## Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample                                  | Description                             | Appearance                                   | Non-Asbestos              |                          | <u>Asbestos</u><br>% Type |
|---|---|--|---------------------------|--------------------------|---------------------------|
|   |   |  | % Fibrous                 | % Non-Fibrous            |                           |
| 08-SG1-26-Glue<br>251508142-0026A       | Dental Clinic - Laminate flooring (RRs) | Clear<br>Non-Fibrous<br>Homogeneous          |                           | 100% Non-fibrous (Other) | None Detected             |
| 08-SG1-26-Leveler<br>251508142-0026B    | Dental Clinic - Laminate flooring (RRs) | Gray<br>Non-Fibrous<br>Homogeneous           |                           | 100% Non-fibrous (Other) | None Detected             |
| 08-SG1-27-Flooring<br>251508142-0027    | Dental Clinic - Laminate flooring (RRs) | Gray/White<br>Fibrous<br>Homogeneous         | 20% Synthetic             | 80% Non-fibrous (Other)  | None Detected             |
| 08-SG1-27-Glue<br>251508142-0027A       | Dental Clinic - Laminate flooring (RRs) | Clear<br>Non-Fibrous<br>Homogeneous          |                           | 100% Non-fibrous (Other) | None Detected             |
| 08-SG1-27-Leveler<br>251508142-0027B    | Dental Clinic - Laminate flooring (RRs) | Gray<br>Non-Fibrous<br>Homogeneous           |                           | 100% Non-fibrous (Other) | None Detected             |
| 08-SG1-28-Flooring<br>251508142-0028    | Dental Clinic - Laminate flooring (RRs) | Gray/White<br>Fibrous<br>Homogeneous         | 20% Synthetic             | 80% Non-fibrous (Other)  | None Detected             |
| 08-SG1-28-Glue<br>251508142-0028A       | Dental Clinic - Laminate flooring (RRs) | Clear<br>Non-Fibrous<br>Homogeneous          |                           | 100% Non-fibrous (Other) | None Detected             |
| 08-SG1-28-Leveler<br>251508142-0028B    | Dental Clinic - Laminate flooring (RRs) | Gray<br>Non-Fibrous<br>Homogeneous           |                           | 100% Non-fibrous (Other) | None Detected             |
| 09-MI4-29-Wrap<br>251508142-0029        | Dental Clinic - Duct wrap w/mastic      | Tan/White/Silver<br>Fibrous<br>Heterogeneous | 30% Cellulose<br>5% Glass | 65% Non-fibrous (Other)  | None Detected             |
| 09-MI4-29-Insulation<br>251508142-0029A | Dental Clinic - Duct wrap w/mastic      | Yellow<br>Fibrous<br>Homogeneous             | 98% Glass                 | 2% Non-fibrous (Other)   | None Detected             |
| 09-MI4-30-Wrap<br>251508142-0030        | Dental Clinic - Duct wrap w/mastic      | Tan/White/Silver<br>Fibrous<br>Heterogeneous | 30% Cellulose<br>5% Glass | 65% Non-fibrous (Other)  | None Detected             |
| 09-MI4-30-Insulation<br>251508142-0030A | Dental Clinic - Duct wrap w/mastic      | Yellow<br>Fibrous<br>Homogeneous             | 98% Glass                 | 2% Non-fibrous (Other)   | None Detected             |
| 09-MI4-31-Wrap<br>251508142-0031        | Dental Clinic - Duct wrap w/mastic      | Tan/White/Silver<br>Fibrous<br>Heterogeneous | 30% Cellulose<br>5% Glass | 65% Non-fibrous (Other)  | None Detected             |
| 09-MI4-31-Insulation<br>251508142-0031A | Dental Clinic - Duct wrap w/mastic      | Yellow<br>Fibrous<br>Homogeneous             | 98% Glass                 | 2% Non-fibrous (Other)   | None Detected             |
| 10-SC6-32<br>251508142-0032             | Dental Clinic - Sink under coating      | Gray<br>Non-Fibrous<br>Homogeneous           | 2% Cellulose              | 98% Non-fibrous (Other)  | None Detected             |
| 10-SC6-33<br>251508142-0033             | Dental Clinic - Sink under coating      | Gray<br>Non-Fibrous<br>Homogeneous           | 2% Cellulose              | 98% Non-fibrous (Other)  | None Detected             |
| 10-SC6-34<br>251508142-0034             | Dental Clinic - Sink under coating      | Gray<br>Non-Fibrous<br>Homogeneous           | 2% Cellulose              | 98% Non-fibrous (Other)  | None Detected             |
| 11-MG5-35<br>251508142-0035             | Dental Clinic - Laminate countertop     | Brown/White<br>Non-Fibrous<br>Homogeneous    | 60% Cellulose             | 40% Non-fibrous (Other)  | None Detected             |
| 11-MG5-36<br>251508142-0036             | Dental Clinic - Laminate countertop     | Brown/Gray<br>Non-Fibrous<br>Homogeneous     | 60% Cellulose             | 40% Non-fibrous (Other)  | None Detected             |



# EMSL Analytical, Inc.

11931 Industriplex, Suite 100 Baton Rouge, LA 70809  
 Tel/Fax: (225) 755-1920 / (225) 755-1989  
<http://www.EMSL.com> / batonrougelab@emsl.com

**EMSL Order:** 251508142

**Customer ID:** AQTE62

**Customer PO:**

**Project ID:**

## Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample                                      | Description                                 | Appearance                                | <u>Non-Asbestos</u>        |   | <u>Asbestos</u><br>% Type |
|---|---|---|----------------------------|---|---------------------------|
|   |   |   | % Fibrous                  | % Non-Fibrous                               |                           |
| 11-MG5-37<br>251508142-0037                 | Dental Clinic - Laminate countertop         | Brown/Gray<br>Non-Fibrous<br>Homogeneous  | 60% Cellulose              | 40% Non-fibrous (Other)                     | None Detected             |
| 12-PI5-38-Tape<br>251508142-0038            | Dental Clinic - Black water pipe insulation | White/Black<br>Non-Fibrous<br>Homogeneous | 10% Synthetic              | 90% Non-fibrous (Other)                     | None Detected             |
| 12-PI5-38-Insulation<br>251508142-0038A     | Dental Clinic - Black water pipe insulation | Black<br>Non-Fibrous<br>Homogeneous       |                            | 100% Non-fibrous (Other)                    | None Detected             |
| 12-PI5-39-Tape<br>251508142-0039            | Dental Clinic - Black water pipe insulation | White/Black<br>Non-Fibrous<br>Homogeneous | 10% Synthetic              | 90% Non-fibrous (Other)                     | None Detected             |
| 12-PI5-39-Insulation<br>251508142-0039A     | Dental Clinic - Black water pipe insulation | Black<br>Non-Fibrous<br>Homogeneous       |                            | 100% Non-fibrous (Other)                    | None Detected             |
| 12-PI5-40-Tape<br>251508142-0040            | Dental Clinic - Black water pipe insulation | White/Black<br>Non-Fibrous<br>Homogeneous | 10% Synthetic              | 90% Non-fibrous (Other)                     | None Detected             |
| 12-PI5-40-Insulation<br>251508142-0040A     | Dental Clinic - Black water pipe insulation | Black<br>Non-Fibrous<br>Homogeneous       |                            | 100% Non-fibrous (Other)                    | None Detected             |
| 13-CA7-41<br>251508142-0041                 | Dental Clinic - Fire stop caulk             | Red<br>Non-Fibrous<br>Homogeneous         |                            | 100% Non-fibrous (Other)                    | None Detected             |
| 13-CA7-42<br>251508142-0042                 | Dental Clinic - Fire stop caulk             | Red<br>Non-Fibrous<br>Homogeneous         |                            | 100% Non-fibrous (Other)                    | None Detected             |
| 13-CA7-43<br>251508142-0043                 | Dental Clinic - Fire stop caulk             | Red<br>Non-Fibrous<br>Homogeneous         |                            | 100% Non-fibrous (Other)                    | None Detected             |
| 14-CT3-44<br>251508142-0044                 | Pharmacy (Lab) - 2'x2' texture CT           | Tan/White<br>Fibrous<br>Homogeneous       | 30% Cellulose<br>15% Glass | 55% Non-fibrous (Other)                     | None Detected             |
| 14-CT3-45<br>251508142-0045                 | Pharmacy (Lab) - 2'x2' texture CT           | Tan/White<br>Fibrous<br>Homogeneous       | 20% Cellulose<br>30% Glass | 50% Non-fibrous (Other)                     | None Detected             |
| 14-CT3-46<br>251508142-0046                 | Pharmacy (Lab) - 2'x2' texture CT           | Tan/White<br>Fibrous<br>Homogeneous       | 20% Cellulose<br>30% Glass | 50% Non-fibrous (Other)                     | None Detected             |
| 15-CT3-47<br>251508142-0047                 | Pharmacy - 2'x2' worm/pin CT                | Tan/White<br>Fibrous<br>Homogeneous       | 20% Cellulose<br>30% Glass | 50% Non-fibrous (Other)                     | None Detected             |
| 15-CT3-48<br>251508142-0048                 | Pharmacy (Hall) - 2'x2' worm/pin CT         | Tan/White<br>Fibrous<br>Homogeneous       | 20% Cellulose<br>30% Glass | 50% Non-fibrous (Other)                     | None Detected             |
| 15-CT3-49<br>251508142-0049                 | Pharmacy (Rm P0100) - 2'x2' worm/pin CT     | Tan/White<br>Fibrous<br>Homogeneous       | 20% Cellulose<br>30% Glass | 50% Non-fibrous (Other)                     | None Detected             |
| 16-WB1-50-Texture<br>251508142-0050         | Pharmacy (P0100) - Drywall walls w/JC       | White<br>Non-Fibrous<br>Homogeneous       |                            | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected             |
| 16-WB1-50-Joint Compound<br>251508142-0050A | Pharmacy (P0100) - Drywall walls w/JC       | White<br>Non-Fibrous<br>Homogeneous       |                            | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected             |
| 16-WB1-50-Sheetrock<br>251508142-0050B      | Pharmacy (P0100) - Drywall walls w/JC       | Beige<br>Non-Fibrous<br>Homogeneous       |                            | 100% Non-fibrous (Other)                    | None Detected             |

Initial Report From: 12/08/2015 13:16:24



# EMSL Analytical, Inc.

11931 Industriplex, Suite 100 Baton Rouge, LA 70809  
 Tel/Fax: (225) 755-1920 / (225) 755-1989  
<http://www.EMSL.com> / batonrougelab@emsl.com

EMSL Order: 251508142

Customer ID: AQTE62

Customer PO:

Project ID:

## Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample                                      | Description                             | Appearance                          | Non-Asbestos |   | Asbestos % Type |
|---|---|-------------------------------------|--------------|---|-----------------|
|   |   |                                     | % Fibrous    | % Non-Fibrous                               |                 |
| 16-WB1-51-Texture<br>251508142-0051         | Pharmacy (Hall) - Drywall walls w/JC    | White<br>Non-Fibrous<br>Homogeneous |              | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected   |
| 16-WB1-51-Joint Compound<br>251508142-0051A | Pharmacy (Hall) - Drywall walls w/JC    | White<br>Non-Fibrous<br>Homogeneous |              | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected   |
| 16-WB1-51-Sheetrock<br>251508142-0051B      | Pharmacy (Hall) - Drywall walls w/JC    | White<br>Non-Fibrous<br>Homogeneous |              | 100% Non-fibrous (Other)                    | None Detected   |
| 16-WB1-52-Texture<br>251508142-0052         | Pharmacy - Drywall walls w/JC           | White<br>Non-Fibrous<br>Homogeneous |              | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected   |
| 16-WB1-52-Sheetrock<br>251508142-0052A      | Pharmacy - Drywall walls w/JC           | White<br>Non-Fibrous<br>Homogeneous |              | 100% Non-fibrous (Other)                    | None Detected   |
| 16-WB1-53-Texture<br>251508142-0053         | Pharmacy (Rm P008) - Drywall walls w/JC | White<br>Non-Fibrous<br>Homogeneous |              | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected   |
| 16-WB1-53-Joint Compound<br>251508142-0053A | Pharmacy (Rm P008) - Drywall walls w/JC | White<br>Non-Fibrous<br>Homogeneous |              | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected   |
| 16-WB1-53-Sheetrock<br>251508142-0053B      | Pharmacy (Rm P008) - Drywall walls w/JC | White<br>Non-Fibrous<br>Homogeneous |              | 100% Non-fibrous (Other)                    | None Detected   |
| 16-WB1-54-Texture<br>251508142-0054         | Pharmacy (Rm P025) - Drywall walls w/JC | White<br>Non-Fibrous<br>Homogeneous |              | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected   |
| 16-WB1-54-Joint Compound<br>251508142-0054A | Pharmacy (Rm P025) - Drywall walls w/JC | White<br>Non-Fibrous<br>Homogeneous |              | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected   |
| 16-WB1-54-Sheetrock<br>251508142-0054B      | Pharmacy (Rm P025) - Drywall walls w/JC | White<br>Non-Fibrous<br>Homogeneous |              | 100% Non-fibrous (Other)                    | None Detected   |
| 16-WB1-55-Texture<br>251508142-0055         | Pharmacy - Drywall walls w/JC           | White<br>Non-Fibrous<br>Homogeneous |              | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected   |
| 16-WB1-55-Joint Compound<br>251508142-0055A | Pharmacy - Drywall walls w/JC           | White<br>Non-Fibrous<br>Homogeneous |              | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected   |
| 16-WB1-55-Sheetrock<br>251508142-0055B      | Pharmacy - Drywall walls w/JC           | Beige<br>Non-Fibrous<br>Homogeneous |              | 100% Non-fibrous (Other)                    | None Detected   |
| 16-WB1-56-Texture<br>251508142-0056         | Pharmacy (Lab) - Drywall walls w/JC     | White<br>Non-Fibrous<br>Homogeneous |              | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected   |
| 16-WB1-56-Joint Compound<br>251508142-0056A | Pharmacy (Lab) - Drywall walls w/JC     | White<br>Non-Fibrous<br>Homogeneous |              | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected   |
| 16-WB1-56-Sheetrock<br>251508142-0056B      | Pharmacy (Lab) - Drywall walls w/JC     | White<br>Non-Fibrous<br>Homogeneous |              | 100% Non-fibrous (Other)                    | None Detected   |
| 17-MG5-57<br>251508142-0057                 | Pharmacy (Hall) - Masic on FRP Wainscot | Tan<br>Fibrous<br>Homogeneous       |              | 100% Non-fibrous (Other)                    | None Detected   |

Initial Report From: 12/08/2015 13:16:24

PLM - 1.65 Printed: 12/8/2015 12:16 PM

Page 6 of 12



# EMSL Analytical, Inc.

11931 Industriplex, Suite 100 Baton Rouge, LA 70809  
 Tel/Fax: (225) 755-1920 / (225) 755-1989  
<http://www.EMSL.com> / [batonrougelab@emsl.com](mailto:batonrougelab@emsl.com)

**EMSL Order:** 251508142

**Customer ID:** AQTE62

**Customer PO:**

**Project ID:**

## Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample                                 | Description                                   | Appearance                                | <u>Non-Asbestos</u> |                          | <u>Asbestos</u><br>% Type |
|--|---|---|---------------------|--------------------------|---------------------------|
|  |   |   | % Fibrous           | % Non-Fibrous            |                           |
| 17-MG5-58<br>251508142-0058            | Pharmacy (Hall) - Masic on FRP Wainscot       | Tan<br>Non-Fibrous<br>Homogeneous         |                     | 100% Non-fibrous (Other) | None Detected             |
| 17-MG5-59<br>251508142-0059            | Pharmacy (Hall) - Masic on FRP Wainscot       | Tan<br>Non-Fibrous<br>Homogeneous         |                     | 100% Non-fibrous (Other) | None Detected             |
| 18-MG3-60<br>251508142-0060            | Pharmacy - Tan cove base adhesive             | Tan<br>Non-Fibrous<br>Homogeneous         |                     | 100% Non-fibrous (Other) | None Detected             |
| 18-MG3-61<br>251508142-0061            | Pharmacy - Tan cove base adhesive             | Tan<br>Non-Fibrous<br>Homogeneous         |                     | 100% Non-fibrous (Other) | None Detected             |
| 18-MG3-62<br>251508142-0062            | Pharmacy - Tan cove base adhesive             | Tan<br>Non-Fibrous<br>Homogeneous         |                     | 100% Non-fibrous (Other) | None Detected             |
| 19-FT5-63-Floor Tile<br>251508142-0063 | Pharmacy - 12"x12" tan FT w/yellow glue       | Tan<br>Non-Fibrous<br>Homogeneous         |                     | 100% Non-fibrous (Other) | None Detected             |
| 19-FT5-63-Mastic<br>251508142-0063A    | Pharmacy - 12"x12" tan FT w/yellow glue       | Tan<br>Non-Fibrous<br>Homogeneous         |                     | 100% Non-fibrous (Other) | None Detected             |
| 19-FT5-64-Floor Tile<br>251508142-0064 | Pharmacy - 12"x12" tan FT w/yellow glue       | Tan<br>Non-Fibrous<br>Homogeneous         |                     | 100% Non-fibrous (Other) | None Detected             |
| 19-FT5-64-Mastic<br>251508142-0064A    | Pharmacy - 12"x12" tan FT w/yellow glue       | Tan<br>Non-Fibrous<br>Homogeneous         |                     | 100% Non-fibrous (Other) | None Detected             |
| 19-FT5-65-Floor Tile<br>251508142-0065 | Pharmacy - 12"x12" tan FT w/yellow glue       | Tan<br>Non-Fibrous<br>Homogeneous         |                     | 100% Non-fibrous (Other) | None Detected             |
| 19-FT5-65-Mastic<br>251508142-0065A    | Pharmacy - 12"x12" tan FT w/yellow glue       | Tan<br>Non-Fibrous<br>Homogeneous         |                     | 100% Non-fibrous (Other) | None Detected             |
| 19-FT5-65-Leveler<br>251508142-0065B   | Pharmacy - 12"x12" off-white FT w/yellow glue | Gray<br>Non-Fibrous<br>Homogeneous        |                     | 100% Non-fibrous (Other) | None Detected             |
| 20-FT5-66-Floor Tile<br>251508142-0066 | Pharmacy - 12"x12" off-white FT w/yellow glue | White<br>Non-Fibrous<br>Homogeneous       |                     | 100% Non-fibrous (Other) | None Detected             |
| 20-FT5-66-Mastic<br>251508142-0066A    | Pharmacy - 12"x12" off-white FT w/yellow glue | Gray/Yellow<br>Non-Fibrous<br>Homogeneous |                     | 100% Non-fibrous (Other) | None Detected             |
| 20-FT5-67-Floor Tile<br>251508142-0067 | Pharmacy - 12"x12" off-white FT w/yellow glue | White<br>Non-Fibrous<br>Homogeneous       |                     | 100% Non-fibrous (Other) | None Detected             |
| 20-FT5-67-Mastic<br>251508142-0067A    | Pharmacy - 12"x12" off-white FT w/yellow glue | Gray/Yellow<br>Non-Fibrous<br>Homogeneous |                     | 100% Non-fibrous (Other) | None Detected             |
| 20-FT5-68-Floor Tile<br>251508142-0068 | Pharmacy - 12"x12" off-white FT w/yellow glue | White<br>Non-Fibrous<br>Homogeneous       |                     | 100% Non-fibrous (Other) | None Detected             |
| 20-FT5-68-Mastic<br>251508142-0068A    | Pharmacy - 12"x12" off-white FT w/yellow glue | Gray/Yellow<br>Non-Fibrous<br>Homogeneous |                     | 100% Non-fibrous (Other) | None Detected             |
| 21-FT5-69-Floor Tile<br>251508142-0069 | Pharmacy - 12"x12" blue FT w/yellow glue      | Blue<br>Non-Fibrous<br>Homogeneous        |                     | 100% Non-fibrous (Other) | None Detected             |

Initial Report From: 12/08/2015 13:16:24

PLM - 1.65 Printed: 12/8/2015 12:16 PM

Page 7 of 12



# EMSL Analytical, Inc.

11931 Industriplex, Suite 100 Baton Rouge, LA 70809  
 Tel/Fax: (225) 755-1920 / (225) 755-1989  
<http://www.EMSL.com> / batonrougelab@emsl.com

EMSL Order: 251508142

Customer ID: AQTE62

Customer PO:

Project ID:

## Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample                                 | Description  | Appearance                                | Non-Asbestos |                          | Asbestos      |
|--|--|---|--------------|--------------------------|---------------|
|  |  |   | % Fibrous    | % Non-Fibrous            | % Type        |
| 21-FT5-69-Mastic<br>251508142-0069A    | Pharmacy - 12"x12"<br>blue FT w/yellow glue              | Tan<br>Non-Fibrous<br>Homogeneous         |              | 100% Non-fibrous (Other) | None Detected |
| 21-FT5-70-Floor Tile<br>251508142-0070 | Pharmacy - 12"x12"<br>blue FT w/yellow glue              | Blue<br>Non-Fibrous<br>Homogeneous        |              | 100% Non-fibrous (Other) | None Detected |
| 21-FT5-70-Mastic<br>251508142-0070A    | Pharmacy - 12"x12"<br>blue FT w/yellow glue              | Tan<br>Non-Fibrous<br>Homogeneous         |              | 100% Non-fibrous (Other) | None Detected |
| 21-FT5-71-Floor Tile<br>251508142-0071 | Pharmacy - 12"x12"<br>blue FT w/yellow glue              | Blue<br>Non-Fibrous<br>Homogeneous        |              | 100% Non-fibrous (Other) | None Detected |
| 21-FT5-71-Mastic<br>251508142-0071A    | Pharmacy - 12"x12"<br>blue FT w/yellow glue              | Tan<br>Non-Fibrous<br>Homogeneous         |              | 100% Non-fibrous (Other) | None Detected |
| 22-FT5-72-Floor Tile<br>251508142-0072 | Pharmacy - 12"x12"<br>light blue FT w/yellow<br>glue     | Brown<br>Non-Fibrous<br>Homogeneous       |              | 100% Non-fibrous (Other) | None Detected |
| 22-FT5-72-Mastic<br>251508142-0072A    | Pharmacy - 12"x12"<br>light blue FT w/yellow<br>glue     | Yellow<br>Non-Fibrous<br>Homogeneous      |              | 100% Non-fibrous (Other) | None Detected |
| 22-FT5-73<br>251508142-0073            | Pharmacy - 12"x12"<br>light blue FT w/yellow<br>glue     | Brown<br>Non-Fibrous<br>Homogeneous       |              | 100% Non-fibrous (Other) | None Detected |
| 22-FT5-74-Floor Tile<br>251508142-0074 | Pharmacy - 12"x12"<br>light blue FT w/yellow<br>glue     | Brown<br>Non-Fibrous<br>Homogeneous       |              | 100% Non-fibrous (Other) | None Detected |
| 22-FT5-74-Mastic<br>251508142-0074A    | Pharmacy - 12"x12"<br>light blue FT w/yellow<br>glue     | Gray/Yellow<br>Non-Fibrous<br>Homogeneous |              | 100% Non-fibrous (Other) | None Detected |
| 23-FT5-75<br>251508142-0075            | Pharmacy - 12"x12"<br>dark brown FT<br>w/yellow glue     | Brown<br>Non-Fibrous<br>Homogeneous       |              | 100% Non-fibrous (Other) | None Detected |
| 23-FT5-76<br>251508142-0076            | Pharmacy - 12"x12"<br>dark brown FT<br>w/yellow glue     | Brown<br>Non-Fibrous<br>Homogeneous       |              | 100% Non-fibrous (Other) | None Detected |
| 23-FT5-77-Floor Tile<br>251508142-0077 | Pharmacy - 12"x12"<br>dark brown FT<br>w/yellow glue     | Brown<br>Non-Fibrous<br>Homogeneous       |              | 100% Non-fibrous (Other) | None Detected |
| 23-FT5-77-Mastic<br>251508142-0077A    | Pharmacy - 12"x12"<br>dark brown FT<br>w/yellow glue     | Gray/Yellow<br>Non-Fibrous<br>Homogeneous |              | 100% Non-fibrous (Other) | None Detected |
| 24-FT5-78-Floor Tile<br>251508142-0078 | Pharmacy - 12"x12"<br>white w/streak FT<br>w/yellow glue | White<br>Non-Fibrous<br>Homogeneous       |              | 100% Non-fibrous (Other) | None Detected |
| 24-FT5-78-Mastic<br>251508142-0078A    | Pharmacy - 12"x12"<br>white w/streak FT<br>w/yellow glue | Yellow<br>Non-Fibrous<br>Homogeneous      |              | 100% Non-fibrous (Other) | None Detected |
| 24-FT5-79<br>251508142-0079            | Pharmacy - 12"x12"<br>white w/streak FT<br>w/yellow glue | White<br>Non-Fibrous<br>Homogeneous       |              | 100% Non-fibrous (Other) | None Detected |
| 24-FT5-80<br>251508142-0080            | Pharmacy - 12"x12"<br>white w/streak FT<br>w/yellow glue | White<br>Non-Fibrous<br>Homogeneous       |              | 100% Non-fibrous (Other) | None Detected |
| 25-MG7-81<br>251508142-0081            | Pharmacy - Yellow<br>carpet glue                         | Yellow<br>Non-Fibrous<br>Homogeneous      |              | 100% Non-fibrous (Other) | None Detected |



# EMSL Analytical, Inc.

11931 Industriplex, Suite 100 Baton Rouge, LA 70809  
 Tel/Fax: (225) 755-1920 / (225) 755-1989  
<http://www.EMSL.com> / [batonrougelab@emsl.com](mailto:batonrougelab@emsl.com)

EMSL Order: 251508142

Customer ID: AQTE62

Customer PO:

Project ID:

## Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample                                 | Description                             | Appearance                               | Non-Asbestos             |                          | Asbestos<br>% Type |
|--|---|--|--------------------------|--------------------------|--------------------|
|  |   |  | % Fibrous                | % Non-Fibrous            |                    |
| 25-MG7-82<br>251508142-0082            | Pharmacy - Yellow carpet glue           | Yellow<br>Non-Fibrous<br>Homogeneous     |                          | 100% Non-fibrous (Other) | None Detected      |
| 25-MG7-83<br>251508142-0083            | Pharmacy - Yellow carpet glue           | Yellow<br>Non-Fibrous<br>Homogeneous     |                          | 100% Non-fibrous (Other) | None Detected      |
| 26-FC1-84-Floor Tile<br>251508142-0084 | Pharmacy - Rubberize floor w/glue       | Tan<br>Non-Fibrous<br>Homogeneous        |                          | 100% Non-fibrous (Other) | None Detected      |
| 26-FC1-84-Mastic<br>251508142-0084A    | Pharmacy - Rubberize floor w/glue       | Gray/Tan<br>Non-Fibrous<br>Homogeneous   | 4% Cellulose             | 96% Non-fibrous (Other)  | None Detected      |
| 26-FC1-85-Floor Tile<br>251508142-0085 | Pharmacy - Rubberize floor w/glue       | Tan<br>Non-Fibrous<br>Homogeneous        |                          | 100% Non-fibrous (Other) | None Detected      |
| 26-FC1-85-Mastic<br>251508142-0085A    | Pharmacy - Rubberize floor w/glue       | Gray/Tan<br>Non-Fibrous<br>Homogeneous   |                          | 100% Non-fibrous (Other) | None Detected      |
| 26-FC1-86-Floor Tile<br>251508142-0086 | Pharmacy - Rubberize floor w/glue       | Tan<br>Non-Fibrous<br>Homogeneous        |                          | 100% Non-fibrous (Other) | None Detected      |
| 27-FC1-86-Mastic<br>251508142-0086A    | Pharmacy - Rubberize floor w/glue       | Gray/Tan<br>Non-Fibrous<br>Homogeneous   | 5% Cellulose             | 95% Non-fibrous (Other)  | None Detected      |
| 27-FC1-87-Flooring<br>251508142-0087   | Pharmacy - Runway to bldg floor         | Gray<br>Non-Fibrous<br>Homogeneous       | 3% Synthetic<br>2% Glass | 95% Non-fibrous (Other)  | None Detected      |
| 27-FC1-87-Mastic<br>251508142-0087A    | Pharmacy - Runway to bldg floor         | Tan<br>Non-Fibrous<br>Homogeneous        |                          | 100% Non-fibrous (Other) | None Detected      |
| 27-FC1-88-Flooring<br>251508142-0088   | Pharmacy - Runway to bldg floor         | Gray<br>Non-Fibrous<br>Homogeneous       | 3% Synthetic<br>2% Glass | 95% Non-fibrous (Other)  | None Detected      |
| 27-FC1-88-Mastic<br>251508142-0088A    | Pharmacy - Runway to bldg floor         | Tan<br>Non-Fibrous<br>Homogeneous        |                          | 100% Non-fibrous (Other) | None Detected      |
| 27-FC1-89-Flooring<br>251508142-0089   | Pharmacy - Runway to bldg floor         | Gray<br>Non-Fibrous<br>Homogeneous       | 3% Synthetic<br>2% Glass | 95% Non-fibrous (Other)  | None Detected      |
| 27-FC1-89-Mastic<br>251508142-0089A    | Pharmacy - Runway to bldg floor         | Tan<br>Non-Fibrous<br>Homogeneous        |                          | 100% Non-fibrous (Other) | None Detected      |
| 28-SG1-90-Formica<br>251508142-0090    | Pharmacy - Laminate counters w/adhesive | Brown/Gray<br>Non-Fibrous<br>Homogeneous | 60% Cellulose            | 40% Non-fibrous (Other)  | None Detected      |
| 28-SG1-90-Adhesive<br>251508142-0090A  | Pharmacy - Laminate counters w/adhesive | Red<br>Non-Fibrous<br>Homogeneous        |                          | 100% Non-fibrous (Other) | None Detected      |
| 28-SG1-91-Formica<br>251508142-0091    | Pharmacy - Laminate counters w/adhesive | Brown/Gray<br>Non-Fibrous<br>Homogeneous | 60% Cellulose            | 40% Non-fibrous (Other)  | None Detected      |
| 28-SG1-91-Adhesive<br>251508142-0091A  | Pharmacy - Laminate counters w/adhesive | Red<br>Non-Fibrous<br>Homogeneous        |                          | 100% Non-fibrous (Other) | None Detected      |
| 28-SG1-92-Formica<br>251508142-0092    | Pharmacy - Laminate counters w/adhesive | Brown/Gray<br>Non-Fibrous<br>Homogeneous | 60% Cellulose            | 40% Non-fibrous (Other)  | None Detected      |



# EMSL Analytical, Inc.

11931 Industriplex, Suite 100 Baton Rouge, LA 70809  
 Tel/Fax: (225) 755-1920 / (225) 755-1989  
<http://www.EMSL.com> / batonrougelab@emsl.com

EMSL Order: 251508142

Customer ID: AQTE62

Customer PO:

Project ID:

## Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample                                       | Description                             | Appearance                               | Non-Asbestos               |   | Asbestos % Type |
|--|---|--|----------------------------|---|-----------------|
|  |   |  | % Fibrous                  | % Non-Fibrous                               |                 |
| 28-SG1-92-Adhesive<br>251508142-0092A        | Pharmacy - Laminate counters w/adhesive | Red<br>Non-Fibrous<br>Homogeneous        |                            | 100% Non-fibrous (Other)                    | None Detected   |
| 29-MG5-93<br>251508142-0093                  | Pharmacy - Black mirror mastic          | Black<br>Non-Fibrous<br>Homogeneous      |                            | 90% Non-fibrous (Other)                     | 10% Chrysotile  |
| 29-MG5-94<br>251508142-0094                  | Pharmacy - Black mirror mastic          | Black<br>Non-Fibrous<br>Homogeneous      |                            | 90% Non-fibrous (Other)                     | 10% Chrysotile  |
| 29-MG5-95<br>251508142-0095                  | Pharmacy - Black mirror mastic          | Black<br>Non-Fibrous<br>Homogeneous      |                            | 90% Non-fibrous (Other)                     | 10% Chrysotile  |
| 30-MI4-96-Wrap<br>251508142-0096             | Pharmacy - Mechanical duct insulation   | Tan/Silver<br>Fibrous<br>Heterogeneous   | 40% Cellulose<br>10% Glass | 50% Non-fibrous (Other)                     | None Detected   |
| 30-MI4-96-Insulation<br>251508142-0096A      | Pharmacy - Mechanical duct insulation   | White<br>Fibrous<br>Homogeneous          | 98% Glass                  | 2% Non-fibrous (Other)                      | None Detected   |
| 30-MI4-97-Wrap<br>251508142-0097             | Pharmacy - Mechanical duct insulation   | Tan/Silver<br>Fibrous<br>Heterogeneous   | 40% Cellulose<br>10% Glass | 50% Non-fibrous (Other)                     | None Detected   |
| 30-MI4-97-Insulation<br>251508142-0097A      | Pharmacy - Mechanical duct insulation   | White<br>Fibrous<br>Homogeneous          | 98% Glass                  | 2% Non-fibrous (Other)                      | None Detected   |
| 30-MI4-98-Wrap<br>251508142-0098             | Pharmacy - Mechanical duct insulation   | Tan/Silver<br>Fibrous<br>Heterogeneous   | 40% Cellulose<br>10% Glass | 50% Non-fibrous (Other)                     | None Detected   |
| 30-MI4-98-Insulation<br>251508142-0098A      | Pharmacy - Mechanical duct insulation   | White<br>Fibrous<br>Homogeneous          | 98% Glass                  | 2% Non-fibrous (Other)                      | None Detected   |
| 31-CA7-99<br>251508142-0099                  | Pharmacy - Fire stop caulk              | Red<br>Non-Fibrous<br>Homogeneous        |                            | 100% Non-fibrous (Other)                    | None Detected   |
| 31-CA7-100<br>251508142-0100                 | Pharmacy - Fire stop caulk              | Red<br>Non-Fibrous<br>Homogeneous        |                            | 100% Non-fibrous (Other)                    | None Detected   |
| 31-CA7-101<br>251508142-0101                 | Pharmacy - Fire stop caulk              | Red<br>Non-Fibrous<br>Homogeneous        |                            | 100% Non-fibrous (Other)                    | None Detected   |
| 32-PI4-102<br>251508142-0102                 | Pharmacy - Pipe insulation wrap         | White/Silver<br>Fibrous<br>Heterogeneous | 40% Cellulose<br>10% Glass | 50% Non-fibrous (Other)                     | None Detected   |
| 32-PI4-103<br>251508142-0103                 | Pharmacy - Pipe insulation wrap         | White/Silver<br>Fibrous<br>Heterogeneous | 40% Cellulose<br>10% Glass | 50% Non-fibrous (Other)                     | None Detected   |
| 32-PI4-104<br>251508142-0104                 | Pharmacy - Pipe insulation wrap         | White/Silver<br>Fibrous<br>Heterogeneous | 40% Cellulose<br>10% Glass | 50% Non-fibrous (Other)                     | None Detected   |
| 33-WB1-105-Texture<br>251508142-0105         | Pharmacy - Drywall ceiling w/JC         | White<br>Non-Fibrous<br>Homogeneous      |                            | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected   |
| 33-WB1-105-Joint Compound<br>251508142-0105A | Pharmacy - Drywall ceiling w/JC         | White<br>Non-Fibrous<br>Homogeneous      |                            | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected   |
| 33-WB1-105-Sheetrock<br>251508142-0105B      | Pharmacy - Drywall ceiling w/JC         | White<br>Non-Fibrous<br>Homogeneous      |                            | 100% Non-fibrous (Other)                    | None Detected   |

Initial Report From: 12/08/2015 13:16:24

PLM - 1.65 Printed: 12/8/2015 12:16 PM

Page 10 of 12



# EMSL Analytical, Inc.

11931 Industriplex, Suite 100 Baton Rouge, LA 70809  
 Tel/Fax: (225) 755-1920 / (225) 755-1989  
<http://www.EMSL.com> / [batonrougelab@emsl.com](mailto:batonrougelab@emsl.com)

EMSL Order: 251508142

Customer ID: AQTE62

Customer PO:

Project ID:

## Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample                                       | Description                                 | Appearance                               | Non-Asbestos  |   | Asbestos<br>% Type |
|--|---|--|---------------|---|--------------------|
|  |   |  | % Fibrous     | % Non-Fibrous                               |                    |
| 33-WB1-106-Texture<br>251508142-0106         | Pharmacy - Drywall ceiling w/JC             | White<br>Non-Fibrous<br>Homogeneous      |               | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected      |
| 33-WB1-106-Joint Compound<br>251508142-0106A | Pharmacy - Drywall ceiling w/JC             | White<br>Non-Fibrous<br>Homogeneous      |               | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected      |
| 33-WB1-106-Sheetrock<br>251508142-0106B      | Pharmacy - Drywall ceiling w/JC             | White<br>Non-Fibrous<br>Homogeneous      |               | 100% Non-fibrous (Other)                    | None Detected      |
| 33-WB1-107-Texture<br>251508142-0107         | Pharmacy - Drywall ceiling w/JC             | White<br>Non-Fibrous<br>Homogeneous      |               | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected      |
| 33-WB1-107-Joint Compound<br>251508142-0107A | Pharmacy - Drywall ceiling w/JC             | White<br>Non-Fibrous<br>Homogeneous      |               | 10% Ca Carbonate<br>90% Non-fibrous (Other) | None Detected      |
| 33-WB1-107-Sheetrock<br>251508142-0107B      | Pharmacy - Drywall ceiling w/JC             | White<br>Non-Fibrous<br>Homogeneous      |               | 100% Non-fibrous (Other)                    | None Detected      |
| 34-PI5-108<br>251508142-0108                 | Pharmacy - Exterior pipe insulation on HVAC | Black<br>Non-Fibrous<br>Homogeneous      |               | 100% Non-fibrous (Other)                    | None Detected      |
| 34-PI5-109<br>251508142-0109                 | Pharmacy - Exterior pipe insulation on HVAC | Black<br>Non-Fibrous<br>Homogeneous      |               | 100% Non-fibrous (Other)                    | None Detected      |
| 34-PI5-110<br>251508142-0110                 | Pharmacy - Exterior pipe insulation on HVAC | Black<br>Non-Fibrous<br>Homogeneous      |               | 100% Non-fibrous (Other)                    | None Detected      |
| 35-RF4-111<br>251508142-0111                 | Pharmacy - Vent flashing on roof            | Black<br>Non-Fibrous<br>Homogeneous      | 10% Cellulose | 90% Non-fibrous (Other)                     | None Detected      |
| 35-RF4-112<br>251508142-0112                 | Pharmacy - Vent flashing on roof            | Black<br>Non-Fibrous<br>Homogeneous      | 10% Cellulose | 90% Non-fibrous (Other)                     | None Detected      |
| 35-RF4-113<br>251508142-0113                 | Pharmacy - Vent flashing on roof            | Black<br>Non-Fibrous<br>Homogeneous      | 10% Cellulose | 90% Non-fibrous (Other)                     | None Detected      |
| 36-RF8-114<br>251508142-0114                 | Pharmacy - Pitch tar walkway roof           | Gray/Black<br>Non-Fibrous<br>Homogeneous |               | 100% Non-fibrous (Other)                    | None Detected      |
| 36-RF8-115<br>251508142-0115                 | Pharmacy - Pitch tar walkway roof           | Gray/Black<br>Non-Fibrous<br>Homogeneous |               | 100% Non-fibrous (Other)                    | None Detected      |
| 36-RF8-116<br>251508142-0116                 | Pharmacy - Pitch tar walkway roof           | Gray/Black<br>Non-Fibrous<br>Homogeneous |               | 100% Non-fibrous (Other)                    | None Detected      |



# EMSL Analytical, Inc.

11931 Industriplex, Suite 100 Baton Rouge, LA 70809  
Tel/Fax: (225) 755-1920 / (225) 755-1989  
<http://www.EMSL.com> / batonrougelab@emsl.com

EMSL Order: 251508142

Customer ID: AQTE62

Customer PO:

Project ID:

## ***Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy***

| Sample | Description | Appearance | % Fibrous | Non-Asbestos  | Asbestos |
|--------|-------------|------------|-----------|---------------|----------|
|        |             |            |           | % Non-Fibrous | % Type   |

Analyst(s)

Leah Delahoussaye (200)

Brett Heitzmann, Laboratory Manager  
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%

Samples analyzed by EMSL Analytical, Inc. Baton Rouge, LA NVLAP Lab Code 200375-0, LELAP 01950, TX 300238

Initial Report From: 12/08/2015 13:16:24

PLM - 1.65 Printed: 12/8/2015 12:16 PM

Page 12 of 12

**EMSL Analytical, Inc.**

11931 Industriplex, Suite 100, Baton Rouge, LA 70809

Phone/Fax (225) 755-1920 / (225) 755-1989

<http://www.EMSL.com>[batonrougeland@emsl.com](mailto:batonrougeland@emsl.com)

EMSL Order: 251508142  
CustomerID: AQTE62  
CustomerPO:  
ProjectID:

Attn: **Phillip Bellan**  
**Terracon Consultants, Inc.**  
**2822-B O'Neal Lane**  
**Baton Rouge, LA 70816**

Phone: (225) 442-7019  
Fax: (225) 344-6346  
Received: 12/03/15 8:00 AM  
Analysis Date: 12/10/2015  
Collected: 12/2/2015

Project: EH137101-2016-01

**Test Report: Polarized Light Microscopy (PLM) - Point Count Performed by EPA 600/R-93/116 Method with Gravimetric Reduction and 400 Point Count**

| SAMPLE ID      | DESCRIPTION                    | APPEARANCE                | (%) MATRIX<br>Organic Acid | NON-ASBESTOS<br>% Fibrous | NON-ASBESTOS<br>% NON-FIBROUS | ASBESTOS<br>% TYPES |
|----------------|--------------------------------|---------------------------|----------------------------|---------------------------|-------------------------------|---------------------|
| 29-MG5-93      | Pharmacy - Black mirror mastic | Black Fibrous Homogeneous | 69.3                       | 1.9                       | 13.4 Non-fibrous (other)      | 15.4 Chrysotile     |
| 251508142-0093 |                                |                           |                            |                           |                               |                     |

Analyst(s)

Leah Delahoussaye (1)

Brett Heitzmann, Laboratory Manager  
or other approved signatory

Disclaimers: Some samples may contain asbestos fibers present in dimensions below PLM resolution limits. The limit of detection as stated in the method is 0.25%. EMSL Analytical Inc. suggests that samples reported as <0.25% or none detected undergo additional analysis via TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical Inc.. This report must not be used to claim product endorsement by NVLAP or any agency of the United States Government. EMSL Analytical Inc. bears no responsibility for sample collection activities, analytical method limitations, or the accuracy of results when requested to separate layer samples. EMSL Analytical Inc. liability is limited to the cost of sample analysis. The test results contained within this report meet the requirements of NELAC unless otherwise noted. Samples received in good condition unless otherwise noted. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample.

Samples analyzed by EMSL Analytical, Inc. Baton Rouge, LA

Initial report from 12/10/2015 11:21:23



# Asbestos Chain of Custody

## EMSL Order Number (Lab Use Only):

EMSL ANALYTICAL, INC.  
11931 INDUSTRIPLEX BLVD. 100  
BATON ROUGE, LA 70809  
PHONE: (225) 755-1920  
FAX (225) 755-1989

8142

|  |                    |   |              |
|--|--------------------|---|--------------|
| Company : Terracon Consultants, Inc. EMSL Acct# AQTE62   |                    | EMSL-Bill to: <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different<br><small>If Bill to is Different note instructions in Comments**</small> |              |
| Street: 2822 - B O'Neal Lane   |                    | Third Party Billing requires written authorization from third party   |              |
| City: Baton Rouge  | State/Province: LA | Zip/Postal Code: 70816  | Country: USA |
| Report To (Name): Phillip Bellan   |                    | Fax #: 225-344-6346   |              |
| Telephone #: 225-442-7019 or 225-588-9066  |                    | Email Address: philip.bellan@terracon.com   |              |
| Project Name/Number: EH 137101 - 2016-01   |                    | U.S. State Samples Taken: LA  |              |
| Please Provide Results: <input type="checkbox"/> Fax <input checked="" type="checkbox"/> Email |                    | Purchase Order:   |              |

### Turnaround Time (TAT) Options\* - Please Check

3 Hour     6 Hour     24 Hour     48 Hour     72 Hour     96 Hour     1 Week     2 Week

\*For TEM Air 3 hr through 6 hr, please call ahead to schedule \*There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide

**PCM - Air**  Check if samples are from NY

NIOSH 7400

w/ OSHA 8hr. TWA

**PLM - Bulk (reporting limit)**

PLM EPA 600/R-93/116 (<1%)

PLM EPA NOB (<1%)

Point Count

400 (<0.25%)  1000 (<0.1%)

Point Count w/Gravimetric

400 (<0.25%)  1000 (<0.1%)

NYS 198.1 (friable in NY)

NYS 198.6 NOB (non-friable-NY)

NIOSH 9002 (<1%)

**TEM - Air**  4-4.5hr TAT (AHERA only)

AHERA 40 CFR, Part 763

NIOSH 7402

EPA Level II

ISO 10312

**TEM - Bulk**

TEM EPA NOB

NYS NOB 198.4 (non-friable-NY)

Chatfield SOP

TEM Mass Analysis-EPA 600 sec. 2.5

**TEM - Water:** EPA 100.2

Fibers >10µm  Waste  Drinking

All Fiber Sizes  Waste  Drinking

**TEM- Dust**

Microvac - ASTM D 5755

Wipe - ASTM D6480

Carpet Sonication (EPA 600/J-93/167)

**Soln/Rock/Vermiculite**

PLM CARB 435 - A (0.25% sensitivity)

PLM CARB 435 - B (0.1% sensitivity)

TEM CARB 435 - B (0.1% sensitivity)

TEM CARB 435 - C (0.01% sensitivity)

EPA Protocol (Semi-Quantitative)

EPA Protocol (Quantitative)

**Other:**

Check For Positive Stop - Clearly Identify Homogenous Group      Filter Pore Size (Air Samples):  0.8µm  0.45µm

Samplers Name: Phillip Bellan

Samplers Signature:

| Sample #     | Sample Description                             | Volume/Area (Air)<br>HA # (Bulk) | Date/Time<br>Sampled |
|--------------|--|----------------------------------|----------------------|
| 01 - CT3 01  | Dental clinic - 2x2' warm /pin ceiling flke    | 01                               | 11/30/15             |
| 01 - CT3- 02 |  | 5,000 sa                         |                      |
| 01 - CT3- 03 |  |                                  |                      |
| 02 - WBI- 04 | Dental clinic - drywall walls w/joint compound | 02                               |                      |
| 02 - WBI- 05 |  |                                  |                      |
| 02 - WBI- 06 |  |                                  |                      |
| 02 - WBI- 07 |  |                                  |                      |
| 02 - WBI- 08 |  |                                  |                      |

Client Sample # (s): #11-XX#-104

- #11-XX#-116

Total # of Samples: 116

Relinquished (Client):

Date: 12/2/15

Time: 18:00

Received (Lab):

Date: 12/03/15

Time: 8:00 am

Comments/Special Instructions:

(\*) Please composite all dry wall samples over 1% ACM

EMSL ANALYTICAL, INC.  
LABORATORY • PRODUCTS • TRAINING
**Asbestos Chain of Custody**  
**EMSL Order Number (Lab Use Only):**

 EMSL ANALYTICAL, INC.  
 11931 INDUSTRIPLEX BLVD 100  
 BATON ROUGE, LA 70809  
 PHONE: (225) 755-1920  
 FAX: (225) 755-1989

8142

Additional Pages of the Chain of Custody are only necessary if needed for additional sample information

| Sample #  | Sample Description  | Volume/Area (Air)<br>HA # (Bulk) | Date/Time<br>Sampled |
|-----------|---|----------------------------------|----------------------|
| 02-WB1-09 | Dental clinic: Drywall wall w/joint compound              | 02                               | 11/30/15             |
| 02-WB1-10 | 1   | 1                                | 1                    |
| 03-M63-11 | Dental clinic: cove base adhesive                         | 03                               | 1                    |
| 03-M63-12 | 5,000 in  | 1                                | 1                    |
| 03-M63-13 | 1   | 1                                | 1                    |
| 04-FT5-14 | Dental clinic: 12"x12" float tile w/yellow glue<br>7 down | 04                               | 1                    |
| 04-FT5-15 | 5,000 sq in   | 1                                | 1                    |
| 04-FT5-16 | 1   | 1                                | 1                    |
| 05-FT5-17 | Dental clinic: 12"x12" blue float tile w/yellow glue      | 05                               | 1                    |
| 05-FT5-18 | 1,000 sq in   | 1                                | 1                    |
| 05-FT5-19 | 1   | 1                                | 1                    |
| 06-FT5-20 | Dental clinic: 12"x12" brown floor tile w/yellow glue     | 06                               | 1                    |
| 06-FT5-21 | 600 sq in   | 1                                | 1                    |
| 06-FT5-22 | 1   | 1                                | 1                    |
| 07-M67-23 | Dental clinic: yellow carpet glue                         | 07                               | 1                    |
| 07-M67-24 | 185 sq in   | 1                                | 1                    |
| 07-M67-25 | 1   | 1                                | 1                    |
| 08-SG1-26 | Dental clinic: laminate flooring (Restrooms)              | 08                               | 1                    |
| 08-SG1-27 | 120 sq in   | 1                                | 1                    |
| 08-SG1-28 | 1   | 1                                | 1                    |
| 09-MI4-29 | Dental clinic: duct wrap w/mastic                         | 09                               | 1                    |
| 09-MI4-30 | 1   | 1                                | 1                    |
| 09-MI4-31 | 1   | 1                                | 1                    |
| 10-SG6-32 | Dental clinic: sink under coating                         | 18                               | 1                    |

\*Comments/Special Instructions:



# Asbestos Chain of Custody

EMSL Order Number (Lab Use Only):

EMSL ANALYTICAL, INC.  
11931 INDUSTRIPLEX BLVD 100  
BATON ROUGE, LA 70809  
PHONE: (225) 755-1920  
FAX: (225) 755-1989

8142

Additional Pages of the Chain of Custody are only necessary if needed for additional sample information

| Sample #      | Sample Description                                   | Volume/Area (Air)<br>HA # (Bulk) | Date/Time<br>Sampled |
|---------------|--|----------------------------------|----------------------|
| 10 - SC6 - 33 | Dental clinic: sink under coat                       | 10                               | 11/30/15             |
| 10 - SC6 - 34 |  | 1                                | 1                    |
| 11 - MG5 - 35 | Dental clinic: laminate counter top                  | 11                               | 11/30/15             |
| 11 - MG5 - 36 |  | 1                                | 1                    |
| 11 - MG5 - 37 |  | 1                                | 1                    |
| 12 - PIS - 38 | Dental clinic: black water pipe insulation           | 12                               |                      |
| 12 - PIS - 39 |  | 500 ln                           | 1                    |
| 12 - PIS - 40 |  | 1                                | 1                    |
| 13 - CA7 - 41 | Dental clinic: fire stop caulk                       | 13                               |                      |
| 13 - CA7 - 42 |  | 100 sa                           | 1                    |
| 13 - CA7 - 43 |  | 1                                | 1                    |
| 14 - CT3 - 44 | Pharmacy: 2x2 texture ceiling tile                   | 14                               | 12/02/15             |
| 14 - CT3 - 45 |  | 630 sa (lab)                     | 1                    |
| 14 - CT3 - 46 |  | 1                                | 1                    |
| 15 - CT3 - 47 | Pharmacy: 2x2 worn/pin ceiling tile<br>(phone)       | 15                               |                      |
| 15 - CT3 - 48 | (ctn)  | 3448 sa                          | 1                    |
| 15 - CT3 - 49 | (Rm P000)  | 1                                | 1                    |
| 16 - WBI - 50 | Pharmacy: Drywall walls w/ joint compound<br>(P0100) | 16                               |                      |
| 16 - WBI - 51 |  | (10,000 sa) (all)                | 1                    |
| 16 - WBI - 52 |  | (phone)                          | 1                    |
| 16 - WBI - 53 |  | Rm P008                          | 1                    |
| 16 - WBI - 54 |  | Rm P025                          | 1                    |
| 16 - WBI - 55 |  | Pharma                           | 1                    |
| 16 - WBI - 56 |  | lab                              | 1                    |

\*Comments/Special Instructions:

EMSL ANALYTICAL, INC.  
LABORATORY • PRODUCTS • TRAINING
**Asbestos Chain of Custody**  
**EMSL Order Number (Lab Use Only)**

 EMSL ANALYTICAL, INC.  
 11931 INDUSTRIAL PLEX BLVD 100  
 BATON ROUGE, LA 70809

 PHONE: (225) 755-1920  
 FAX: (225) 755-1989

8142

Additional Pages of the Chain of Custody are only necessary if needed for additional sample information

| Sample #     | Sample Description  | Volume/Area (Air)<br>HA # (Bulk) | Date/Time<br>Sampled |
|--------------|---|----------------------------------|----------------------|
| 17-M65 - 57  | Pharmacy: Clear plastic on FRP waistcoat (800 sq ft)          | 17                               | 12/02/15             |
| 17- M65 - 58 |   | 1                                |                      |
| 17- M65 - 59 |   | 1                                |                      |
| 18- M63 - 60 | Pharmacy: tan cove base adhesive, 2000 ft                     | 18                               |                      |
| 18- M63 - 61 |   | 1                                |                      |
| 18- M63 - 62 |   | 1                                |                      |
| 19- FTS - 63 | Pharmacy: 12" x 12" tan floor tile w/ yellow glue             | 19                               | 12/02/15             |
| 19- FTS - 64 |   | 1                                |                      |
| 19- FTS - 65 |   | 1                                |                      |
| 20- FTS - 66 | Pharmacy: 12" x 12" off-white floor tile w/ yellow glue       | 20                               |                      |
| 20- FTS - 67 |   | 1                                |                      |
| 20- FTS - 68 |   | 1                                |                      |
| 21- FTS - 69 | Pharmacy: 12" x 12" blue floor tile w/ yellow glue            | 21                               |                      |
| 21- FTS - 70 |   | 1                                |                      |
| 21- FTS - 71 |   | 1                                |                      |
| 22- FTS - 72 | Pharmacy: 12" x 12" light brown floor tile w/ yellow glue     | 22                               |                      |
| 22- FTS - 73 |   | 1                                |                      |
| 22- FTS - 74 |   | 1                                |                      |
| 23- FTS - 75 | Pharmacy: 12" x 12" dark brown floor tile w/ yellow glue      | 23                               |                      |
| 23- FTS - 76 |   | 1                                |                      |
| 23- FTS - 77 |   | 1                                |                      |
| 24- FTS - 78 | Pharmacy: 12" x 12" white w/ streak floor tile w/ yellow glue | 24                               |                      |
| 24- FTS - 79 |   | 1                                |                      |
| 24- FTS - 80 |   | 1                                |                      |

\*Comments/Special Instructions:



EMSL ANALYTICAL, INC.  
LABORATORY • PRODUCTS • TRAINING

**Asbestos Chain of Custody**  
**EMSL Order Number (Lab Use Only).**

EMSL ANALYTICAL, INC.  
11931 INDUSTRIALPLEX BLVD 100  
BATON ROUGE, LA 70809  
PHONE (225) 755-1920  
FAX (225) 755-1939

8142

Additional Pages of the Chain of Custody are only necessary if needed for additional sample information

| Sample #   | Sample Description                           | Volume/Area (Air)<br>HA # (Bulk) | Date/Time<br>Sampled |
|------------|--|----------------------------------|----------------------|
| 25-M67-81  | pharmacy: yellow carpet glue<br>(800 sq)     | 25                               | 12/02/15             |
| 25-M67-82  |  | 1                                | 1                    |
| 25-M67-83  |  | 1                                | 1                    |
| 26-FC1-84  | pharmacy: rubberine floor w/ glue            | 26                               |                      |
| 26-FC1-85  |  | 1                                |                      |
| 26-FC1-86  |  | 1                                |                      |
| 27-FC1-87  | pharmacy: runway to bldgs floor<br>400 sq    | 27                               |                      |
| 27-FC1-88  |  | 1                                |                      |
| 27-FC1-89  |  | 1                                |                      |
| 28-SG1-90  | pharmacy: laminate counters w/ adhesive      | 28                               |                      |
| 28-SG1-91  |  | 1                                |                      |
| 28-SG1-92  |  | 1                                |                      |
| 29-M65-93  | pharmacy: black mirror mosaic<br>(2 mirrors) | 29                               |                      |
| 29-M65-94  |  | 1                                |                      |
| 29-M65-95  |  | 1                                |                      |
| 30-MI4-96  | pharmacy: mechanical duct insulation         | 30                               |                      |
| 30-MI4-97  |  | 1                                |                      |
| 30-MI4-98  |  | 1                                |                      |
| 31-(A7-99  | pharmacy: Fire stop caulk<br>50 sq           | 31                               |                      |
| 31-(A7-100 |  | 1                                |                      |
| 31-(A7-101 |  | 1                                |                      |
| 32-PI4-102 | pharmacy: pipe insulation wrap               | 32                               |                      |
| 32-PI4-103 |  | 1                                |                      |
| 32-PI4-104 |  | 1                                |                      |

\*Comments/Special Instructions:



**EMSL ANALYTICAL, INC.**

**Asbestos Chain of Custody  
EMSL Order Number (Lab Use Only):**

EMSL ANALYTICAL, INC.  
11931 INDUSTRIALPLEX BLVD 100  
BATON ROUGE LA 70809  
PHONE: (225) 755-1920  
FAX: (225) 755-1939

*Additional Pages of the Chain of Custody are only necessary if needed for additional sample information*

**\*Comments/Special Instructions:**



# EMSL Analytical, Inc.

11931 Industriplex, Suite 100 Baton Rouge, LA 70809  
 Tel/Fax: (225) 755-1920 / (225) 755-1989  
<http://www.EMSL.com> / batonrougelab@emsl.com

EMSL Order: 251508175

Customer ID: AQTE62

Customer PO:

Project ID:

**Attention:** Phillip Bellan  
 Terracon Consultants, Inc.  
 2822-B O'Neal Lane  
 Baton Rouge, LA 70816

**Phone:** (225) 442-7019

**Fax:** (225) 344-6346

**Received Date:** 12/3/2015 4:25 PM

**Analysis Date:** 12/4/2015

**Collected Date:** 12/3/2015

**Project:** EH137101-2016-1

## Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample                               | Description                                     | Appearance                           | Non-Asbestos  |                          | % Type        |
|--------------------------------------|---|--------------------------------------|---------------|--------------------------|---------------|
|                                      |   |                                      | % Fibrous     | % Non-Fibrous            |               |
| 01-MG5-01<br>251508175-0001          | Kitchen - Rubber floor mastic                   | Tan<br>Non-Fibrous<br>Homogeneous    |               | 100% Non-fibrous (Other) | None Detected |
| 01-MG5-02<br>251508175-0002          | Kitchen - Rubber floor mastic                   | Tan<br>Non-Fibrous<br>Homogeneous    |               | 100% Non-fibrous (Other) | None Detected |
| 01-MG5-03<br>251508175-0003          | Kitchen - Rubber floor mastic                   | Tan<br>Non-Fibrous<br>Homogeneous    |               | 100% Non-fibrous (Other) | None Detected |
| 02-MG5-04-Paneling<br>251508175-0004 | Kitchen - FRP mastic on walls                   | White<br>Fibrous<br>Homogeneous      | 60% Glass     | 40% Non-fibrous (Other)  | None Detected |
| 02-MG5-04-Mastic<br>251508175-0004A  | Kitchen - FRP mastic on walls                   | Yellow<br>Non-Fibrous<br>Homogeneous |               | 100% Non-fibrous (Other) | None Detected |
| 02-MG5-05-Paneling<br>251508175-0005 | Kitchen - FRP mastic on walls                   | White<br>Fibrous<br>Homogeneous      | 60% Glass     | 40% Non-fibrous (Other)  | None Detected |
| 02-MG5-05-Mastic<br>251508175-0005A  | Kitchen - FRP mastic on walls                   | Yellow<br>Non-Fibrous<br>Homogeneous |               | 100% Non-fibrous (Other) | None Detected |
| 02-MG5-06-Paneling<br>251508175-0006 | Kitchen - FRP mastic on walls                   | White<br>Fibrous<br>Homogeneous      | 60% Glass     | 40% Non-fibrous (Other)  | None Detected |
| 02-MG5-06-Mastic<br>251508175-0006A  | Kitchen - FRP mastic on walls                   | Yellow<br>Non-Fibrous<br>Homogeneous |               | 100% Non-fibrous (Other) | None Detected |
| 03-CT4-07<br>251508175-0007          | Kitchen annex - 2'x4' w/m/pin CT                | White<br>Fibrous<br>Heterogeneous    | 60% Cellulose | 40% Non-fibrous (Other)  | None Detected |
| 03-CT4-08<br>251508175-0008          | Kitchen annex - 2'x4' w/m/pin CT                | White<br>Fibrous<br>Heterogeneous    | 70% Cellulose | 30% Non-fibrous (Other)  | None Detected |
| 03-CT4-09<br>251508175-0009          | Kitchen annex - 2'x4' w/m/pin CT                | White<br>Fibrous<br>Heterogeneous    | 70% Cellulose | 30% Non-fibrous (Other)  | None Detected |
| 04-SC6-10<br>251508175-0010          | Kitchen annex - Sink undercoat                  | White<br>Non-Fibrous<br>Homogeneous  | 10% Cellulose | 90% Non-fibrous (Other)  | None Detected |
| 04-SC6-11<br>251508175-0011          | Kitchen annex - Sink undercoat                  | White<br>Non-Fibrous<br>Homogeneous  | 10% Cellulose | 90% Non-fibrous (Other)  | None Detected |
| 04-SC6-12<br>251508175-0012          | Kitchen annex - Sink undercoat                  | White<br>Non-Fibrous<br>Homogeneous  | 10% Cellulose | 90% Non-fibrous (Other)  | None Detected |
| 05-FT5-13<br>251508175-0013          | Kitchen annex - 12"x12" grey FT w/yellow mastic | Gray<br>Non-Fibrous<br>Homogeneous   |               | 100% Non-fibrous (Other) | None Detected |

Initial Report From: 12/04/2015 11:45:32



# EMSL Analytical, Inc.

11931 Industriplex, Suite 100 Baton Rouge, LA 70809  
Tel/Fax: (225) 755-1920 / (225) 755-1989  
<http://www.EMSL.com> / [batonrougelab@emsl.com](mailto:batonrougelab@emsl.com)

EMSL Order: 251508175

Customer ID: AQTE62

Customer PO:

Project ID:

## Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample                                 | Description   | Appearance                                | Non-Asbestos  |                          | Asbestos |               |
|--|---|---|---------------|--------------------------|----------|---------------|
|  |   |   | % Fibrous     | % Non-Fibrous            |          | % Type        |
| 05-FT5-14-Floor Tile<br>251508175-0014 | Kitchen annex -<br>12"x12" grey FT<br>w/yellow mastic | Gray<br>Non-Fibrous<br>Homogeneous        |               | 100% Non-fibrous (Other) |          | None Detected |
| 05-FT5-14-Mastic<br>251508175-0014A    | Kitchen annex -<br>12"x12" grey FT<br>w/yellow mastic | Yellow<br>Non-Fibrous<br>Homogeneous      |               | 100% Non-fibrous (Other) |          | None Detected |
| 05-FT5-15-Floor Tile<br>251508175-0015 | Kitchen annex -<br>12"x12" grey FT<br>w/yellow mastic | Gray<br>Non-Fibrous<br>Homogeneous        |               | 100% Non-fibrous (Other) |          | None Detected |
| 05-FT5-15-Mastic<br>251508175-0015A    | Kitchen annex -<br>12"x12" grey FT<br>w/yellow mastic | Yellow<br>Non-Fibrous<br>Homogeneous      |               | 100% Non-fibrous (Other) |          | None Detected |
| 06-SG1-16<br>251508175-0016            | Kitchen annex -<br>Laminate countertops               | Brown/White<br>Non-Fibrous<br>Homogeneous | 40% Cellulose | 60% Non-fibrous (Other)  |          | None Detected |
| 06-SG1-17<br>251508175-0017            | Kitchen annex -<br>Laminate countertops               | Brown/White<br>Fibrous<br>Heterogeneous   | 60% Cellulose | 40% Non-fibrous (Other)  |          | None Detected |
| 06-SG1-18<br>251508175-0018            | Kitchen annex -<br>Laminate countertops               | Brown/White<br>Non-Fibrous<br>Homogeneous | 40% Cellulose | 60% Non-fibrous (Other)  |          | None Detected |

Analyst(s)

Brett Heitzmann (23)

Brett Heitzmann, Laboratory Manager  
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%

Samples analyzed by EMSL Analytical, Inc. Baton Rouge, LA NVLAP Lab Code 200375-0, LELAP 01950, TX 300238

Initial Report From: 12/04/2015 11:45:32

PLM - 1.65 Printed: 12/4/2015 10:45 AM

Page 2 of 2






# Asbestos Chain of Custody

## EMSL Order Number (Lab Use Only):

EMSL ANALYTICAL, INC.  
11931 INDUSTRIPLEX BLVD 100  
BATON ROUGE, LA 70809  
PHONE: (225) 755-1920  
FAX: (225) 755-1989

8175

| <b>Company :</b> Terracon Consultants, Inc. <b>EMSL Acct#</b> AQTE62  |   | <b>EMSL-Bill to:</b> <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different<br>If Bill to is Different note instructions in Comments**<br><i>Third Party Billing requires written authorization from third party</i>   |                        |
|---|---|---|------------------------|
| <b>Street:</b> 2822 - B O'Neal Lane   |   | <b>Zip/Postal Code:</b> 70816 <b>Country:</b> USA   |                        |
| <b>City:</b> Baton Rouge  | <b>State/Province:</b> LA                             | <b>Fax #:</b> 225-344-6346  |                        |
| <b>Report To (Name):</b> Phillip Bellan   |   | <b>Email Address:</b> phillip.bellan@terracon.com   |                        |
| <b>Telephone #:</b> 225-442-7019 or 225-588-9066  |   | <b>Project Name/Number:</b> E4137101-2d16-1   |                        |
| <b>Please Provide Results:</b> <input type="checkbox"/> Fax <input checked="" type="checkbox"/> Email <input type="checkbox"/> Purchase Order:  |   | <b>U.S. State Samples Taken:</b> LA   |                        |
| <b>Turnaround Time (TAT) Options* – Please Check</b>  |   |   |                        |
| <input type="checkbox"/> 3 Hour <input type="checkbox"/> 6 Hour <input type="checkbox"/> 24 Hour <input type="checkbox"/> 48 Hour <input type="checkbox"/> 72 Hour <input checked="" type="checkbox"/> 96 Hour <input type="checkbox"/> 1 Week <input type="checkbox"/> 2 Week                                |   |   |                        |
| *For TEM Air 3 hr through 6 hr, please call ahead to schedule *There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide. |   |   |                        |
| <b>PCM - Air</b> <input type="checkbox"/> Check if samples are from NY<br><input type="checkbox"/> NIOSH 7400<br><input type="checkbox"/> w/ OSHA 8hr. TWA  |   | <b>TEM - Air</b> <input type="checkbox"/> 4-4.5hr TAT (AHERA only)<br><input type="checkbox"/> AHERA 40 CFR, Part 763<br><input type="checkbox"/> NIOSH 7402<br><input type="checkbox"/> EPA Level II<br><input type="checkbox"/> ISO 10312   |                        |
| <b>PLM - Bulk (reporting limit)</b><br><input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%)<br><input type="checkbox"/> PLM EPA NOB (<1%)   |   | <b>TEM - Bulk</b><br><input type="checkbox"/> TEM EPA NOB<br><input type="checkbox"/> NYS NOB 198.4 (non-friable-NY)<br><input type="checkbox"/> Chatfield SOP<br><input type="checkbox"/> TEM Mass Analysis-EPA 600 sec. 2.5   |                        |
| <b>Point Count</b><br><input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%)   |   | <b>TEM - Water:</b> EPA 100.2<br>Fibers >10µm <input type="checkbox"/> Waste <input type="checkbox"/> Drinking<br>All Fiber Sizes <input type="checkbox"/> Waste <input type="checkbox"/> Drinking  |                        |
| <b>Point Count w/Gravimetric</b><br><input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%)   |   | <b>TEM - Dust</b><br><input type="checkbox"/> Microvac - ASTM D 5755<br><input type="checkbox"/> Wipe - ASTM D6480<br><input type="checkbox"/> Carpet Sonication (EPA 600/J-93/167)   |                        |
| <input type="checkbox"/> NYS 198.1 (friable in NY)  |   | <b>Soil/Rock/Vermiculite</b><br><input type="checkbox"/> PLM CARB 435 - A (0.25% sensitivity)<br><input type="checkbox"/> PLM CARB 435 - B (0.1% sensitivity)<br><input type="checkbox"/> TEM CARB 435 - B (0.1% sensitivity)<br><input type="checkbox"/> TEM CARB 435 - C (0.01% sensitivity)<br><input type="checkbox"/> EPA Protocol (Semi-Quantitative)<br><input type="checkbox"/> EPA Protocol (Quantitative) |                        |
| <input type="checkbox"/> NYS 198.6 NOB (non-friable-NY)   |   | <b>Other:</b><br><input type="checkbox"/>   |                        |
| <input type="checkbox"/> NIOSH 9002 (<1%)   |   |   |                        |
| <input type="checkbox"/> Check For Positive Stop – Clearly Identify Homogenous Group  |   | Filter Pore Size (Air Samples): <input type="checkbox"/> 0.8µm <input type="checkbox"/> 0.45µm  |                        |
| Samplers Name: Phillip Bellan   |   | Samplers Signature:   |                        |
| Sample #  | Sample Description                                    | Volume/Area (Air)<br>HA # (Bulk)  | Date/Time<br>Sampled   |
| 01-M65-01   | kitchen: rubber floor mastic                          | 01  | 12/3/15                |
| 01-M65-02   | (1000 sq)   |   |                        |
| 01-M65-03   |   |   |                        |
| 02-M65-04   | kitchen: FRP mastic on walls                          | 02  |                        |
| 02-M65-05   | (5000 sq)   |   |                        |
| 02-M65-06   |   |   |                        |
| 03-CT4-07   | kitchen answer: 2'x4' wall/ceiling tiles<br>(6000 sq) | 03  |                        |
| 03-CT4-08   |   |   |                        |
| Client Sample # (s): ## - XX# - 01  |   | ## - XX# - 18   | Total # of Samples: 18 |
| Relinquished (Client):   |   | Date: 12/3/15   | Time: 16:25            |
| Received (Lab):    |   | Date: 12/03/15  | Time: 4:25pm           |
| Comments/Special Instructions:<br><br><i>Walk JX</i>  |   |   |                        |



**Asbestos Chain of Custody  
EMSL Order Number (Lab Use Only):**

EMSL ANALYTICAL INC  
11931 INDUSTRIPLEX Blvd 100  
BATON ROUGE LA 70809  
PHONE (225) 755-1929  
FAX (225) 755-1989

*Additional Pages of the Chain of Custody are only necessary if needed for additional sample information*

**\*Comments/Special Instructions:**

**APPENDIX D**

**LICENSES AND CERTIFICATIONS**

**STATE OF LOUISIANA**  
**DEPARTMENT OF ENVIRONMENTAL QUALITY**

certifies that

***Phillip Bellan***

Has complied with all requirements of the Louisiana Department of Environmental Quality  
and is authorized to perform the duties of

**ASBESTOS INSPECTOR**

Accreditation No. 61187169

Date of Issuance 6/22/2015 Expiration 8/5/2016

Failure to comply with all applicable provisions of La. R.S. 2025.E. (1)(a) and La. R.S. 2025.F. (2)(a)  
may result in civil and/or criminal enforcement actions by the State.

*Christopher Manary*  
\_\_\_\_\_  
Permit Support Services Division  
Office of Environmental Services

**STATE OF LOUISIANA**  
**DEPARTMENT OF ENVIRONMENTAL QUALITY**

certifies that

***Phillip Bellan***

Has complied with all requirements of the Louisiana Department of Environmental Quality  
and is authorized to perform the duties of

Lead Inspector

Accreditation No. **61187169**

Date of Issuance **May 20, 2015**

AI No. **187169**

Expiration **April 30, 2016**

Failure to comply with all applicable provisions of La. R.S. 2025.E. (1)(a) and La. R.S. 2025.F. (2)(a)  
may result in civil and/or criminal enforcement actions by the State.

*Christopher A. Mooney*  
Public Participation & Permit Support Division  
Office of Environmental Services



# National Voluntary Laboratory Accreditation Program



## SCOPE OF ACCREDITATION TO ISO/IEC 17025:2005

**EMSL Analytical, Inc.**  
11931 Industriplex, Suite 100  
Baton Rouge, LA 70809  
Mr. Brett Heitzmann  
Phone: 225-755-1920 Fax: 225-755-1989  
E-Mail: bheitzmann@emsl.com  
URL: <http://www.emsl.com>

### BULK ASBESTOS FIBER ANALYSIS (PLM)

**NVLAP LAB CODE 200375-0**

**NVLAP Code      Designation / Description**


- |        |  |
|--------|--|
| 18/A01 | EPA 600/M4-82-020: Interim Method for the Determination of Asbestos in Bulk Insulation Samples |
| 18/A03 | EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials          |

2015-01-01 through 2015-12-31

*Effective dates*


Page 1 of 1

*For the National Institute of Standards and Technology*



NVLAP-01S (REV. 2005-05-19)

United States Department of Commerce  
National Institute of Standards and Technology



## Certificate of Accreditation to ISO/IEC 17025:2005

NVLAP LAB CODE: 200375-0

EMSL Analytical, Inc.  
Baton Rouge, LA

*is accredited by the National Voluntary Laboratory Accreditation Program for specific services,  
listed on the Scope of Accreditation, for:*

### BULK ASBESTOS FIBER ANALYSIS

*This laboratory is accredited in accordance with the recognized International Standard ISO/IEC 17025:2005.  
This accreditation demonstrates technical competence for a defined scope and the operation of a laboratory quality  
management system (refer to joint ISO/ILAC-IAF Communique dated January 2009).*



2015-01-01 through 2015-12-31

*Effective dates*

A handwritten signature in black ink that reads "Michael D. Mullan".

*For the National Institute of Standards and Technology*



**STATE OF LOUISIANA  
DEPARTMENT OF ENVIRONMENTAL QUALITY**

Is hereby granting a Louisiana Environmental Laboratory Accreditation to



**EMSL Analytical Inc  
11931 Industriplex Blvd Ste 100  
Baton Rouge, Louisiana 70809**

**Agency Interest No. 30659**

According to the Louisiana Administrative Code, Title 33, Part I, Subpart 3, LABORATORY ACCREDITATION, the State of Louisiana formally recognizes that this laboratory is technically competent to perform the environmental analyses listed on the scope of accreditation detailed in the attachment.

The laboratory agrees to perform all analyses listed on this scope of accreditation according to the Part I, Subpart 3 requirements and acknowledges that continued accreditation is dependent on successful ongoing compliance with the applicable requirements of Part I. Please contact the Department of Environmental Quality, Louisiana Environmental Laboratory Accreditation Program (LELAP) to verify the laboratory's scope of accreditation and accreditation status.

Accreditation by the State of Louisiana is not an endorsement or a guarantee of validity of the data generated by the laboratory. To be accredited initially and maintain accreditation, the laboratory agrees to participate in two single-blind, single-concentration PT studies, where available, per year for each field of testing for which it seeks accreditation or maintains accreditation as required in LAC 33:1:4711.

**Certificate Number: 01950**

**Expiration Date: June 30, 2015  
Issued On: July 1, 2014**

Lourdes Iturralde, Administrator  
Notifications and Accreditations Section  
Public Participation & Permit Support Services Division



STATE OF LOUISIANA

DEPARTMENT OF ENVIRONMENTAL QUALITY

Issue Date: July 1, 2014

EMSL Analytical Inc

AI Number: 30659

Expiration Date: June 30, 2015

11931 Industriplex Blvd Ste 100, Baton Rouge, Louisiana 70809

Certificate Number: 01950

### Air Emissions

| Analyte                                    | Method Name  | Method Code | Type  | AB |
|--|--|-------------|-------|----|
| 1520 - Asbestos                            | NIOSH 7402, Rev.2                                      | 2016        | NVLAP | LA |
| 1520 - Asbestos                            | 40 CFR Part 763, Subpart E, Appendix A (Mandatory TEM) | 2062        | NVLAP | LA |
| 1075 - Lead                                | NIOSH 7082, Rev.2                                      | 2453        | State | LA |
| 100683 - Fungal - Direct Examination (Air) | EMSL 05-TP-003.5                                       | 2885        | State | LA |
| 1520 - Asbestos                            | NIOSH 7400, Rev.3                                      | 90018001    | NVLAP | LA |

### Non Potable Water

| Analyte         | Method Name | Method Code | Type  | AB |
|-----------------|-------------|-------------|-------|----|
| 1520 - Asbestos | EPA 100.2   | 10004407    | NVLAP | LA |

### Solid Chemical Materials

| Analyte  | Method Name             | Method Code | Type  | AB |
|--|-------------------------|-------------|-------|----|
| 100095 - Asbestos in Bulk Insulation           | EPA 600/M4-82-020 (PLM) | 1488        | NVLAP | LA |
| 100681 - Fungal - Direct Examination (Bulk)    | EMSL SOP M041           | 2886        | State | LA |
| 100682 - Fungal - Direct Examination (Surface) | EMSL SOP M041           | 2886        | State | LA |
| 1075 - Lead                                    | EPA 3050                | 10135203    | State | LA |
| 1075 - Lead                                    | EPA 7000                | 10157401    | State | LA |
| 1075 - Lead                                    | EPA 7420                | 10164406    | State | LA |
| 1520 - Asbestos                                | EPA 600/R-93/116        | 10294583    | NVLAP | LA |

### Biological Tissue

| Analyte | Method Name | Method Code | Type | AB   |
|---------|-------------|-------------|------|------|
| NONE    | NONE        | NONE        | NONE | NONE |

**APPENDIX E**

**PHOTOGRAPHIC DOCUMENTATION**

**Asbestos, LBP & URW Survey Report**

Interim Louisiana Hospital Dental Clinic and Pharmacy Building ■ New Orleans, Louisiana


Date Photos Taken: Nov. 30, 2015 thru Dec. 3, 2015 ■ Terracon Project No. EH137101

LSUHSC PO No. 00374423B ■ Task Order No. 2016-01


**Terracon**



**Photo #1** Exterior view of dental clinic building



**Photo #2** View of HA No. 01 – 2'x2' worm/pinhole ceiling tile located in the dental clinic (ND)



**Photo #3** View of HA No. 02 – drywall walls with associated joint compound located in the dental clinic (ND)



**Photo #4** View of HA No. 03 – cove base adhesive located in the dental clinic (ND)



**Photo #5** View of HA No. 04 – 12"x12" floor tile with yellow glue located in the dental clinic (ND)



**Photo #6** View of HA No. 05 – 12"x12" blue floor tile with yellow glue located in the dental clinic (ND)

**Asbestos, LBP & URW Survey Report**

Interim Louisiana Hospital Dental Clinic and Pharmacy Building ■ New Orleans, Louisiana

Date Photos Taken: Nov. 30, 2015 thru Dec. 3, 2015 ■ Terracon Project No. EH137101

LSUHSC PO No. 00374423B ■ Task Order No. 2016-01

**Terracon**



**Photo #7** View of HA No. 06 – 12"x12" brown floor tile with yellow glue located in the dental clinic (ND)



**Photo #8** View of HA No. 07 – yellow carpet glue located in meeting rooms of the dental clinic (ND)




**Photo #9** View of HA No. 08 – laminate flooring located in the restrooms of the dental clinic (ND)



**Photo #10** View of HA No. 09 – HVAC duct wrap with associated mastic located above the ceiling deck in the dental clinic (ND)



**Photo #11** View of HA No. 10 – sink undercoating in the dental clinic (ND)



**Photo #12** View of HA No. 11 – laminate countertops in the dental clinic (ND)


**Asbestos, LBP & URW Survey Report**

Interim Louisiana Hospital Dental Clinic and Pharmacy Building ■ New Orleans, Louisiana

Date Photos Taken: Nov. 30, 2015 thru Dec. 3, 2015 ■ Terracon Project No. EH137101

LSUHSC PO No. 00374423B ■ Task Order No. 2016-01


**Terracon**




**Photo #13** View of HA No. 12 – black insulation on the water pipes located above the ceiling deck of the dental clinic (ND)




**Photo #14** View of HA No. 13 – fire stop caulk located above the ceiling deck in the dental clinic (ND)




**Photo #15** View of exterior of pharmacy building



**Photo #16** View of HA No. 14 – texture ceiling tile located in the IV lab of the pharmacy building (ND)



**Photo #17** View of HA No. 15 – 2'x2' worm/pinhole ceiling tile located in the pharmacy building (ND)



**Photo #18** View of HA No. 16 – drywall walls with associated joint compound located in the pharmacy building (ND)


**Asbestos, LBP & URW Survey Report**

Interim Louisiana Hospital Dental Clinic and Pharmacy Building ■ New Orleans, Louisiana

Date Photos Taken: Nov. 30, 2015 thru Dec. 3, 2015 ■ Terracon Project No. EH137101

LSUHSC PO No. 00374423B ■ Task Order No. 2016-01

**Terracon**



**Photo #19** View of HA No. 17 – Clear mastic behind the Fiber Reinforced plastic wainscot located in the pharmacy building (ND)




**Photo #20** View of HA No. 18 – cove base adhesive located in the pharmacy building (ND)



**Photo #21** View of HA No. 19 – 12"x12" tan floor tile with yellow glue located in the pharmacy building (ND)



**Photo #22** View of HA No. 20 – 12"x12" off-white floor tile with yellow glue located in the pharmacy building (ND)



**Photo #23** View of HA No. 21 – 12"x12" blue floor tile with yellow glue located in the pharmacy building (ND)



**Photo #24** View of HA No. 22 – 12"x12" light brown floor tile with yellow glue located in the pharmacy building (ND)


**Asbestos, LBP & URW Survey Report**

Interim Louisiana Hospital Dental Clinic and Pharmacy Building ■ New Orleans, Louisiana

Date Photos Taken: Nov. 30, 2015 thru Dec. 3, 2015 ■ Terracon Project No. EH137101

LSUHSC PO No. 00374423B ■ Task Order No. 2016-01


**Terracon**



**Photo #25** View of HA No. 23 – 12"x12" dark brown floor tile with yellow glue located in the pharmacy building (ND)



**Photo #26** View of HA No. 24 – 12"x12" white streak floor tile with yellow glue located in the pharmacy building (ND)




**Photo #27** View of HA No. 25 – yellow carpet glue located in the pharmacy building (ND)



**Photo #28** View of HA No. 26 – rubberized flooring with glue located in the IV lab of the pharmacy building (ND)



**Photo #29** View of HA No. 27 – flooring from the walkway to the pharmacy building (ND)



**Photo #30** View of HA No. 28 – laminate counter tops with adhesive located in the pharmacy building (ND)


**Asbestos, LBP & URW Survey Report**

Interim Louisiana Hospital Dental Clinic and Pharmacy Building ■ New Orleans, Louisiana


Date Photos Taken: Nov. 30, 2015 thru Dec. 3, 2015 ■ Terracon Project No. EH137101

LSUHSC PO No. 00374423B ■ Task Order No. 2016-01


**Terracon**




**Photo #31** View of HA No. 29 – black mirror mastic behind restroom mirrors in the pharmacy building (10% C / 15% C – point count)




**Photo #32** View of HA No. 30 – HVAC duct insulation located above the ceiling deck in the pharmacy building (ND)




**Photo #33** View of HA No. 31 – fire stop caulk located above the ceiling deck in the pharmacy building (ND)



**Photo #34** View of HA No. 32 – pipe insulation wrap located on pipes above the ceiling deck in the pharmacy building (ND)



**Photo #35** View of HA No. 33 – drywall ceiling with associated joint compound located in the pharmacy building (ND)



**Photo #36** View of HA No. 34 – exterior pipe insulation on HVAC unit of the pharmacy building (ND)

**Asbestos, LBP & URW Survey Report**

Interim Louisiana Hospital Dental Clinic and Pharmacy Building ■ New Orleans, Louisiana


Date Photos Taken: Nov. 30, 2015 thru Dec. 3, 2015 ■ Terracon Project No. EH137101

LSUHSC PO No. 00374423B ■ Task Order No. 2016-01

**Terracon**




**Photo #37** View of HA No. 35 – vent flashing on the roof of the pharmacy building (ND)



**Photo #38** View of HA No. 36 – pitch tar roof located on the walkway leading to the pharmacy building (ND)




**Photo #39** View of HA No. 01 – rubber floor glue located in the kitchen extension of the pharmacy building (ND)



**Photo #40** View of HA No. 02 – fiber re-enforced panel mastic on walls of kitchen extension of the pharmacy building (ND)



**Photo #41** View of HA No. 03 – 2'x4' worm/pinhole ceiling tile in the kitchen extension of the pharmacy building (ND)



**Photo #42** View of HA No. 04 – Sink undercoating in the kitchen extension of the pharmacy building (ND)

**Asbestos, LBP & URW Survey Report**

Interim Louisiana Hospital Dental Clinic and Pharmacy Building ■ New Orleans, Louisiana  
Date Photos Taken: Nov. 30, 2015 thru Dec. 3, 2015 ■ Terracon Project No. EH137101  
LSUHSC PO No. 00374423B ■ Task Order No. 2016-01

**Terracon**



**Photo #43** View of HA No. 05 – 12"x12" grey floor tile with yellow glue located in the kitchen extension of the pharmacy building (ND)



**Photo #44** View of HA No. 06 – laminate countertops with associated glue located in the kitchen extension of the pharmacy building (ND)




**Photo #45** View of various hazardous waste trash cans located in the dental clinic



**Photo #46** View of sharps containers located in the dental clinic



**Photo #47** View of surgical lights which may contain mercury in the dental clinic



**Photo #48** View of sink traps in the dental clinic laboratory area


**Asbestos, LBP & URW Survey Report**

Interim Louisiana Hospital Dental Clinic and Pharmacy Building ■ New Orleans, Louisiana


Date Photos Taken: Nov. 30, 2015 thru Dec. 3, 2015 ■ Terracon Project No. EH137101

LSUHSC PO No. 00374423B ■ Task Order No. 2016-01

**Terracon**



**Photo #49** View of HVAC with R-410A refrigerant on top of dental clinic roof



**Photo #50** View of an example of Mercury containing fluorescent light bulbs in both the dental and pharmacy building



**Photo #51** View of PCB containing fluorescent light ballast in both the dental and pharmacy building



**Photo #52** View of various sharps containers located in pharmacy building



**Photo #53** View of various medical waste containers located in pharmacy building



**Photo #54** View of sink traps in the kitchen extension of the pharmacy building


**Asbestos, LBP & URW Survey Report**

Interim Louisiana Hospital Dental Clinic and Pharmacy Building ■ New Orleans, Louisiana

Date Photos Taken: Nov. 30, 2015 thru Dec. 3, 2015 ■ Terracon Project No. EH137101

LSUHSC PO No. 00374423B ■ Task Order No. 2016-01


**Terracon**



**Photo #55** View of grease in fryers in the kitchen extension of the pharmacy building



**Photo #56** View of sanitization chemicals still present in the kitchen extension of the pharmacy building




**Photo #57** View of grease storage dumpster outside the kitchen extension of the pharmacy building



**Photo #58** View of hydraulic lift located outside the kitchen extension of the pharmacy building




**Photo #59** View of refrigerant containing motors for walk in freezer for kitchen extension of the pharmacy building



**Photo #60** View of refrigerant containing HVAC unit for kitchen extension of pharmacy building

**APPENDIX F**

**ACM HOMOGENEOUS AREA DIAGRAMS**



NOT TO SCALE

**EXHIBIT**

**SITE DIAGRAM-DENTAL CLINIC**

|   |         |             |                       |
|---|---------|-------------|-----------------------|
| Project Mgr:  | PMB     | Project No: | EH137101-2016-01      |
| Drawn By:   | TLY     | Scale:      | AS SHOWN              |
| Checked By:   | PMB/MRF | File No:    | ACMEH137101-2016-01-1 |
| Approved By:  | PMB     | Date:       | DECEMBER 2015         |
| 2822-B O'Neal Lane, Building B, Baton Rouge, LA 70816<br>(225) 342-6552 |         |             |                       |


All sample numbers are shown as last two digits xx-xx#-# #  
THIS DIAGRAM IS FOR GENERAL LOCATION ONLY, AND IS NOT INTENDED FOR CONSTRUCTION PURPOSES

**\* SAMPLING LOCATION**

|                     |                            |
|---------------------|----------------------------|
| ACM                 | Interim Louisiana Hospital |
| 2021 Perdido Street | NEW ORLEANS, LA            |

1

**LEGEND**



### LEGEND

\* SAMPLING LOCATION

All sample numbers are shown as last  
two digits xx-xx#-##

THIS DIAGRAM IS FOR GENERAL LOCATION ONLY, AND IS NOT INTENDED FOR CONSTRUCTION PURPOSES

### SITE DIAGRAM-PHARMACY

ACM

Interim Louisiana Hospital  
2021 Perdido Street  
NEW ORLEANS, LA



|                     |                                |
|---------------------|--------------------------------|
| Project Mgr. PMB    | Proj. No. EH137101-2016-01     |
| Drawn By: TLY       | Scale: AS SHOWN                |
| Checked By: PMB/MRF | File No. ACMEH137101-2016-01-2 |
| Approved By: PMB    | Date: DECEMBER 2015            |

EXHIBIT

2

N

NOT TO SCALE



### LEGEND

\* SAMPLING LOCATION

All sample numbers are shown  
as last two digits xx-xx#-# #

| SITE DIAGRAM  |   | EXHIBIT  |
|---|---|--|
| <br>ACM   |   | 3  |
| Project No:<br>PMB<br>Drawn By:<br>TLY<br>Checked By:<br>PMB/MRF<br>Approved By:<br>PMB | Project No:<br>EH137101-2016-01<br>Scale:<br>AS SHOWN<br>File No.:<br>ACMEH137101-2016-01-3<br>Date:<br>DECEMBER 2015 | INTERIM LSU HOSPITAL<br>433 BOLIVAR STREET<br>NEW ORLEANS, LA<br>2822-B O'Neal Lane, Building B, Baton Rouge, LA 70816<br>(225) 344-6052 |

THIS DIAGRAM IS FOR GENERAL LOCATION ONLY AND IS NOT INTENDED FOR CONSTRUCTION PURPOSES